

Lead-Based Paint Inspection Report

Cedar Grove III
1413 4th Street
Sedro-Woolley, Washington

Prepared for:
Deborah McCaslin
King County Housing
700 Andover Park West, Suite C
Seattle, Washington 98188

February 22, 2018
PBS Project No. 40573.153



2517 EASTLAKE AVENUE EAST
SUITE 100
SEATTLE, WA 98102
206.233.9639 MAIN
866.727.0140 FAX
PBSUSA.COM

LEAD-BASED PAINT INSPECTION REPORT

Cedar Grove III
1413 4th Street
Sedro-Woolley, Washington

For

King County Housing Authority
700 Andover Park West, Suite C
Seattle, Washington 98188

This report is for the exclusive use of the client and is not to be photographed, photocopied, or similarly reproduced, in total or in part, without the express written consent of the client and/or PBS Engineering and Environmental Inc.

Prepared by:

PBS Engineering and Environmental Inc.
2517 Eastlake Avenue East Suite 100
Seattle, Washington 98102



TABLE OF CONTENTS

1 IDENTIFYING INFORMATION.....1

2 LEAD-BASED PAINT INSPECTION.....2

2.1 Site Information..... 2

2.2 Lead-Based Paint Inspection and Sampling 2

 2.2.1 XRF Sampling..... 2

 2.2.2 Bulk Paint-Chip Sampling 3

2.3 Components with Lead-Based Paint..... 3

2.4 Deteriorated Lead-Based Paint Surfaces..... 3

SUPPORTING DATA

TAB 1: XRF Data Sheets

TAB 2: Certifications

1 IDENTIFYING INFORMATION

BUILDING DATA

Cedar Grove III
1413 4th Street
Sedro-Woolley, Washington

CLIENT DATA

King County Housing Authority
700 Andover Park West, Suite C
Seattle, WA 98188
Attn: Ms. Deborah McCaslin

SCOPE OF ASSESSMENT

PBS Engineering and Environmental, Inc. (PBS) conducted a lead-based paint inspection at Cedar Grove III on January 18, 2018, in accordance with the U.S. Department Housing and Urban Development (HUD), Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing.

CERTIFICATIONS

Risk Assessor

Janet Murphy
State of Washington
Department of Community, Trade and Economic Development
Risk Assessor Certification No: 0258, Expiration Date: 3/8/2019



Signature

February 22, 2018

Date

Firm

PBS Engineering and Environmental
2517 Eastlake Avenue East
Seattle, Washington 98102
Telephone: 206.223.9639

Certification No: 129143
Expiration Date: 7/31/2018

2 LEAD-BASED PAINT INSPECTION

2.1 Site Information

Cedar Grove III consist of 21 buildings with a total of 4 units and a playground. The buildings are of wood construction with gypsum interior walls and ceilings. The exterior is vinyl siding and vinyl trim. Apartment units are three and four bedrooms with a bathroom and a kitchen/dining room and living room area. The buildings are in good condition.

Architectural finishes are uniform throughout. The majority of the interior components are painted. Walls are painted gypsum wallboard. Doors are wood or metal. Door and window frames are painted medium density particle board (MDF) and metal. The exterior window frames are vinyl.

2.2 Lead-Based Paint Inspection and Sampling

Based on information provided by KCHA, Cedar Grove III was constructed in 1971. All buildings and units were found to have a similar construction and painting history. Based on Table 7.3 in Chapter 7 of the HUD Guidelines, six (6) units at the site were included in PBS's inspection. Additionally, PBS inspected the playground.

2.2.1 XRF Sampling

The presence of lead in paint was determined through x-ray fluorescence spectroscopy. A handheld Niton X-Ray Fluorescence Analyzer (XRF), Model XLP-300A Serial # 102877 operating in lead paint mode was used to perform a surface by surface lead paint inspection of each painted surface in the selected units and other building areas. Calibration was checked based on the requirements of the Performance Characteristic Sheet for the XRF Analyzer. All calibration readings were within the tolerance for this instrument.

HUD and the Environmental Protection Agency (EPA) have set 1.0 milligrams per square centimeter (mg/cm^2) as the threshold limit for lead-based paint as determined through X-Ray Fluorescence (XRF) testing. HUD and EPA have set 5,000 parts per million (ppm) or 0.5 percent by atomic absorption spectroscopy (AAS) laboratory analysis as the threshold limit for lead-based paint. Paint that is known to contain lead levels less than those described above does not have to be evaluated, although all deteriorated paint (paint surfaces in poor condition) should be repaired because it may contain lower levels of lead that may contribute to lead dust or lead contaminated soil hazards.

The "Side" information presented on the XRF data sheets is in relation to the side of the rooms, or building exteriors where the unit address is located. The inspector/risk assessor used the address side of each residence as the basis to establish side "A". Sides B, C, and D follow in clockwise rotation.

Please refer to the XRF Sample Data Table located in Tab 1 for a complete list of XRF samples.

2.2.2 Bulk Paint-Chip Sampling

Bulk paint chip verification samples were collected when there was an inconclusive result with the XRF. Inconclusive results were not recorded during the Cedar Grove III inspection.

2.3 Components with Lead-Based Paint

None of the paint tested contained lead above the HUD level of 1.0 mg/cm² by XRF.

2.4 Deteriorated Lead-Based Paint Surfaces

Lead-based paint was not identified at the subject property. Painted surfaces were evaluated to be in an intact condition.

TAB 1

XRF Data Sheets

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1	SHUTTER	CAL									6.85
2	NIST STANDARD	PAINT			RED	CEDAR GROVE III				Negative	0.9
3	NIST STANDARD	PAINT			RED	CEDAR GROVE III				Null	1.1
4	NIST STANDARD	PAINT			RED	CEDAR GROVE III				Positive	1.1
5	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1417	Negative	< LOD
6	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1417	Negative	< LOD
7	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1417	Negative	< LOD
8	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1417	Negative	< LOD
9	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1417	Negative	< LOD
10	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1417	Negative	< LOD
11	WINDOW FRAME	WOOD	D	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1417	Negative	< LOD
12	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
13	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
14	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
15	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
16	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
17	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
18	DOOR	METAL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
19	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
20	WINDOW FRAME	WOOD	B	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
21	WINDOW SILL	WOOD	B	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1417	Negative	< LOD
22	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
23	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
24	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
25	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
26	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
27	CLOSET ROOL DOOR	WOOD	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
28	DOOR	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
29	DOOR FRAME	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1417	Negative	< LOD
30	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
31	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
32	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
33	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
34	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
35	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
36	DOOR	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
37	DOOR FRAME	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1417	Negative	< LOD
38	CEILING	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD
39	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
40	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD
41	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD
42	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD
43	CLOSET ROOL DOOR	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD
44	DOOR	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD
45	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1417	Negative	< LOD
46	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
47	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
48	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
49	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
50	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
51	CLOSET ROLL DOOR	WOOD	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
52	DOOR	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
53	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1417	Negative	< LOD
54	RISER	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	STAIR	UNIT 1417	Negative	< LOD
55	HAND RAIL	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	STAIR	UNIT 1417	Negative	< LOD
56	WALL	WOOD	B	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1417	Negative	< LOD
57	WALL	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1417	Negative	< LOD
58	WINDOW FRAME	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1417	Negative	< LOD
59	WINDOW SILL	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1417	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
60	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
61	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
62	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
63	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
64	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
65	SLIDING DOOR FRAME	WOOD	D	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
66	WINDOW FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
67	WINDOW SILL	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1419	Negative	< LOD
68	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
69	TRIM	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
70	TRIM	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
71	TRIM	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
72	TRIM	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
73	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
74	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
75	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
76	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
77	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
78	DOOR	METAL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
79	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1419	Negative	< LOD
80	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
81	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
82	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
83	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
84	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
85	CLOSET ROOL DOOR	WOOD	D	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
86	DOOR	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
87	DOOR	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
88	DOOR FRAME	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1419	Negative	< LOD
89	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1419	Negative	< LOD
90	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1419	Negative	< LOD
91	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1419	Negative	< LOD
92	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1419	Negative	< LOD
93	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1419	Negative	< LOD
94	DOOR	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1419	Negative	< LOD
95	DOOR FRAME	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1419	Negative	< LOD
96	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
97	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
98	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
99	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
100	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
101	DOOR	PLASTER	B	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
102	DOOR FRAME	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
103	WINDOW FRAME	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
104	WINDOW SILL	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
105	CLOSET ROLL DOOR	WOOD	D	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1419	Negative	< LOD
106	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
107	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
108	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
109	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
110	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
111	DOOR	WOOD	D	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
112	DOOR FRAME	WOOD	D	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
113	CLOSET ROLL DOOR	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
114	WINDOW FRAME	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
115	WINDOW SILL	WOOD	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1419	Negative	< LOD
116	RISER	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	STAIR	UNIT 1419	Negative	< LOD
117	HANDRAIL	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	STAIR	UNIT 1419	Negative	< LOD
118	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1419	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
119	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1419	Negative	< LOD
120	WINDOW FRAME	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1419	Negative	< LOD
121	WINDOW SILL	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1419	Negative	< LOD
122	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1415	Negative	< LOD
123	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1415	Negative	< LOD
124	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1415	Negative	< LOD
125	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1415	Negative	< LOD
126	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1415	Negative	< LOD
127	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1415	Negative	< LOD
128	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1415	Negative	< LOD
129	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1415	Negative	< LOD
130	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1415	Negative	< LOD
131	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1415	Negative	< LOD
132	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1415	Negative	< LOD
133	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
134	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
135	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
136	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
137	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
138	CLOSET ROLL DOOR	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
139	DOOR	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
140	DOOR FRAME	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
141	WINDOW FRAME	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
142	WINDOW SILL	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1415	Negative	< LOD
143	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1415	Negative	< LOD
144	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1415	Negative	< LOD
145	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1415	Negative	< LOD
146	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1415	Negative	< LOD
147	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1415	Negative	< LOD
148	DOOR	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1415	Negative	< LOD
149	DOOR FRAME	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1415	Negative	< LOD
150	CEILING	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
151	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
152	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
153	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
154	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
155	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
156	CLOSET ROLL DOOR	WOOD	D	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
157	DOOR	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
158	DOOR FRAME	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
159	WINDOW FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
160	WINDOW SILL	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1415	Negative	< LOD
161	RISER	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	STAIR	UNIT 1415	Negative	< LOD
162	HAND RAIL	WOOD	D	INTACT	BROWN	CEDAR GROVE III	SECOND	STAIR	UNIT 1415	Negative	< LOD
163	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
164	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
165	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
166	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
167	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
168	WINDOW SILL	WOOD	B	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
169	WINDOW FRAME	WOOD	B	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
170	SLIDING DOOR FRAME	WOOD	B	INTACT	WHITE	CEDAR GROVE III	FIRST	KITCHEN	UNIT 1413	Negative	< LOD
171	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD
172	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD
173	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD
174	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD
175	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD
176	WINDOW SILL	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
177	DOOR	METAL	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD
178	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	LIVING ROOM	UNIT 1413	Negative	< LOD
179	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
180	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
181	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
182	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
183	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
184	WIDOW SILL	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
185	WIDOW FRAME	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
186	DOOR	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
187	DOOR FRAME	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 1	UNIT 1413	Negative	< LOD
188	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
189	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
190	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
191	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
192	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
193	DOOR	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
194	DOOR FRAME	WOOD	A	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
195	WINDOW FRAME	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD
196	WINDOW SILL	WOOD	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 2	UNIT 1413	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
197	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1413	Negative	< LOD
198	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1413	Negative	< LOD
199	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1413	Negative	< LOD
200	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1413	Negative	< LOD
201	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1413	Negative	< LOD
202	DOOR	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1413	Negative	< LOD
203	DOOR FRAME	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	BATHROOM	UNIT 1413	Negative	< LOD
204	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
205	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
206	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
207	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
208	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
209	WINDO SILL	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
210	WINDO FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
211	DOOR	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
212	DOOR FRAME	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	BEDROOM 3	UNIT 1413	Negative	< LOD
213	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1413	Negative	< LOD
214	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE III	SECOND	HALL	UNIT 1413	Negative	< LOD
215	RISER	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	HALL	UNIT 1413	Negative	< LOD
216	HAND RAIL	WOOD	B	INTACT	BROWN	CEDAR GROVE III	SECOND	HALL	UNIT 1413	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
217	FENCE	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	EXTEIOR	UNIT 1413	Negative	< LOD
218	FENCE	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	EXTEIOR	UNIT 1415	Negative	< LOD
219	FENCE	WOOD	C	INTACT	BROWN	CEDAR GROVE III	SECOND	EXTEIOR	UNIT 1419	Negative	< LOD
220	SIDING	WOOD	C	INTACT	GRAY	CEDAR GROVE III	SECOND	EXTEIOR	UNIT 1419	Negative	< LOD
221	SIDING	WOOD	C	INTACT	GRAY	CEDAR GROVE III	SECOND	EXTEIOR	UNIT 1417	Negative	< LOD
222	SIDING	WOOD	C	INTACT	GRAY	CEDAR GROVE III	SECOND	EXTEIOR	UNIT 1415	Negative	< LOD
223	SIDING	WOOD	C	INTACT	GRAY	CEDAR GROVE III	SECOND	EXTEIOR	UNIT 1413	Negative	< LOD
224	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	EXTEIOR	UNIT 1413	Negative	< LOD
225	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	EXTEIOR	UNIT 1415	Negative	< LOD
226	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	EXTEIOR	UNIT 1417	Negative	< LOD
227	DOOR FRAME	WOOD	A	INTACT	WHITE	CEDAR GROVE III	FIRST	EXTEIOR	UNIT 1419	Negative	< LOD
228	POLE	METAL		INTACT	YELLOW	CEDAR GROVE III	FIRST	EXTEIOR	PLAYGRO UD	Negative	< LOD
229	POLE	METAL		INTACT	BLUE	CEDAR GROVE III	FIRST	EXTEIOR	PLAYGRO UD	Negative	< LOD
230	POLE	METAL		INTACT	PURPLE	CEDAR GROVE III	FIRST	EXTEIOR	PLAYGRO UD	Negative	< LOD
231	BENCH	METAL		INTACT	BROWN	CEDAR GROVE III	FIRST	EXTEIOR	PLAYGRO UD	Negative	< LOD
232	SHUTTER CAL										7.03
233	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
234	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
235	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
236	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
237	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
238	WINDOW FRAME	WOOD	B	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
239	WINDOW SILL	WOOD	B	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
240	DOOR	WOOD	D	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
241	DOOR FRAME	WOOD	D	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 1	UNIT 816	Negative	< LOD
242	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
243	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
244	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
245	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
246	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
247	CLOSET ROOL DOOR	WOOD	A	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
248	WINDOW SILL	WOOD	B	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
249	WINDOW FRAME	WOOD	B	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
250	DOOR	WOOD	D	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
251	DOOR FRAME	WOOD	D	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 2	UNIT 816	Negative	< LOD
252	CEILING	DRYWALL		INTACT	WHITE	CEDAR GROVE 1	SECOND	BATHROOM	UNIT 816	Negative	< LOD
253	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE 1	SECOND	BATHROOM	UNIT 816	Negative	< LOD
254	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE 1	SECOND	BATHROOM	UNIT 816	Negative	< LOD
255	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE 1	SECOND	BATHROOM	UNIT 816	Negative	< LOD
256	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE 1	SECOND	BATHROOM	UNIT 816	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
257	DOOR	WOOD	A	INTACT	BROWN	CEDAR GROVE 1	SECOND	BATHROOM	UNIT 816	Negative	< LOD
258	DOOR FRAME	WOOD	A	INTACT	BROWN	CEDAR GROVE 1	SECOND	BATHROOM	UNIT 816	Negative	< LOD
259	CEILING	DRYWALL	A	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
260	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
261	WALL	DRYWALL	A	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
262	WALL	DRYWALL	B	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
263	WALL	DRYWALL	C	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
264	WALL	DRYWALL	D	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
265	DOOR	WOOD	B	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
266	DOOR FRAME	WOOD	B	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
267	DOOR FRAME	WOOD	B	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
268	CLOSRT ROLL DOOR	WOOD	B	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
269	WINDOW FRAME	WOOD	D	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
270	WINDOW SILL	WOOD	D	INTACT	WHITE	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
271	RISER	WOOD	A	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD
272	HAND RAIL	WOOD	A	INTACT	BROWN	CEDAR GROVE 1	SECOND	BEDROOM 3	UNIT 816	Negative	< LOD

TAB 2
Certification



STATE OF WASHINGTON

Department of Commerce
Lead-Based Paint Program

Janet J. Murphy

Has fulfilled the certification requirements of Washington Administrative code (WAC) 365-230 and has been certified to conduct lead-based paint activities pursuant to WAC 365-230-200 as a:

Risk Assessor

<u>Certification #</u>	<u>Issuance Date</u>	<u>Expiration Date</u>
0258	3/23/2016	3/8/2019

STATE OF WASHINGTON

Department of Commerce

Lead-Based Paint Abatement Firm

PBS Engineering & Environmental Inc.

*Has fulfilled the certification requirements of
WAC 365-230
and has been certified to conduct lead-based
paint activities.*

Certification #

178

Issuance Date

05/24/2017

Expiration Date

09/03/2019