

Lead-Based Paint Inspection Report

Birch Creek
27360 129th Avenue SE
Kent, Washington

Prepared for:
Deborah McCaslin
King County Housing
700 Andover Park West, Suite C
Seattle, Washington 98188

February 23, 2018
PBS Project No. 40573.152



2517 EASTLAKE AVENUE EAST
SUITE 100
SEATTLE, WA 98102
206.233.9639 MAIN
866.727.0140 FAX
PBSUSA.COM

LEAD-BASED PAINT INSPECTION REPORT

Birch Creek
27360 129th Avenue SE
Kent, WA 98030

For

King County Housing Authority
700 Andover Park West, Suite C
Seattle, Washington 98188

This report is for the exclusive use of the client and is not to be photographed, photocopied, or similarly reproduced, in total or in part, without the express written consent of the client and/or PBS Engineering and Environmental Inc.

Prepared by:

PBS Engineering and Environmental Inc.
2517 Eastlake Avenue East Suite 100
Seattle, Washington 98102



TABLE OF CONTENTS

1 IDENTIFYING INFORMATION.....	1
2 LEAD-BASED PAINT INSPECTION.....	2
2.1 Site Information.....	2
2.2 Lead-Based Paint Inspection and Sampling	2
2.2.1 XRF Sampling.....	2
2.2.2 Bulk Paint-Chip Sampling	3
2.3 Components with Lead-Based Paint.....	3
2.4 Deteriorated Lead-Based Paint Surfaces.....	3

SUPPORTING DATA

TAB 1: XRF Data Sheets

TAB 2: Certifications

1 IDENTIFYING INFORMATION

BUILDING DATA

Birch Creek
27360 129th Ave SE
Kent, WA 98030

CLIENT DATA

King County Housing Authority
700 Andover Park West, Suite C
Seattle, WA 98188
Attn: Ms. Deborah McCaslin

SCOPE OF ASSESSMENT

PBS Engineering and Environmental, Inc. (PBS) conducted a lead-based paint inspection at Birch Creek on February 20 - 22, 2018, in accordance with the U.S. Department Housing and Urban Development (HUD), Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing.

CERTIFICATIONS

Risk Assessor

Janet Murphy
State of Washington
Department of Community, Trade and Economic Development
Risk Assessor Certification No: 0258, Expiration Date: 3/8/2019



Signature

February 23, 2018

Date

Firm

PBS Engineering and Environmental
2517 Eastlake Avenue East
Seattle, Washington 98102
Telephone: 206.223.9639

Certification No: 129143
Expiration Date: 7/31/2018

2 LEAD-BASED PAINT INSPECTION

2.1 Site Information

Birch Creek consist of 32 residential buildings with 262 units and separate Family Center, Recreation and Maintenance/Food Bank buildings. The Family Center Building and the Recreation Building were constructed in 2005 and 2006, respectively, and, therefore they were not included in the scope of this survey.

The residential buildings were substantially renovated in 2009-2010. All exterior siding and trim was replaced as well as interior walls, floors and ceilings. The buildings are of wood construction with gypsum interior walls and ceilings. The exterior is cement board siding and trim. Residential units are one, two, three, four and five bedrooms with a bathroom, kitchen/dining room and living room area. The buildings are in good condition.

Architectural finishes are uniform throughout. The majority of the interior components are painted. Walls are painted gypsum wallboard. Doors are painted wood or metal. Door and window frames are painted medium density fiberboard (MDF) or metal. The exterior window and door frames are cement board.

2.2 Lead-Based Paint Inspection and Sampling

Based on information provided by KCHA, Birch Creek Homes was constructed in the 1969. Based on Table 7.3 in Chapter 7 of the HUD Guidelines, 27 units at the site were included in PBS's inspection. Additionally, PBS inspected the Food Bank, Housing Tenant Reception and office space and playgrounds.

2.2.1 XRF Sampling

The presence of lead in paint was determined through x-ray fluorescence spectroscopy. A handheld Niton X-Ray Fluorescence Analyzer (XRF), Model XLP-300A Serial # 102877 operating in lead paint mode was used to perform a surface by surface lead paint inspection of each painted surface in the selected units and other building areas. Calibration was checked based on the requirements of the Performance Characteristic Sheet for the XRF Analyzer. All calibration readings were within the tolerance for this instrument.

HUD and the Environmental Protection Agency (EPA) have set 1.0 milligrams per square centimeter (mg/cm^2) as the threshold limit for lead-based paint as determined through X-Ray Fluorescence (XRF) testing. HUD and EPA have set 5,000 parts per million (ppm) or 0.5 percent by atomic absorption spectroscopy (AAS) laboratory analysis as the threshold limit for lead-based paint. Paint that is known to contain lead levels less than those described above does not have to be evaluated, although all deteriorated paint (paint surfaces in poor condition) should be repaired because it may contain lower levels of lead that may contribute to lead dust or lead contaminated soil hazards.

The "Side" information presented on the XRF data sheets is in relation to the side of the rooms or building exteriors where the unit address is located. The inspector/risk assessor used the address side of each residence as the basis to establish side "A". Sides B, C, and D follow in clockwise rotation.

Please refer to the XRF Sample Data Table located in Tab 1 for a complete list of XRF samples.

2.2.2 Bulk Paint-Chip Sampling

Bulk paint chip verification samples were collected when there was an inconclusive result with the XRF. Inconclusive results were not recorded during the Cedar Grove III inspection.

2.3 Components with Lead-Based Paint

None of the paint tested contained lead above the HUD level of 1.0 mg/cm² by XRF.

2.4 Deteriorated Lead-Based Paint Surfaces

Lead-based paint was not identified at the subject property. Painted surfaces were evaluated to be in an intact condition.

TAB 1

XRF Data Sheets

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1	SHUTTER CAL										5.92
2	NIST STANDARD				RED	BIRCH CREEK			TEST	Positive	1.1
3	NIST STANDARD				RED	BIRCH CREEK			TEST	Positive	1
4	NIST STANDARD				RED	BIRCH CREEK			TEST	Positive	1
5	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13118	Negative	<LOD
6	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13118	Negative	<LOD
7	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13118	Negative	<LOD
8	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13118	Negative	<LOD
9	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13118	Negative	<LOD
10	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13118	Negative	<LOD
11	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13118	Negative	<LOD
12	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13118	Negative	<LOD
13	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13118	Negative	<LOD
14	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13118	Negative	<LOD
15	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13118	Negative	<LOD
16	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13118	Negative	<LOD
17	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 13118	Negative	<LOD
18	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 13118	Negative	<LOD
19	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 13118	Negative	<LOD
20	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 13118	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
21	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 13118	Negative	<LOD
22	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 13118	Negative	<LOD
23	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 13118	Negative	<LOD
24	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 13118	Negative	<LOD
25	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 13118	Negative	<LOD
26	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 13118	Negative	<LOD
27	COVEBASE	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 13118	Negative	<LOD
28	BANISTER	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 13118	Negative	<LOD
29	HAND RAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 13118	Negative	<LOD
30	CEILING	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13118	Negative	<LOD
31	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13118	Negative	<LOD
32	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13118	Negative	<LOD
33	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13118	Negative	<LOD
34	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13118	Negative	<LOD
35	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13118	Negative	<LOD
36	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13118	Negative	<LOD
37	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
38	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
39	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
40	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
41	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
42	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
43	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
44	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
45	COVEBASE	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
46	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13118	Negative	<LOD
47	ROLL DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
48	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
49	COVEBASE	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
50	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
51	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
52	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
53	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
54	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13118	Negative	<LOD
55	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 13118	Negative	<LOD
56	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 13118	Negative	<LOD
57	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 13118	Negative	<LOD
58	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 13118	Negative	<LOD
59	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
60	DOOR FRAME	WOOD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
61	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
62	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
63	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
64	SIDING	CEMENT BOARD	D	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
65	SLIDING DOOR FRAME	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
66	SIDING	CEMENT BOARD	C	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
67	DOWN SPOUT	METAL	C	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
68	FENCE	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13118	Negative	<LOD
69	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 13153	Negative	<LOD
70	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 13153	Negative	<LOD
71	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 13153	Negative	<LOD
72	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 13153	Negative	<LOD
73	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 13153	Negative	<LOD
74	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD
75	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD
76	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD
77	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD
78	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD
79	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD
80	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
81	FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	LAUNDRY ROOM	UNIT 13153	Negative	<LOD
82	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 13153	Negative	<LOD
83	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 13153	Negative	<LOD
84	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 13153	Negative	<LOD
85	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 13153	Negative	<LOD
86	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 13153	Negative	<LOD
87	WINDOW FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 13153	Negative	<LOD
88	BALCONY DECK	WOOD	C	INTACT	TAN	BIRCH CREEK	SECOND	BALCONY	UNIT 13153	Negative	<LOD
89	HAND RAIL	METAL	C	INTACT	BLACK	BIRCH CREEK	SECOND	BALCONY	UNIT 13153	Negative	<LOD
90	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13153	Negative	<LOD
91	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13153	Negative	<LOD
92	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13153	Negative	<LOD
93	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13153	Negative	<LOD
94	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13153	Negative	<LOD
95	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13153	Negative	<LOD
96	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 13153	Negative	<LOD
97	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD
98	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD
99	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD
100	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
101	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD
102	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD
103	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD
104	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	FULL BATHROOM	UNIT 13153	Negative	<LOD
105	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
106	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
107	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
108	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
109	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
110	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
111	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
112	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 13153	Negative	<LOD
113	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD
114	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD
115	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD
116	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD
117	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD
118	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD
119	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD
120	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 13153	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
121	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
122	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
123	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
124	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
125	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
126	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
127	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
128	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 13153	Negative	<LOD
129	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIRWELL	UNIT 13153	Negative	<LOD
130	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	STAIRWELL	UNIT 13153	Negative	<LOD
131	HANDRAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIRWELL	UNIT 13153	Negative	<LOD
132	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
133	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
134	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
135	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
136	SIDING	CEMENT BOARD	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
137	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
138	DOOR	METAL	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
139	DOOR	METAL	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13153	Negative	<LOD
140	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13151	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
141	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13151	Negative	<LOD
142	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13151	Negative	<LOD
143	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13151	Negative	<LOD
144	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 13151	Negative	<LOD
145	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
146	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
147	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
148	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
149	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
150	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
151	FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
152	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
153	COVEBASE	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 13151	Negative	<LOD
154	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD
155	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD
156	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD
157	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD
158	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD
159	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD
160	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
161	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 13151	Negative	<LOD
162	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
163	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
164	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
165	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
166	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
167	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
168	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
169	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
170	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
171	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 13151	Negative	<LOD
172	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 13151	Negative	<LOD
173	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 13151	Negative	<LOD
174	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 13151	Negative	<LOD
175	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 13151	Negative	<LOD
176	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 13151	Negative	<LOD
177	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 13151	Negative	<LOD
178	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 13151	Negative	<LOD
179	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 13151	Negative	<LOD
180	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 13151	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
181	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 13151	Negative	<LOD
182	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 13151	Negative	<LOD
183	CEILING	DRYWALL	CM	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
184	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
185	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
186	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
187	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
188	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
189	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
190	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
191	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 13151	Negative	<LOD
192	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 13151	Negative	<LOD
193	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 13151	Negative	<LOD
194	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 13151	Negative	<LOD
195	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 13151	Negative	<LOD
196	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 13151	Negative	<LOD
197	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 13151	Negative	<LOD
198	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 13151	Negative	<LOD
199	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13151	Negative	<LOD
200	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13151	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
201	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13151	Negative	<LOD
202	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13151	Negative	<LOD
203	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13151	Negative	<LOD
204	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 13151	Negative	<LOD
205	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12957	Negative	<LOD
206	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12957	Negative	<LOD
207	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12957	Negative	<LOD
208	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12957	Negative	<LOD
209	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12957	Negative	<LOD
210	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12957	Negative	<LOD
211	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
212	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
213	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
214	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
215	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
216	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
217	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
218	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
219	DOOR FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12957	Negative	<LOD
220	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 12957	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
221	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 12957	Negative	<LOD
222	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 12957	Negative	<LOD
223	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 12957	Negative	<LOD
224	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 12957	Negative	<LOD
225	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 12957	Negative	<LOD
226	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	FULL BATHROOM	UNIT 12957	Negative	<LOD
227	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
228	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
229	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
230	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
231	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
232	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
233	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
234	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12957	Negative	<LOD
235	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD
236	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD
237	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD
238	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD
239	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD
240	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
241	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD
242	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	HALF BATHROOM	UNIT 12957	Negative	<LOD
243	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 12957	Negative	<LOD
244	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 12957	Negative	<LOD
245	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 12957	Negative	<LOD
246	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 12957	Negative	<LOD
247	CEILING	DRYWALL	BM	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
248	CEILING	DRYWALL	BM	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
249	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
250	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
251	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
252	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
253	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
254	WINDOW SILL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
255	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
256	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
257	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12957	Negative	<LOD
258	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD
259	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD
260	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
261	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD
262	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD
263	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD
264	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD
265	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12957	Negative	<LOD
266	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12957	Negative	<LOD
267	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12957	Negative	<LOD
268	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12957	Negative	<LOD
269	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12957	Negative	<LOD
270	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12957	Negative	<LOD
271	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12957	Negative	<LOD
272	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12945	Negative	<LOD
273	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12945	Negative	<LOD
274	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12945	Negative	<LOD
275	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12945	Negative	<LOD
276	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12945	Negative	<LOD
277	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12945	Negative	<LOD
278	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
279	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
280	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
281	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
282	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
283	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
284	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
285	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
286	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12945	Negative	<LOD
287	SHUTTER CAL										5.71
288	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12945	Negative	<LOD
289	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12945	Negative	<LOD
290	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12945	Negative	<LOD
291	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12945	Negative	<LOD
292	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12945	Negative	<LOD
293	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12945	Negative	<LOD
294	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12945	Negative	<LOD
295	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD
296	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD
297	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD
298	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD
299	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD
300	ROLL DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
301	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD
302	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12945	Negative	<LOD
303	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 12945	Negative	<LOD
304	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 12945	Negative	<LOD
305	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	LAUNDRY AREA	UNIT 12945	Negative	<LOD
306	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
307	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
308	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
309	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
310	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
311	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
312	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
313	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12945	Negative	<LOD
314	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12945	Negative	<LOD
315	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12945	Negative	<LOD
316	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12945	Negative	<LOD
317	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12945	Negative	<LOD
318	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12945	Negative	<LOD
319	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12945	Negative	<LOD
320	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12945	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
321	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12921	Negative	<LOD
322	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12921	Negative	<LOD
323	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12921	Negative	<LOD
324	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12921	Negative	<LOD
325	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12921	Negative	<LOD
326	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12921	Negative	<LOD
327	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12921	Negative	<LOD
328	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12921	Negative	<LOD
329	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12921	Negative	<LOD
330	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12921	Negative	<LOD
331	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12921	Negative	<LOD
332	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12921	Negative	<LOD
333	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12921	Negative	<LOD
334	DOOR FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12921	Negative	<LOD
335	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
336	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
337	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
338	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
339	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
340	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
341	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
342	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
343	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
344	HAND RAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
345	BANISTER	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12921	Negative	<LOD
346	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12921	Negative	<LOD
347	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12921	Negative	<LOD
348	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12921	Negative	<LOD
349	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12921	Negative	<LOD
350	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12921	Negative	<LOD
351	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12921	Negative	<LOD
352	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12921	Negative	<LOD
353	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
354	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
355	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
356	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
357	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
358	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
359	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
360	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
361	FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
362	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12921	Negative	<LOD
363	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
364	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
365	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
366	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
367	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
368	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
369	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
370	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
371	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12921	Negative	<LOD
372	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
373	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
374	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
375	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
376	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
377	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
378	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
379	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12921	Negative	<LOD
380	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12921	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
381	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12921	Negative	<LOD
382	WINDW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12921	Negative	<LOD
383	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12921	Negative	<LOD
384	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12921	Negative	<LOD
385	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12921	Negative	<LOD
386	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12921	Negative	<LOD
387	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12905	Negative	<LOD
388	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12905	Negative	<LOD
389	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12905	Negative	<LOD
390	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12905	Negative	<LOD
391	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12905	Negative	<LOD
392	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12905	Negative	<LOD
393	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12905	Negative	<LOD
394	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12905	Negative	<LOD
395	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12905	Negative	<LOD
396	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12905	Negative	<LOD
397	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12905	Negative	<LOD
398	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12905	Negative	<LOD
399	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12905	Negative	<LOD
400	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12905	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
401	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12905	Negative	<LOD
402	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12905	Negative	<LOD
403	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12905	Negative	<LOD
404	BANISTER	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12905	Negative	<LOD
405	HAND RAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12905	Negative	<LOD
406	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12905	Negative	<LOD
407	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12905	Negative	<LOD
408	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12905	Negative	<LOD
409	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12905	Negative	<LOD
410	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12905	Negative	<LOD
411	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12905	Negative	<LOD
412	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12905	Negative	<LOD
413	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD
414	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD
415	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD
416	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD
417	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD
418	WINDOW SILL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD
419	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD
420	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1x	UNIT 12905	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
421	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12905	Negative	<LOD
422	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12905	Negative	<LOD
423	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12905	Negative	<LOD
424	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12905	Negative	<LOD
425	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12905	Negative	<LOD
426	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12905	Negative	<LOD
427	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12905	Negative	<LOD
428	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
429	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
430	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
431	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
432	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
433	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
434	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
435	FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12905	Negative	<LOD
436	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12835	Negative	<LOD
437	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12835	Negative	<LOD
438	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12835	Negative	<LOD
439	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12835	Negative	<LOD
440	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12835	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
441	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12835	Negative	<LOD
442	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12835	Negative	<LOD
443	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12835	Negative	<LOD
444	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12835	Negative	<LOD
445	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12835	Negative	<LOD
446	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12835	Negative	<LOD
447	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12835	Negative	<LOD
448	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12385	Negative	<LOD
449	DOOR FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12385	Negative	<LOD
450	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12385	Negative	<LOD
451	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12385	Negative	<LOD
452	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12835	Negative	<LOD
453	HAND RAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12835	Negative	<LOD
454	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
455	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
456	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
457	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
458	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
459	ROLL DOOR	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
460	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
461	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
462	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 12835	Negative	<LOD
463	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12835	Negative	<LOD
464	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
465	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
466	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
467	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
468	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
469	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
470	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
471	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 2	UNIT 12385	Negative	<LOD
472	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12385	Negative	<LOD
473	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12835	Negative	<LOD
474	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12385	Negative	<LOD
475	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12385	Negative	<LOD
476	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12385	Negative	<LOD
477	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12385	Negative	<LOD
478	FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 3	UNIT 12385	Negative	<LOD
479	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12385	Negative	<LOD
480	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12385	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
481	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12385	Negative	<LOD
482	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12385	Negative	<LOD
483	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12835	Negative	<LOD
484	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12385	Negative	<LOD
485	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12385	Negative	<LOD
486	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
487	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
488	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
489	COLUMN	CEMENT BOARD	A	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
490	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
491	SIDING	CEMENT BOARD	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
492	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
493	GAS METER	METAL	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
494	DOOR	METAL	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
495	FOUNDATION	CONCRETE	B	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12385	Negative	<LOD
496	CEILING	CONCRETE		INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
497	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
498	WALL	CMU	A	INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
499	WALL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
500	WALL	CONCRETE	D	INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
501	WALL	CMU	B	INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
502	DOOR	METAL	B	INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
503	DOOR FRAME	METAL	B	INTACT	WHITE	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
504	DOOR FRAME	METAL	B	INTACT	BROWN	BIRCH CREEK	FIRST	FOOD BANK	FOOD BANK	Negative	<LOD
505	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
506	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
507	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
508	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
509	COVEBASE	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
510	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
511	COVEBASE	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
512	COVEBASE	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 1	MANAGEMENT NT OFFICE	Negative	<LOD
513	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT NT OFFICE	Negative	<LOD
514	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT NT OFFICE	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
515	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT OFFICE	Negative	<LOD
516	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT OFFICE	Negative	<LOD
517	COVEBASE	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT OFFICE	Negative	<LOD
518	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT OFFICE	Negative	<LOD
519	COVEBASE	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT OFFICE	Negative	<LOD
520	COVEBASE	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	MEETING ROOM 2	MANAGEMENT OFFICE	Negative	<LOD
521	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	RECEPTION	MANAGEMENT OFFICE	Negative	<LOD
522	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	RECEPTION	MANAGEMENT OFFICE	Negative	<LOD
523	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	RECEPTION	MANAGEMENT OFFICE	Negative	<LOD
524	BEAM COLUMN	METAL	B	INTACT	BLUE	BIRCH CREEK	FIRST	RECEPTION	MANAGEMENT OFFICE	Negative	<LOD
525	BEAM COLUMN	METAL	D	INTACT	BLUE	BIRCH CREEK	FIRST	RECEPTION	MANAGEMENT OFFICE	Negative	<LOD
526	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	RESTROOM	MANAGEMENT OFFICE	Negative	<LOD
527	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	RESTROOM	MANAGEMENT OFFICE	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
528	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	RESTROOM	MANAGEMENT OFFICE	Negative	<LOD
529	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	RESTROOM	MANAGEMENT OFFICE	Negative	<LOD
530	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	RESTROOM	MANAGEMENT OFFICE	Negative	<LOD
531	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	RESTROOM	MANAGEMENT OFFICE	Negative	<LOD
532	SHUTTER CAL										6.03
533	NIST				RED	BIRCH CREEK				Positive	1.4
534	NIST				RED	BIRCH CREEK				Positive	1.5
535	NIST				RED	BIRCH CREEK				Positive	1.4
536	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27410	Negative	<LOD
537	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27410	Negative	<LOD
538	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27410	Negative	<LOD
539	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27410	Negative	<LOD
540	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27410	Negative	<LOD
541	WINDOW SILL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27410	Negative	<LOD
542	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27410	Negative	<LOD
543	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27410	Negative	<LOD
544	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27410	Negative	<LOD
545	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27410	Negative	<LOD
546	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27410	Negative	<LOD
547	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27410	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
548	DOOR FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27410	Negative	<LOD
549	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
550	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
551	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
552	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
553	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
554	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
555	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
556	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27410	Negative	<LOD
557	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27410	Negative	<LOD
558	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27410	Negative	<LOD
559	HAND RAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27410	Negative	<LOD
560	BANISTER	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27410	Negative	<LOD
561	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27410	Negative	<LOD
562	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27410	Negative	<LOD
563	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27410	Negative	<LOD
564	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27410	Negative	<LOD
565	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27410	Negative	<LOD
566	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
567	WALL	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
568	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
569	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
570	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
571	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
572	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
573	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
574	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
575	ROLL DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27410	Negative	<LOD
576	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
577	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
578	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
579	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
580	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
581	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
582	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
583	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
584	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27410	Negative	<LOD
585	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
586	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
587	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
588	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
589	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
590	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
591	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
592	FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
593	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27410	Negative	<LOD
594	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 27410	Negative	<LOD
595	COVEBASE	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 27410	Negative	<LOD
596	DOOR	METAL	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
597	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
598	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
599	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
600	SIDING	CEMENT BOARD	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
601	SIDING	CEMENT BOARD	C	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
602	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
603	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27410	Negative	<LOD
604	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
605	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
606	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
607	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
608	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
609	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
610	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
611	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
612	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
613	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
614	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
615	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
616	DOOR FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
617	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
618	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
619	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
620	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
621	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
622	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
623	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
624	WINDOW SILL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
625	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
626	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27419	Negative	<LOD
627	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
628	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
629	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
630	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
631	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
632	DOOR	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
633	DOOR FRAME	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
634	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
635	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
636	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
637	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
638	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
639	SIDING	CEMENT BOARD	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
640	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
641	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
642	DOWNSPOUT	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
643	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
644	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
645	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
646	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
647	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	0.7

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
648	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27419	Negative	<LOD
649	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
650	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
651	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
652	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
653	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
654	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
655	FRAM	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
656	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27419	Negative	<LOD
657	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
658	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
659	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
660	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
661	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
662	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
663	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27419	Negative	<LOD
664	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27419	Negative	<LOD
665	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27419	Negative	<LOD
666	HANDRAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27419	Negative	<LOD
667	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27419	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
668	CEILING	DRYWALL	DM	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
669	CEILING	DRYWALL	DM	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
670	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
671	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
672	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
673	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
674	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
675	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27419	Negative	<LOD
676	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
677	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
678	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
679	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
680	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
681	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
682	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
683	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
684	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27419	Negative	<LOD
685	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD
686	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD
687	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
688	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD
689	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD
690	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD
691	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD
692	WINDOW FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27419	Negative	<LOD
693	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
694	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
695	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
696	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
697	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
698	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
699	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
700	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 27419	Negative	<LOD
701	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
702	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
703	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
704	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
705	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
706	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD
707	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27419	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
708	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
709	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
710	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
711	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
712	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
713	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
714	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
715	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27371	Negative	<LOD
716	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27371	Negative	<LOD
717	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27371	Negative	<LOD
718	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27371	Negative	<LOD
719	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27371	Negative	<LOD
720	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27371	Negative	<LOD
721	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27371	Negative	<LOD
722	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27371	Negative	<LOD
723	HANDRAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27371	Negative	<LOD
724	BANISTER	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27371	Negative	<LOD
725	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27371	Negative	<LOD
726	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27371	Negative	<LOD
727	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27371	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
728	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27371	Negative	<LOD
729	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27371	Negative	<LOD
730	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27371	Negative	<LOD
731	DOOR	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27371	Negative	<LOD
732	SHUTTER CAL										6.01
733	CEILING	DRYWALL		INTACT	YELLOW	BIRCH CREEK	SECOND	BATHROOM	UNIT 27367	Negative	<LOD
734	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27367	Negative	<LOD
735	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27367	Negative	<LOD
736	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27367	Negative	<LOD
737	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27367	Negative	<LOD
738	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27367	Negative	<LOD
739	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27367	Negative	<LOD
740	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
741	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
742	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
743	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
744	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
745	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
746	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
747	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
748	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27367	Negative	<LOD
749	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
750	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
751	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
752	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
753	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
754	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
755	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
756	FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27367	Negative	<LOD
757	COVEBASE	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 27367	Negative	<LOD
758	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 27367	Negative	<LOD
759	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27367	Negative	<LOD
760	DOOR FRAME	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27367	Negative	<LOD
761	WINDOW FRAME	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27367	Negative	<LOD
762	COLUMN	METAL	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27367	Negative	<LOD
763	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27367	Negative	<LOD
764	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27367	Negative	<LOD
765	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27367	Negative	<LOD
766	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27368	Negative	<LOD
767	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27368	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
768	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27368	Negative	<LOD
769	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27368	Negative	<LOD
770	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27368	Negative	<LOD
771	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27368	Negative	<LOD
772	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27368	Negative	<LOD
773	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27368	Negative	<LOD
774	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27368	Negative	<LOD
775	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27368	Negative	<LOD
776	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27368	Negative	<LOD
777	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27368	Negative	<LOD
778	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27368	Negative	<LOD
779	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27368	Negative	<LOD
780	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27368	Negative	<LOD
781	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27368	Negative	<LOD
782	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27368	Negative	<LOD
783	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27368	Negative	<LOD
784	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27368	Negative	<LOD
785	HAND RAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27368	Negative	<LOD
786	BANISTER	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27368	Negative	<LOD
787	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27368	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
788	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27368	Negative	<LOD
789	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27368	Negative	<LOD
790	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27368	Negative	<LOD
791	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27368	Negative	<LOD
792	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27368	Negative	<LOD
793	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27368	Negative	<LOD
794	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27368	Negative	<LOD
795	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27368	Negative	<LOD
796	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27368	Negative	<LOD
797	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27368	Negative	<LOD
798	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27368	Negative	<LOD
799	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27368	Negative	<LOD
800	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27368	Negative	<LOD
801	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD
802	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD
803	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD
804	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD
805	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD
806	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD
807	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
808	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27368	Negative	<LOD
809	SOFFIT	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
810	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
811	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
812	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
813	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
814	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
815	COLUMN	CEMENT BOARD	A	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
816	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27368	Negative	<LOD
817	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27352	Negative	<LOD
818	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27352	Negative	<LOD
819	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27352	Negative	<LOD
820	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27352	Negative	<LOD
821	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27352	Negative	<LOD
822	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27352	Negative	<LOD
823	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27352	Negative	<LOD
824	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27352	Negative	<LOD
825	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27352	Negative	<LOD
826	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27352	Negative	<LOD
827	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27352	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
828	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27352	Negative	<LOD
829	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27352	Negative	<LOD
830	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27352	Negative	<LOD
831	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27352	Negative	<LOD
832	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27352	Negative	<LOD
833	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27352	Negative	<LOD
834	SHUTTER CAL										5.89
835	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27352	Negative	<LOD
836	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27352	Negative	<LOD
837	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27352	Negative	<LOD
838	HANDRAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27352	Negative	<LOD
839	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27352	Negative	<LOD
840	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27352	Negative	<LOD
841	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27352	Negative	<LOD
842	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27352	Negative	<LOD
843	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27352	Negative	<LOD
844	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27352	Negative	<LOD
845	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27352	Negative	<LOD
846	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27352	Negative	<LOD
847	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
848	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD
849	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD
850	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD
851	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD
852	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD
853	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD
854	DOOR FRAMR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27352	Negative	<LOD
855	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
856	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
857	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
858	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
859	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
860	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
861	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
862	ROLL DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27352	Negative	<LOD
863	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27352	Negative	<LOD
864	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27352	Negative	<LOD
865	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27352	Negative	<LOD
866	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27352	Negative	<LOD
867	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27352	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
868	COLUMN	CEMENT BOARD	A	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27352	Negative	<LOD
869	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27352	Negative	<LOD
870	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12800	Negative	<LOD
871	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12800	Negative	<LOD
872	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12800	Negative	<LOD
873	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12800	Negative	<LOD
874	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12800	Negative	<LOD
875	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12800	Negative	<LOD
876	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12800	Negative	<LOD
877	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12800	Negative	<LOD
878	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12800	Negative	<LOD
879	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12800	Negative	<LOD
880	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12800	Negative	<LOD
881	FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12800	Negative	<LOD
882	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12800	Negative	<LOD
883	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12800	Negative	<LOD
884	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12800	Negative	<LOD
885	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12800	Negative	<LOD
886	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12800	Negative	<LOD
887	DOOR	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12800	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
888	DOOR FRAME	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12800	Negative	<LOD
889	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12800	Negative	<LOD
890	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12800	Negative	<LOD
891	HAND RAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12800	Negative	<LOD
892	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12800	Negative	<LOD
893	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12800	Negative	<LOD
894	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12800	Negative	<LOD
895	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12800	Negative	<LOD
896	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12800	Negative	<LOD
897	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12800	Negative	<LOD
898	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12800	Negative	<LOD
899	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12800	Negative	<LOD
900	CEILING	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD
901	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD
902	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD
903	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD
904	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD
905	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD
906	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD
907	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12800	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
908	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12800	Negative	<LOD
909	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12800	Negative	<LOD
910	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12800	Negative	<LOD
911	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12800	Negative	<LOD
912	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12800	Negative	<LOD
913	WINDOW SILL	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12800	Negative	<LOD
914	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12800	Negative	<LOD
915	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
916	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
917	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
918	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
919	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
920	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
921	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
922	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
923	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12800	Negative	<LOD
924	DOWN SPOUT	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
925	GUTTER	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
926	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
927	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
928	SIDING	CEMENT BOARD	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
929	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
930	DOOR	METAL	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
931	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
932	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
933	COLUMN	CEMENT BOARD	A	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12800	Negative	<LOD
934	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 12920	Negative	<LOD
935	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 12920	Negative	<LOD
936	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 12920	Negative	<LOD
937	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	KITCHEN	UNIT 12920	Negative	<LOD
938	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 12920	Negative	<LOD
939	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 12920	Negative	<LOD
940	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 12920	Negative	<LOD
941	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 12920	Negative	<LOD
942	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	LIVING ROOM	UNIT 12920	Negative	<LOD
943	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	HALF BATHROOM	UNIT 12920	Negative	<LOD
944	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	HALF BATHROOM	UNIT 12920	Negative	<LOD
945	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	HALF BATHROOM	UNIT 12920	Negative	<LOD
946	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	HALF BATHROOM	UNIT 12920	Negative	<LOD
947	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	HALF BATHROOM	UNIT 12920	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
948	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
949	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
950	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
951	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
952	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	0.6
953	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
954	ROLL DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
955	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
956	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12920	Negative	<LOD
957	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12920	Negative	<LOD
958	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12920	Negative	<LOD
959	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12920	Negative	<LOD
960	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12920	Negative	<LOD
961	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12920	Negative	<LOD
962	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12920	Negative	<LOD
963	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12920	Negative	<LOD
964	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12920	Negative	<LOD
965	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12920	Negative	<LOD
966	ROLL DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12920	Negative	<LOD
967	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12920	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
968	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12920	Negative	<LOD
969	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12920	Negative	<LOD
970	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12920	Negative	<LOD
971	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
972	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
973	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
974	COLUMN	CEMENT BOARD	A	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
975	SIDING	CEMENT BOARD	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
976	GAS METER BOX	METAL	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
977	DOOR	METAL	B	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
978	DOOR FRAME	CEMENT BOARD	B	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
979	SOFFIT	CEMENT BOARD	B	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
980	DOWN SPOUT	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12920	Negative	<LOD
981	CEILING	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27253	Negative	<LOD
982	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27253	Negative	<LOD
983	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27253	Negative	<LOD
984	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27253	Negative	<LOD
985	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27253	Negative	<LOD
986	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27253	Negative	<LOD
987	CEILING	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27253	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
988	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27253	Negative	<LOD
989	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27253	Negative	<LOD
990	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27253	Negative	<LOD
991	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27253	Negative	<LOD
992	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27253	Negative	<LOD
993	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27253	Negative	<LOD
994	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27253	Negative	<LOD
995	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27253	Negative	<LOD
996	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27253	Negative	<LOD
997	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27253	Negative	<LOD
998	DOOR FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27253	Negative	<LOD
999	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27253	Negative	<LOD
1000	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27253	Negative	<LOD
1001	HAND RAIL	WOOD	C	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27253	Negative	<LOD
1002	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27253	Negative	<LOD
1003	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27253	Negative	<LOD
1004	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27253	Negative	<LOD
1005	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27253	Negative	<LOD
1006	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27253	Negative	<LOD
1007	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27253	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1008	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27253	Negative	<LOD
1009	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDEOOM 1	UNIT 27253	Negative	<LOD
1010	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDEOOM 1	UNIT 27253	Negative	<LOD
1011	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDEOOM 1	UNIT 27253	Negative	<LOD
1012	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDEOOM 1	UNIT 27253	Negative	<LOD
1013	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDEOOM 1	UNIT 27253	Negative	<LOD
1014	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDEOOM 1	UNIT 27253	Negative	<LOD
1015	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27253	Negative	<LOD
1016	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27253	Negative	<LOD
1017	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27253	Negative	<LOD
1018	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27253	Negative	<LOD
1019	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27253	Negative	<LOD
1020	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27253	Negative	<LOD
1021	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27253	Negative	<LOD
1022	CEILING	MINIBLIND		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1023	WALL	MINIBLIND	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1024	WALL	MINIBLIND	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1025	WALL	MINIBLIND	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1026	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1027	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1028	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1029	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1030	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1031	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1032	SIDING	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	SECOND	BEDROOM 2 3	UNIT 27253	Negative	<LOD
1033	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27315	Negative	<LOD
1034	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27315	Negative	<LOD
1035	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27315	Negative	<LOD
1036	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27315	Negative	<LOD
1037	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27315	Negative	<LOD
1038	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27315	Negative	<LOD
1039	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27315	Negative	<LOD
1040	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27315	Negative	<LOD
1041	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27315	Negative	<LOD
1042	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27315	Negative	<LOD
1043	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27315	Negative	<LOD
1044	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD
1045	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD
1046	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD
1047	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1048	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD
1049	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD
1050	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD
1051	FRAME,	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27315	Negative	<LOD
1052	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27315	Negative	<LOD
1053	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27315	Negative	<LOD
1054	HAND RAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27315	Negative	<LOD
1055	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27315	Negative	<LOD
1056	CABINET	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1057	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1058	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1059	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1060	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1061	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1062	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1063	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27315	Negative	<LOD
1064	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD
1065	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD
1066	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD
1067	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1068	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD
1069	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD
1070	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD
1071	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27315	Negative	<LOD
1072	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1073	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1074	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1075	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1076	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1077	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1078	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1079	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27315	Negative	<LOD
1080	DOWN SPOUT	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD
1081	GUTTER	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD
1082	SOFFIT	CEMENT BOARD	C	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD
1083	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD
1084	DOOR	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD
1085	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD
1086	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD
1087	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27315	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1088	SHUTTER CAL										5.6
1089	NIST				RED	BIRCH CREEK				Positive	1.1
1090	NIST				RED	BIRCH CREEK				Positive	1
1091	NIST				RED	BIRCH CREEK				Positive	1
1092	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12808	Negative	<LOD
1093	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12808	Negative	<LOD
1094	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12808	Negative	<LOD
1095	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12808	Negative	0.7
1096	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12808	Negative	<LOD
1097	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12808	Negative	<LOD
1098	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12808	Negative	<LOD
1099	CEILING	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12808	Negative	<LOD
1100	CEILING	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12808	Negative	<LOD
1101	SHUTTER CAL										6.24
1102	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12808	Negative	<LOD
1103	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12808	Negative	<LOD
1104	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12808	Negative	<LOD
1105	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12808	Negative	<LOD
1106	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12808	Negative	<LOD
1107	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12808	Negative	<LOD
1108	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12808	Negative	<LOD
1109	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12808	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1110	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12808	Negative	<LOD
1111	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12808	Negative	<LOD
1112	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12808	Negative	<LOD
1113	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWEL	UNIT 12808	Negative	<LOD
1114	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWEL	UNIT 12808	Negative	<LOD
1115	HANDRAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWEL	UNIT 12808	Negative	<LOD
1116	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWEL	UNIT 12808	Negative	<LOD
1117	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1118	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1119	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1120	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1121	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1122	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1123	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1124	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12808	Negative	<LOD
1125	CEILING	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12808	Negative	<LOD
1126	CEILING	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12808	Negative	<LOD
1127	CEILING	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12808	Negative	<LOD
1128	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12808	Negative	<LOD
1129	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12808	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1130	ROLL DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12808	Negative	<LOD
1131	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12808	Negative	<LOD
1132	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1133	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1134	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1135	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1136	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1137	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1138	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1139	ROLL DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1140	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12808	Negative	<LOD
1141	DOOR	METAL	A	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12808	Negative	<LOD
1142	DOOR FRAME	CEMENT BOARD	A	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12808	Negative	<LOD
1143	WINDOW FRAME	CEMENT BOARD	A	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12808	Negative	<LOD
1144	COLUMN	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12808	Negative	<LOD
1145	SOFFIT	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12808	Negative	<LOD
1146	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12808	Negative	<LOD
1147	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12820	Negative	<LOD
1148	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12820	Negative	<LOD
1149	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12820	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1150	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12820	Negative	<LOD
1151	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12820	Negative	<LOD
1152	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12820	Negative	<LOD
1153	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12820	Negative	<LOD
1154	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12820	Negative	<LOD
1155	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12820	Negative	<LOD
1156	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12820	Negative	<LOD
1157	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12820	Negative	<LOD
1158	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12820	Negative	<LOD
1159	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12820	Negative	<LOD
1160	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12820	Negative	<LOD
1161	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12820	Negative	<LOD
1162	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12820	Negative	<LOD
1163	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12820	Negative	<LOD
1164	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12820	Negative	<LOD
1165	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12820	Negative	<LOD
1166	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12820	Negative	<LOD
1167	HANDRAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12820	Negative	<LOD
1168	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12820	Negative	<LOD
1169	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12820	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1170	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12820	Negative	<LOD
1171	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12820	Negative	<LOD
1172	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12820	Negative	<LOD
1173	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12820	Negative	<LOD
1174	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12820	Negative	<LOD
1175	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12820	Negative	<LOD
1176	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12820	Negative	<LOD
1177	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12820	Negative	<LOD
1178	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12820	Negative	<LOD
1179	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12820	Negative	<LOD
1180	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12820	Negative	<LOD
1181	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12820	Negative	<LOD
1182	DOOR FRAMD	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12820	Negative	<LOD
1183	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1184	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1185	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1186	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1187	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1188	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1189	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1190	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1191	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1192	ROLL DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1193	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12820	Negative	<LOD
1194	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12820	Negative	<LOD
1195	COVEBASE	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12820	Negative	<LOD
1196	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1197	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1198	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1199	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1200	COLUMN	CEMENT BOARD	A	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1201	SOFFIT	CEMENT BOARD	A	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1202	SIDING	CEMENT BOARD	A	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1203	SIDING	CEMENT BOARD	C	INTACT	BLUE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1204	GUTTER	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1205	DOWNSPOUT	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12820	Negative	<LOD
1206	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12832	Negative	<LOD
1207	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12832	Negative	<LOD
1208	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12832	Negative	<LOD
1209	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12832	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1210	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12832	Negative	<LOD
1211	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12832	Negative	<LOD
1212	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12832	Negative	<LOD
1213	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12832	Negative	<LOD
1214	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12832	Negative	<LOD
1215	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12832	Negative	<LOD
1216	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12832	Negative	<LOD
1217	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12832	Negative	<LOD
1218	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12832	Negative	<LOD
1219	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12832	Negative	<LOD
1220	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12832	Negative	<LOD
1221	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12832	Negative	<LOD
1222	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12832	Negative	<LOD
1223	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12832	Negative	<LOD
1224	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12832	Negative	<LOD
1225	HAND RAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12832	Negative	<LOD
1226	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12832	Negative	<LOD
1227	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12832	Negative	<LOD
1228	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12832	Negative	<LOD
1229	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12832	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1230	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12832	Negative	<LOD
1231	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12832	Negative	<LOD
1232	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12832	Negative	<LOD
1233	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12832	Negative	<LOD
1234	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1235	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1236	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1237	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1238	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1239	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1240	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1241	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12832	Negative	<LOD
1242	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD
1243	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD
1244	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD
1245	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD
1246	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD
1247	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD
1248	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD
1249	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12832	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1250	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12832	Negative	<LOD
1251	COVEBASE	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12832	Negative	<LOD
1252	DOOR	METAL	A	INTACT	WHITE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1253	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1254	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1255	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1256	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1257	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1258	COLUMN	CEMENT BOARD	C	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1259	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12832	Negative	<LOD
1260	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12848	Negative	<LOD
1261	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12848	Negative	<LOD
1262	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12848	Negative	<LOD
1263	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12848	Negative	<LOD
1264	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12848	Negative	<LOD
1265	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12848	Negative	<LOD
1266	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12848	Negative	<LOD
1267	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12848	Negative	<LOD
1268	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12848	Negative	<LOD
1269	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12848	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1270	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM	UNIT 12848	Negative	<LOD
1271	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM	UNIT 12848	Negative	<LOD
1272	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM	UNIT 12848	Negative	<LOD
1273	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM	UNIT 12848	Negative	<LOD
1274	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM	UNIT 12848	Negative	<LOD
1275	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM	UNIT 12848	Negative	<LOD
1276	SHUTTER CAL										6.21
1277	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12848	Negative	<LOD
1278	HAND RAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12848	Negative	<LOD
1279	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12848	Negative	<LOD
1280	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12848	Negative	<LOD
1281	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12848	Negative	<LOD
1282	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12848	Negative	<LOD
1283	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12848	Negative	<LOD
1284	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12848	Negative	<LOD
1285	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12848	Negative	<LOD
1286	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12848	Negative	<LOD
1287	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12848	Negative	<LOD
1288	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12848	Negative	<LOD
1289	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12848	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1290	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12848	Negative	<LOD
1291	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12848	Negative	<LOD
1292	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12848	Negative	<LOD
1293	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1294	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1295	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1296	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1297	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1298	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1299	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1300	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12848	Negative	<LOD
1301	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12848	Negative	<LOD
1302	COVEBASE	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12848	Negative	<LOD
1303	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12848	Negative	<LOD
1304	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12848	Negative	<LOD
1305	WINDOW FRAME	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12848	Negative	<LOD
1306	SIDING	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12848	Negative	<LOD
1307	SOFFIT	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12848	Negative	<LOD
1308	COLUMN	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12848	Negative	<LOD
1309	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12848	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1310	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12849	Negative	<LOD
1311	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12849	Negative	<LOD
1312	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12849	Negative	<LOD
1313	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12849	Negative	<LOD
1314	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12849	Negative	<LOD
1315	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12849	Negative	<LOD
1316	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12849	Negative	<LOD
1317	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12849	Negative	<LOD
1318	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12849	Negative	<LOD
1319	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12849	Negative	<LOD
1320	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12849	Negative	<LOD
1321	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12849	Negative	<LOD
1322	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12849	Negative	<LOD
1323	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12849	Negative	<LOD
1324	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12849	Negative	<LOD
1325	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12849	Negative	<LOD
1326	CEILING	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12849	Negative	<LOD
1327	CEILING	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12849	Negative	<LOD
1328	HAND RAIL	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12849	Negative	<LOD
1329	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12849	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1330	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12849	Negative	<LOD
1331	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12849	Negative	<LOD
1332	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12849	Negative	<LOD
1333	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12849	Negative	<LOD
1334	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12849	Negative	<LOD
1335	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12849	Negative	<LOD
1336	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12849	Negative	<LOD
1337	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12849	Negative	<LOD
1338	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12849	Negative	<LOD
1339	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12849	Negative	<LOD
1340	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12849	Negative	<LOD
1341	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12849	Negative	<LOD
1342	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12849	Negative	<LOD
1343	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD
1344	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD
1345	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD
1346	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD
1347	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD
1348	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD
1349	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1350	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12849	Negative	<LOD
1351	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12849	Negative	<LOD
1352	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12849	Negative	<LOD
1353	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12849	Negative	<LOD
1354	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12849	Negative	<LOD
1355	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12849	Negative	<LOD
1356	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12849	Negative	<LOD
1357	WINDOW SILL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12849	Negative	<LOD
1358	DOOR	METAL	A	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12849	Negative	<LOD
1359	DOOR FRAME	CEMENT BOARD	A	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12849	Negative	<LOD
1360	WINDOW FRAME	CEMENT BOARD	A	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12849	Negative	<LOD
1361	SOFFIT	CEMENT BOARD	A	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12849	Negative	<LOD
1362	SIDING	CEMENT BOARD	A	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12849	Negative	<LOD
1363	SIDING	CEMENT BOARD	C	INTACT	TAN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12849	Negative	<LOD
1364	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12839	Negative	<LOD
1365	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12839	Negative	<LOD
1366	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12839	Negative	<LOD
1367	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12839	Negative	<LOD
1368	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12839	Negative	<LOD
1369	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12839	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1370	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12839	Negative	<LOD
1371	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12839	Negative	<LOD
1372	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12839	Negative	<LOD
1373	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12839	Negative	<LOD
1374	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12839	Negative	<LOD
1375	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12839	Negative	<LOD
1376	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12839	Negative	<LOD
1377	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12839	Negative	<LOD
1378	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12839	Negative	<LOD
1379	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12839	Negative	<LOD
1380	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12839	Negative	<LOD
1381	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12839	Negative	<LOD
1382	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12839	Negative	<LOD
1383	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12839	Negative	<LOD
1384	HAND RAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12839	Negative	<LOD
1385	HAND RAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12839	Negative	<LOD
1386	BANISTER	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12839	Negative	<LOD
1387	CEILING	DRYWALL	BM	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD
1388	CEILING	DRYWALL	BM	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD
1389	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1390	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD
1391	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD
1392	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD
1393	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD
1394	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12839	Negative	<LOD
1395	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1396	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1397	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1398	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1399	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1400	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1401	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1402	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12839	Negative	<LOD
1403	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1404	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1405	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1406	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1407	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1408	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1409	ROLL DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1410	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1411	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12839	Negative	<LOD
1412	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12839	Negative	<LOD
1413	COVEBASE	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12839	Negative	<LOD
1414	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12839	Negative	<LOD
1415	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12839	Negative	<LOD
1416	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12839	Negative	<LOD
1417	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12839	Negative	<LOD
1418	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12839	Negative	<LOD
1419	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12839	Negative	<LOD
1420	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12839	Negative	<LOD
1421	BENCH	METAL	C	INTACT	GREEN	BIRCH CREEK	FIRST	EXTERIOR	North Play Area	Negative	<LOD
1422	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12967	Negative	<LOD
1423	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12967	Negative	<LOD
1424	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12967	Negative	<LOD
1425	WINDOW	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12967	Negative	<LOD
1426	WINDOW	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12967	Negative	<LOD
1427	WINDOW	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12967	Negative	<LOD
1428	WINDOW	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 12967	Negative	<LOD
1429	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1430	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD
1431	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD
1432	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD
1433	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD
1434	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD
1435	DOOR	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD
1436	DOOR FRAME	METAL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 12967	Negative	<LOD
1437	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12967	Negative	<LOD
1438	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12967	Negative	<LOD
1439	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12967	Negative	<LOD
1440	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12967	Negative	<LOD
1441	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12967	Negative	<LOD
1442	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12967	Negative	<LOD
1443	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 12967	Negative	<LOD
1444	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12967	Negative	<LOD
1445	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12967	Negative	<LOD
1446	HANDRAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12967	Negative	<LOD
1447	BANISTER	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 12967	Negative	<LOD
1448	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12967	Negative	<LOD
1449	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12967	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1450	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12967	Negative	<LOD
1451	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12967	Negative	<LOD
1452	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12967	Negative	<LOD
1453	DOOR	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12967	Negative	<LOD
1454	DOOR FRAME	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 12967	Negative	<LOD
1455	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1456	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1457	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1458	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1459	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1460	WINDOW SIL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1461	DOOR	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1462	DOOR FRAME	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 12967	Negative	<LOD
1463	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD
1464	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD
1465	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD
1466	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD
1467	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD
1468	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD
1469	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1470	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 12967	Negative	<LOD
1471	WALL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12967	Negative	<LOD
1472	WALL	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12967	Negative	<LOD
1473	WALL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12967	Negative	<LOD
1474	WALL	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12967	Negative	<LOD
1475	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12967	Negative	<LOD
1476	WINDOW SILL	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 3	UNIT 12967	Negative	<LOD
1477	COVEBASE	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12967	Negative	<LOD
1478	COVEBASE	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12967	Negative	<LOD
1479	COVEBASE	WOOD	D	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 12967	Negative	<LOD
1480	SOFFIT	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1481	COLUMN	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1482	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1483	SIDING	CEMENT BOARD	D	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1484	GAS METER BOX	METAL	D	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1485	SIDING	CEMENT BOARD	D	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1486	SIDING	CEMENT BOARD	C	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1487	DOWNSPOUT	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1488	GUTTER	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 12967	Negative	<LOD
1489	SHUTTER CAL										6.5

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1490	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1491	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1492	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1493	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1494	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1495	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1496	DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1497	DOOR FRAME	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 1	UNIT 27415	Negative	<LOD
1498	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1499	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1500	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1501	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1502	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1503	DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1504	DOOR FRAME	WOOD	A	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1505	ROLL DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1506	ROLL DOOR	WOOD	C	INTACT	WHITE	BIRCH CREEK	SECOND	BEDROOM 2	UNIT 27415	Negative	<LOD
1507	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27415	Negative	<LOD
1508	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27415	Negative	<LOD
1509	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27415	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1510	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27415	Negative	<LOD
1511	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27415	Negative	<LOD
1512	DOOR	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27415	Negative	<LOD
1513	DOOR FRAME	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	SECOND	BATHROOM	UNIT 27415	Negative	<LOD
1514	COVEBASE	WOOD	B	INTACT	WHITE	BIRCH CREEK	SECOND	STAIR LANDING	UNIT 27415	Negative	<LOD
1515	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27415	Negative	<LOD
1516	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27415	Negative	<LOD
1517	HANDRAIL	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27415	Negative	<LOD
1518	BANISTER	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	STAIRWELL	UNIT 27415	Negative	<LOD
1519	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27415	Negative	<LOD
1520	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27415	Negative	<LOD
1521	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27415	Negative	<LOD
1522	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27415	Negative	<LOD
1523	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27415	Negative	<LOD
1524	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27415	Negative	<LOD
1525	WINDOW SILL	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27415	Negative	<LOD
1526	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27415	Negative	<LOD
1527	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27415	Negative	<LOD
1528	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27415	Negative	<LOD
1529	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27415	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1530	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27415	Negative	<LOD
1531	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27415	Negative	<LOD
1532	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27415	Negative	<LOD
1533	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27415	Negative	<LOD
1534	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27415	Negative	<LOD
1535	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27415	Negative	<LOD
1536	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1537	SOFFIT	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1538	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1539	SIDING	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1540	COLUMN	CEMENT BOARD	A	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1541	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1542	WINDOW SILL	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1543	WINDOW SILL	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1544	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1545	GUTTER	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1546	DOWNSPOUT	METAL	C	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27415	Negative	<LOD
1547	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27351	Negative	<LOD
1548	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27351	Negative	<LOD
1549	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27351	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1550	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27351	Negative	<LOD
1551	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27351	Negative	<LOD
1552	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	KITCHEN	UNIT 27351	Negative	<LOD
1553	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27351	Negative	<LOD
1554	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27351	Negative	<LOD
1555	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27351	Negative	<LOD
1556	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27351	Negative	<LOD
1557	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27351	Negative	<LOD
1558	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	LIVING ROOM	UNIT 27351	Negative	<LOD
1559	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1560	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1561	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1562	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1563	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1564	WINDOW FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1565	ROLL DOOR	WOOD	A	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1566	DOOR	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1567	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1568	DOOR FRAME	WOOD	D	INTACT	WHITE	BIRCH CREEK	FIRST	BEDROOM 1	UNIT 27351	Negative	<LOD
1569	CEILING	DRYWALL		INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27351	Negative	<LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1570	WALL	DRYWALL	A	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27351	Negative	<LOD
1571	WALL	DRYWALL	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27351	Negative	<LOD
1572	WALL	DRYWALL	C	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27351	Negative	<LOD
1573	WALL	DRYWALL	D	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27351	Negative	<LOD
1574	DOOR	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27351	Negative	<LOD
1575	DOOR FRAME	WOOD	B	INTACT	WHITE	BIRCH CREEK	FIRST	BATHROOM	UNIT 27351	Negative	<LOD
1576	DOOR	METAL	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1577	DOOR FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1578	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1579	WINDOW FRAME	CEMENT BOARD	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1580	WINDOW FRAME	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1581	SOFFIT	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1582	COLUMN	CEMENT BOARD	C	INTACT	ORANGE	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1583	SIDING	CEMENT BOARD	A	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1584	SIDING	CEMENT BOARD	B	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1585	SIDING	CEMENT BOARD	C	INTACT	YELLOW	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1586	GUTTER	METAL	B	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1587	DOWNSPOUT	METAL	B	INTACT	BROWN	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1588	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD
1589	FENCING	METAL	A	INTACT	BLACK	BIRCH CREEK	FIRST	EXTERIOR	UNIT 27351	Negative	<LOD

TAB 2
Certification



STATE OF WASHINGTON

Department of Commerce
Lead-Based Paint Program

Janet J. Murphy

Has fulfilled the certification requirements of Washington Administrative code (WAC) 365-230 and has been certified to conduct lead-based paint activities pursuant to WAC 365-230-200 as a:

Risk Assessor

<u>Certification #</u>	<u>Issuance Date</u>	<u>Expiration Date</u>
0258	3/23/2016	3/8/2019

STATE OF WASHINGTON

Department of Commerce

Lead-Based Paint Abatement Firm

PBS Engineering & Environmental Inc.

*Has fulfilled the certification requirements of
WAC 365-230
and has been certified to conduct lead-based
paint activities.*

Certification #

178

Issuance Date

05/24/2017

Expiration Date

09/03/2019