

Lead-Based Paint Inspection Report

Cascade
20500 106th Avenue SE
Kent, Washington 98031

Prepared for:
Deborah McCaslin
King County Housing
700 Andover Park West, Suite C
Seattle, Washington 98188

September 27, 2017
PBS Project No. 40573.140



2517 EASTLAKE AVENUE EAST
SUITE 100
SEATTLE, WA 98102
206.233.9639 MAIN
866.727.0140 FAX
PBSUSA.COM

LEAD-BASED PAINT INSPECTION REPORT

Cascade
20500 106th Ave. SE
Kent, Washington 98031

For

King County Housing Authority
700 Andover Park West, Suite C
Seattle, Washington 98188

This report is for the exclusive use of the client and is not to be photographed, photocopied, or similarly reproduced, in total or in part, without the express written consent of the client and/or PBS Engineering and Environmental Inc.

Prepared by:

PBS Engineering and Environmental Inc.
2517 Eastlake Avenue East Suite 100
Seattle, Washington 98102



TABLE OF CONTENTS

| | |
|---|----------|
| 1 IDENTIFYING INFORMATION..... | 1 |
| 2 LEAD PAINT INSPECTION | 2 |
| 2.1 Site Information..... | 2 |
| 2.2 Lead-Based Paint Inspection and Sampling..... | 2 |
| 2.2.1 XRF Sampling..... | 2 |
| 2.2.2 Bulk Paint-Chip Sampling | 3 |
| 2.3 Components with Lead-Based Paint..... | 3 |
| 2.4 Deteriorated Lead-Based Paint Surfaces..... | 3 |
| 3 LEAD-BASED PAINT RISK ASSESSMENT | 3 |

SUPPORTING DATA

TAB 1: XRF Data Sheets and Lab Reports

TAB 2: Certifications

1 IDENTIFYING INFORMATION

BUILDING DATA

Cascade
29500 106th Ave. SE
Kent, WA 98031

CLIENT DATA

King County Housing Authority
700 Andover Park West, Suite C
Seattle, WA 98188
Attn: Ms. Deborah McCaslin

SCOPE OF ASSESSMENT

PBS Engineering and Environmental, Inc. (PBS) conducted a lead-based paint inspection at the KCHA Cascade property from September 18-22, 2017 in accordance with the U.S. Department Housing and Urban Development (HUD), Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing.

CERTIFICATIONS

Risk Assessor

Janet Murphy
State of Washington
Department of Community, Trade and Economic Development
Risk Assessor Certification No: 0258, Expiration Date: 3/8/2019



Signature

September 27, 2017

Date

Firm

PBS Engineering and Environmental
2517 Eastlake Avenue East
Seattle, Washington 98102
Telephone: 206.223.9639

Certification No: 129143
Expiration Date: 7/31/2018

Laboratory

EMSL Analytical Inc.
3317 3rd Avenue South, Suite D
Seattle, Washington 98134
Telephone: 206.269.6310

Certification No: 167337

2 LEAD PAINT INSPECTION

2.1 Site Information

Cascade Homes consists of 27 buildings with a total of 108 units. The buildings are of wood construction with gypsum interior walls and ceilings. The exterior is cement board siding with wood trim. Apartment units are one, two and three bedrooms with a bathroom and a kitchen/living room area.

Architectural finishes are uniform throughout. The majority of the interior components are painted. Walls are painted gypsum wallboard. Windows in bathrooms have laminate sills. Doors and doors frames are painted wood or metal. The window frames are vinyl.

2.2 Lead-Based Paint Inspection and Sampling

Based on discussions with KCHA staff and a review of King County Assessor records, Cascade Homes was constructed in 1969. All buildings and units were found to have a similar construction and painting history. Based on Table 7.3 in Chapter 7 of the HUD Guidelines, 25 of the 108 units at the site were included in PBS's inspection. PBS selected which of the units to be inspected by assigning each unit a number (1-108) and inputting the numbers into a random number generator until the 25 different units were selected. Additionally, PBS inspected the playground and building exteriors.

2.2.1 XRF Sampling

The presence of lead in paint was determined through x-ray fluorescence spectroscopy. A handheld INNOV-X Systems Inc. X-Ray Fluorescence Analyzer (XRF), Model α -4000 Serial # 6576 operating in lead paint mode was used to perform a surface by surface lead paint inspection of each painted surface in the selected units and other building areas. Calibration was checked based on the requirements of the Performance Characteristic Sheet for the XRF Analyzer. All calibration readings were within the tolerance for this instrument. No substrate correction is required with this instrument.

HUD and the Environmental Protection Agency (EPA) have set 1.0 milligrams per square centimeter (mg/cm^2) as the threshold limit for lead-based paint as determined through X-Ray Fluorescence (XRF) testing. HUD and EPA have set 5,000 parts per million (ppm) or 0.5 percent by atomic absorption spectroscopy (AAS) laboratory analysis as the threshold limit for lead-based paint. Paint that is known to contain lead levels less than those described above does not have to be evaluated, although all deteriorated paint (paint surfaces in poor condition) should be repaired because it may contain lower levels of lead that may contribute to lead dust or lead contaminated soil hazards.

The "Side" information presented on the XRF data sheets is in relation to the side of the rooms, or building exteriors where the street address is located. The inspector/risk assessor used the address side of each residence as the basis to establish side "A". Sides B, C, and D follow in clockwise rotation.

Please refer to the XRF Sample Data Table located in Tab 1 for a complete list of XRF samples.

2.2.2 Bulk Paint-Chip Sampling

Bulk paint chip verification samples were collected when there was an inconclusive result with the XRF.

The following table lists the results of AAS paint chip samples that were collected due to an inconclusive XRF results.

| Sample Number | Building | Location | Lead (%) |
|---------------|------------------------|---|----------|
| Pb1 | Building D Unit 102 | XRF Reading 205 on 9/20/17 White/GWB/Kitchen Wall A | <0.010 |
| Pb2 | Building D Unit 102 | XRF Reading 217 on 9/20/17 White (layer 1) Tan (layer 2)/GWB/Bedroom Ceiling | <0.010 |
| Pb3 | Building D Unit 102 | Reading 219 on 9/20/17 White (layer 1) Tan (layer 2)/GWB/Bedroom Wall B | <0.010 |
| Pb4 | Building D Unit 102 | Reading 222 on 9/20/17 White (layer 1) Tan (layer 2) /GWB/Bedroom Wall D | <0.010 |
| Pb5 | Building D Unit 102 | Reading 227 on 9/20/17 White/GWB/Foyer Wall B | 0.028 |

2.3 Components with Lead-Based Paint

None of the paint tested contained lead above the HUD level of 1.0 mg/cm² by XRF or 0.5% by AAS.

2.4 Deteriorated Lead-Based Paint Surfaces

Lead-based paint was not identified at the subject property. Painted surfaces were evaluated to be in an intact condition.

3 LEAD-BASED PAINT RISK ASSESSMENT

Lead-based paint was not identified at the subject property. As such, a risk assessment was not performed.

TAB 1

XRF Data Sheets and Lab Reports

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|------------|--------------------|-------|-------------------|-------------|-----------|
| 1 | Standardize | --- | --- | --- | --- | --- | Intact |
| 2 | Calibration | Test Paint | --- | Red | Positive | 1.13 | Intact |
| 3 | Calibration | Test Paint | --- | Red | Positive | 1.03 | Intact |
| 4 | Calibration | Test Paint | --- | Red | Positive | 1.03 | Intact |
| Building P - Unit 101 | | | | | | | |
| 5 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 6 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 7 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 8 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 9 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 10 | Living Room A | Metal | Door | White | Negative | 0.00 | Intact |
| 11 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 12 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 13 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 14 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 15 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 16 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 17 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 18 | Kitchen/Dining Room A | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 19 | Kitchen/Dining Room B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 20 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 21 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 22 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 23 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 24 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 25 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 26 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 27 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 28 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 29 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 30 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 31 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 32 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 33 | Bedroom 1 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 34 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 35 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 36 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 37 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 38 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 39 | Bedroom 2 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 40 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 41 | Bedroom 2 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 42 | Bedroom 2 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 43 | Bedroom 2 D | Wood | Door Frame | Brown | Negative | 0.01 | Intact |
| 44 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 45 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 46 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 47 | Bedroom 3 B | Wood | Rolling door | White | Negative | 0.00 | Intact |
| 48 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 49 | Bedroom 3 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 50 | Bedroom 3 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 51 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 52 | Bedroom 3 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 53 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 54 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 55 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 56 | Stairwell D | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 57 | Stairwell B | Wood | Handrail | White | Negative | 0.00 | Intact |
| 58 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 59 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 60 | Exterior A | Cement Board | Square Shingle | Brown | Negative | 0.00 | Intact |
| 61 | Exterior A | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 62 | Exterior B | Cement Board | Corner Trim | White | Negative | 0.00 | Intact |
| 63 | Exterior D | Cement Board | Window Frame | Tan | Negative | 0.00 | Intact |
| 64 | Exterior D | Cement Board | Sliding Door Frame | Tan | Negative | 0.00 | Intact |
| 65 | Exterior D | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 66 | Exterior D | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 67 | Exterior D | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| Building S - Unit 101 | | | | | | | |
| 68 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 69 | Living Room | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 70 | Living Room | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 71 | Living Room | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 72 | Living Room | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 73 | Living Room | Metal | Door | Tan | Negative | 0.00 | Intact |
| 74 | Living Room | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 75 | Kitchen | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 76 | Kitchen A | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|-----------|--------------|-------|-------------------|-------------|-----------|
| 77 | Kitchen B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 78 | Kitchen B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 79 | Kitchen C | Gypsum | Wall | White | Negative | 0.02 | Intact |
| 80 | Kitchen C | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 81 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 82 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 83 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 84 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 85 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 86 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 87 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 88 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 89 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 90 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 91 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 92 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 93 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 94 | Bedroom 1 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 95 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 96 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 97 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 98 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 99 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 100 | Bedroom 2 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 101 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 102 | Bedroom 2 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 103 | Bedroom 2 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 104 | Bedroom 2 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 105 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.01 | Intact |
| 106 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 107 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 108 | Bedroom 3 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 109 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 110 | Bedroom 3 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 111 | Bedroom 3 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 112 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 113 | Bedroom 3 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 114 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 115 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 116 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 117 | Stairwell D | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 118 | Stairwell B | Wood | Handrail | White | Negative | 0.00 | Intact |
| 119 | Exterior A | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 120 | Exterior A | Cement Board | Square Shingle | Gray | Negative | 0.00 | Intact |
| 121 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 122 | Exterior B | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 123 | Exterior B | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| Building S - Unit 103 | | | | | | | |
| 124 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 125 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 126 | Living Room A | Metal | Door | Tan | Negative | 0.00 | Intact |
| 127 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 128 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 129 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 130 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 131 | Living Room D | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 132 | Kitchen | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 133 | Kitchen | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 134 | Kitchen | Gypsum | Wall | White | Negative | 0.04 | Intact |
| 135 | Kitchen | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 136 | Kitchen | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 137 | Kitchen | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 138 | Kitchen | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 139 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 140 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 141 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 142 | Bathroom B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 143 | Bathroom B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 144 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 145 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 146 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 147 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 148 | Bedroom 1 A | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 149 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 150 | Bedroom 1 B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 151 | Bedroom 1 B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 152 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 153 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------|--------------|-------------------|--------|-------------------|-------------------|-----------|
| 154 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 155 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 156 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 157 | Bedroom 2 A | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 158 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 159 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 160 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 161 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 162 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 163 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 164 | Bedroom 3 A | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 165 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 166 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 167 | Bedroom 3 C | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 168 | Bedroom 3 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 169 | Bedroom 3 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 170 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 171 | Stairwell | Wood | Attic Hatch | White | Negative | 0.00 | Intact |
| 172 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 173 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 174 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 175 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 176 | Stairwell C | Wood | Handrail | White | Negative | 0.00 | Intact |
| 177 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 178 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 179 | Exterior A | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 180 | Exterior A | Cement Board | Fish Scale Siding | Gray | Negative | 0.00 | Intact |
| 181 | Exterior A | Metal | Downspout | White | Negative | 0.00 | Intact |
| 182 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 183 | Calibrate | Test Paint | --- | Red | Positive | 1.02 | Intact |
| 184 | Calibrate | Test Paint | --- | Red | Positive | 1.11 | Intact |
| 185 | Calibrate | Test Paint | --- | Red | Positive | 1.00 | Intact |
| Building T - Unit 101 | | | | | | | |
| 187 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 188 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 189 | Living Room B | Gypsum | Wall | Tan | | Insufficient Time | Intact |
| 190 | Living Room B | Metal | Door | Tan | Negative | 0.00 | Intact |
| 191 | Living Room D | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 192 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------------|-----------|----------------------------|-------|-------------------|-------------|-----------|
| 193 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 194 | Living Room D | Gypsum | Wall | White | Negative | 0.05 | Intact |
| 195 | Living Room B | Gypsum | Wall (Reading 189 Re-Test) | White | Negative | 0.00 | Intact |
| 196 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 197 | Kitchen/Dining Room | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 198 | Kitchen/Dining Room | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 199 | Kitchen/Dining Room | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 200 | Kitchen/Dining Room | Gypsum | Window Frame | White | Negative | 0.00 | Intact |
| 201 | Kitchen/Dining Room | Gypsum | Wall | Brown | Negative | 0.00 | Intact |
| 202 | Kitchen/Dining Room | Wood | Cabinet | White | Negative | 0.00 | Intact |
| 203 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 204 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 205 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 206 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 207 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 208 | Bathroom B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 209 | Bathroom B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 210 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 211 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 212 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 213 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 214 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 215 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 216 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 217 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 218 | Bedroom 1 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 219 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 220 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 221 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 222 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 223 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 224 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 225 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 226 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 227 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 228 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 229 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 230 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 231 | Bedroom 3 A | Wood | Window Frame | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 232 | Bedroom 3 C | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 233 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 234 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 235 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 236 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 237 | Exterior B | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 238 | Exterior A | Cement Board | Square Siding | Yellow | Negative | 0.00 | Intact |
| 239 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 240 | Exterior A | Cement Board | Porch Column | White | Negative | 0.01 | Intact |
| Building U - Unit 101 | | | | | | | |
| 241 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 242 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 243 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 244 | Living Room B | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 245 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 246 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 247 | Kitchen | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 248 | Kitchen A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 249 | Kitchen B | Gypsum | Wall | White | Negative | 0.04 | Intact |
| 250 | Kitchen B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 251 | Kitchen A | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 252 | Bathroom | Gypsum | Ceiling | White | Negative | 0.01 | Intact |
| 253 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 254 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 255 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 256 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 257 | Bathroom B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 258 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 259 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 260 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 261 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 262 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 263 | Bedroom 1 A | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 264 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 265 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 266 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 267 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 268 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 269 | Stairwell | Wood | Attic Hatch | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|--------------|---------------|-------|-------------------|-------------|-----------|
| 270 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 271 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 272 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 273 | Stairwell C | Wood | Handrail | White | Negative | 0.00 | Intact |
| 274 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 275 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 276 | Bedroom 3 A | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 277 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 278 | Bedroom 3 B | Wood | Door | Brown | Negative | 0.01 | Intact |
| 279 | Bedroom 3 B | Wood | Door Frame | Brown | Negative | 0.01 | Intact |
| 280 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 281 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 282 | Bedroom 3 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 283 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 284 | Exterior A | Cement Board | Square Siding | Brown | Negative | 0.00 | Intact |
| 285 | Exterior A | Metal | Door | White | Negative | 0.00 | Intact |
| 286 | Exterior A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 287 | Exterior A | Cement Board | Column | White | Negative | 0.01 | Intact |
| 288 | Exterior B | Metal | Downspout | White | Negative | 0.00 | Intact |
| 289 | Exterior B | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 290 | Exterior B | Cement Board | Trim | White | Negative | 0.00 | Intact |
| 291 | Exterior B | Cement Board | Window Frame | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------|------------|--------------------|-------|-------------------|-------------|-----------|
| 1 | Standardize | --- | --- | --- | --- | --- | --- |
| 2 | Calibrate | Test Paint | --- | Red | Positive | 0.98 | Intact |
| 3 | Calibrate | Test Paint | --- | Red | Positive | 1.01 | Intact |
| 4 | Calibrate | Test Paint | --- | Red | Positive | 1.04 | Intact |
| 5 | Calibrate | Test Paint | --- | Red | Positive | 1.10 | Intact |
| Building M - Unit 101 | | | | | | | |
| 6 | Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 7 | Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 8 | Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 9 | Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 10 | Dining Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 11 | Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 12 | Dining Room A | Metal | Door | White | Negative | 0.00 | Intact |
| 13 | Dining Room D | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 14 | Kitchen | Gypsum | Ceiling | White | Negative | 0.04 | Intact |
| 15 | Kitchen A | Gypsum | Wall | White | Negative | 0.03 | Intact |
| 16 | Kitchen B | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 17 | Kitchen B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 18 | Kitchen C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 19 | Kitchen D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 20 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 21 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 22 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 23 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 24 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 25 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 26 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 27 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 28 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 29 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 30 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 31 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 32 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 33 | Bedroom 1 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 34 | Bedroom 1 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 35 | Bedroom 1 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 36 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 37 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 38 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 39 | Bedroom 2 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 40 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 41 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 42 | Bedroom 2 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 43 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 44 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.02 | Intact |
| 45 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 46 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 47 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 48 | Bedroom 3 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 49 | Bedroom 3 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 50 | Bedroom 3 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 51 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 52 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 53 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 54 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 55 | Exterior A | Cement Board | Corner Trim | White | Negative | 0.00 | Intact |
| 56 | Exterior A | Cement Board | Square Siding | Green | Negative | 0.00 | Intact |
| 57 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 58 | Exterior B | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 59 | Exterior B | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 60 | Exterior B | Metal | Downspout | White | Negative | 0.00 | Intact |
| 61 | Exterior B | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| Building Q - Unit 101 | | | | | | | |
| 62 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 63 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.02 | Intact |
| 64 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 65 | Kitchen/Dining Room B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 66 | Kitchen/Dining Room C | Gypsum | Wall | Orange | Negative | 0.00 | Intact |
| 67 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.06 | Intact |
| 68 | Kitchen/Dining Room A | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 69 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 70 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 71 | Living Room A | Metal | Door | White | Negative | 0.00 | Intact |
| 72 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 73 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 74 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 75 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 76 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|-----------|--------------|-------|-------------------|-------------|-----------|
| 77 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 78 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 79 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 80 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 81 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 82 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 83 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 84 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 85 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 86 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 87 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 88 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 89 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 90 | Bedroom 1 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 91 | Bedroom 1 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 92 | Bedroom 1 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 93 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 94 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 95 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 96 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 97 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 98 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 99 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 100 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 101 | Bedroom 2 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 102 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 103 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 104 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 105 | Bedroom 3 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 106 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 107 | Bedroom 3 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 108 | Bedroom 3 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 109 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 110 | Bedroom 3 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 111 | Stairwell B | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 112 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 113 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 114 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 115 | Stairwell B | Wood | Handrail | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 116 | Exterior A | Cement Board | Square Siding | Yellow | Negative | 0.00 | Intact |
| 117 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 118 | Exterior A | Cement Board | Soffit | Brown | Negative | 0.00 | Intact |
| 119 | Exterior A | Metal | Door | Gray | Negative | 0.00 | Intact |
| 120 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |
| 121 | Exterior B | Cement Board | Siding | Brown | Negative | 0.00 | Intact |
| 122 | Exterior B | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 123 | Exterior B | Metal | Downspout | White | Negative | 0.00 | Intact |
| 124 | Exterior D | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 125 | Exterior D | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 126 | Exterior D | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 127 | Exterior D | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 128 | Exterior D | Wood | Fence | Brown | Negative | 0.00 | Intact |
| Building K - Unit 103 | | | | | | | |
| 129 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 130 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 131 | Living Room A | Metal | Door | Tan | Negative | 0.00 | Intact |
| 132 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 133 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 134 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 135 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 136 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 137 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 138 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 139 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.20 | Intact |
| 140 | Kitchen/Dining Room B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 141 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 142 | Kitchen/Dining Room C | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 143 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 144 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 145 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 146 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 147 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 148 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 149 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 150 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 151 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 152 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 153 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 154 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 155 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 156 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 157 | Bedroom 1 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 158 | Bedroom 1 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 159 | Bedroom 1 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 160 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 161 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 162 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 163 | Bedroom 2 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 164 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 165 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 166 | Bedroom 2 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 167 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 168 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 169 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 170 | Bedroom 3 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 171 | Bedroom 3 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 172 | Bedroom 3 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 173 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 174 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 175 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 176 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 177 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 178 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 179 | Stairwell C | Wood | Handrail | White | Negative | 0.00 | Intact |
| 180 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 181 | Exterior A | Cement Board | Square Siding | Brown | Negative | 0.00 | Intact |
| 182 | Exterior A | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 183 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 184 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 185 | Exterior B | Metal | Door | White | Negative | 0.00 | Intact |
| 186 | Exterior B | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 187 | Exterior D | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 188 | Exterior D | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 189 | Exterior D | Cement Board | Corner Trim | White | Negative | 0.00 | Intact |
| 190 | Standardize | --- | --- | --- | --- | --- | --- |
| 191 | Calibration | Test Paint | --- | Red | Positive | 0.81 | Intact |
| 192 | Calibration | Test Paint | --- | Red | Positive | 1.17 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------|------------|--------------------|-------|-------------------|-------------|-----------|
| 193 | Calibration | Test Paint | --- | Red | Positive | 1.09 | Intact |
| 194 | Calibration | Test Paint | --- | Red | Positive | 1.16 | Intact |
| Building J - Unit 104 | | | | | | | |
| 195 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 196 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 197 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 198 | Living Room B | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 199 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 200 | Living Room C | Wood | Door | White | Negative | 0.00 | Intact |
| 201 | Living Room C | Metal | Door Frame | Gray | Negative | 0.00 | Intact |
| 202 | Kitchen | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 203 | Kitchen A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 204 | Kitchen B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 205 | Kitchen C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 206 | Kitchen D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 207 | Kitchen D | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 208 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 209 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 210 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 211 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 212 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 213 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 214 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 215 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 216 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 217 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 218 | Bedroom 1 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 219 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 220 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 221 | Bedroom 1 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 222 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 223 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 224 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 225 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 226 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 227 | Bedroom 2 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 228 | Bedroom 2 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 229 | Bedroom 2 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 230 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 231 | Bedroom 2 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 232 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 233 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 234 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 235 | Hall C | Gypsum | Wall | White | Negative | 0.00 | --- |
| 236 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 237 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 238 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 239 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 240 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 241 | Exterior A | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 242 | Exterior A | Cement Board | Fish Scale Siding | Brown | Negative | 0.00 | Intact |
| 243 | Exterior A | Cement Board | Soffit | Tan | Negative | 0.00 | Intact |
| 244 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 245 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 246 | Exterior C | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 247 | Exterior D | Cement Board | Corner Trim | White | Negative | 0.00 | Intact |
| 248 | Exterior D | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 249 | Exterior D | Cement Board | Fish Scale Siding | Brown | Negative | 0.00 | Intact |
| 250 | Exterior D | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| Building H - Unit 104 | | | | | | | |
| 251 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 252 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 253 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.11 | Intact |
| 254 | Kitchen/Dining Room B | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 255 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 256 | Kitchen/Dining Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 257 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 258 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 259 | Living Room A | Metal | Door | Tan | Negative | 0.00 | Intact |
| 260 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 261 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 262 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 263 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 264 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 265 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 266 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.02 | Intact |
| 267 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 268 | Bedroom 1 A | Wood | Rolling door | Brown | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|-----------|--------------|-------|-------------------|-------------|-----------|
| 269 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 270 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 271 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 272 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 273 | Bedroom 1 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 274 | Bedroom 1 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 275 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 276 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 277 | Bedroom 2 A | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 278 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 279 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 280 | Bedroom 2 W | Wood | Window Frame | White | Negative | 0.00 | |
| 281 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 282 | Bedroom 2 D | Wood | Door | Brown | Negative | 0.01 | Intact |
| 283 | Bedroom 2 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 284 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 285 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 286 | Bedroom 3 A | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 287 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 288 | Bedroom 3 B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 289 | Bedroom 3 B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 290 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 291 | Bedroom 3 C | Wood | Rolling door | Brown | Negative | 0.01 | Intact |
| 292 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 293 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 294 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 295 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 296 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 297 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 298 | Bathroom D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 299 | Bathroom D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 300 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 301 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 302 | Hall B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 303 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 304 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 305 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 306 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 307 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 308 | Exterior A | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 309 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 310 | Exterior A | Metal | Door | Tan | Negative | 0.00 | Intact |
| 311 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |
| 312 | Exterior A | Cement Board | Fish Scale Siding | Gray | Negative | 0.00 | Intact |
| 313 | Exterior C | Cement Board | Soffit | Brown | Negative | 0.00 | Intact |
| 314 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 315 | Exterior C | Cement Board | Trim | White | Negative | 0.00 | Intact |
| 316 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 317 | Exterior C | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 318 | Exterior C | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 319 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|------------------------|------------|--------------------|-------|-------------------|-------------|-----------|
| 1 | Standardize | Test Paint | --- | Red | Positive | 1.12 | Intact |
| 2 | Calibrate | Test Paint | --- | Red | Positive | 1.16 | Intact |
| 3 | Calibrate | Test Paint | --- | Red | Positive | 1.04 | Intact |
| 4 | --- | --- | --- | --- | --- | --- | --- |
| Building G - Unit 101 | | | | | | | |
| 5 | Kitchen/ Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 6 | Kitchen/ Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 7 | Kitchen/ Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 8 | Kitchen/ Dining Room B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 9 | Kitchen/ Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 10 | Kitchen/ Dining Room C | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 11 | Kitchen/ Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 12 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 13 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 14 | Living Room A | Metal | Door | White | Negative | 0.00 | Intact |
| 15 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 16 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 17 | Living Room B | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 18 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 19 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 20 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 21 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 22 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 23 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 24 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 25 | Bathroom A | Wood | Wall | Brown | Negative | 0.00 | Intact |
| 26 | Bathroom A | Wood | Wall Frame | Brown | Negative | 0.00 | Intact |
| 27 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 28 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 29 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 30 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 31 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 32 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 33 | Bedroom 1 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 34 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 35 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 36 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 37 | Bedroom 2 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 38 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 39 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 40 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 41 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 42 | Hall C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 43 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 44 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 45 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 46 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 47 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 48 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 49 | Exterior A | Cement Board | Square Siding | Brown | Negative | 0.00 | Intact |
| 50 | Exterior A | Cement Board | Soffit | Gray | Negative | 0.00 | Intact |
| 51 | Exterior A | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 52 | Exterior A | Cement Board | Corner Trim | White | Negative | 0.00 | Intact |
| 53 | Exterior D | Metal | Gutter | White | Negative | 0.00 | Intact |
| 54 | Exterior D | Metal | Downspout | White | Negative | 0.00 | Intact |
| 55 | Exterior D | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 56 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| Building F - Unit 104 | | | | | | | |
| 57 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 58 | Living Room A | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 59 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 60 | Living Room C | Gypsum | Wall | White | Negative | 0.02 | Intact |
| 61 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 62 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 63 | Living Room A | Metal | Door | White | Negative | 0.00 | Intact |
| 64 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 65 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.07 | Intact |
| 66 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 67 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 68 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.05 | Intact |
| 69 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 70 | Kitchen/Dining Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 71 | Kitchen/Dining Room B | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 72 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 73 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 74 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 75 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 76 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|--------------|---------------|--------|-------------------|-------------|-----------|
| 77 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 78 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 79 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 80 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 81 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 82 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 83 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 84 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 85 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 86 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 87 | Bedroom 1 A | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 88 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 89 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 90 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 91 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 92 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 93 | Bedroom 2 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 94 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 95 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 96 | Bedroom 2 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 97 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.01 | Intact |
| 98 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 99 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 100 | Bedroom 3 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 101 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 102 | Bedroom 3 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 103 | Bedroom 3 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 104 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 105 | Bedroom 3 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 106 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 107 | Hall C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 108 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 109 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 110 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 111 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 112 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 113 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 114 | Exterior A | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 115 | Exterior A | Cement Board | Square Siding | Yellow | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 116 | Exterior A | Metal | Door | Green | Negative | 0.00 | Intact |
| 117 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |
| 118 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 119 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 120 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 121 | Exterior D | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 122 | Exterior D | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| Building E - Unit 104 | | | | | | | |
| 123 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 124 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 125 | Living Room A | Metal | Door | Tan | Negative | 0.00 | Intact |
| 126 | Living Room A | Metal | Door Frame | White | Negative | 0.00 | Intact |
| 127 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 128 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 129 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 130 | Living Room D | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 131 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 132 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 133 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 134 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.06 | Intact |
| 135 | Kitchen/Dining Room D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 136 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 137 | Kitchen/Dining Room C | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 138 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 139 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 140 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 141 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 142 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 143 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 144 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 145 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 146 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 147 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 148 | Bedroom 1 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 149 | Bedroom 1 B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 150 | Bedroom 1 B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 151 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 152 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 153 | Bedroom 1 D | Gypsum | Window Frame | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|--------------|--------------------|------------|-------------------|-------------|-----------|
| 154 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 155 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 156 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 157 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 158 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 159 | Bedroom 2 B | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 160 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 161 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 162 | Bedroom 2 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 163 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 164 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 165 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 166 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 167 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 168 | Bedroom 3 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 169 | Bedroom 3 C | Wood | Door | Brown | Negative | 0.00 | Intact |
| 170 | Bedroom 3 C | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 171 | Bedroom 3 D | Wood | Rolling door | Brown | Negative | 0.00 | Intact |
| 172 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 173 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 174 | Hall C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 175 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 176 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 177 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 178 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 179 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 180 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 181 | Exterior A | Cement Board | Square Siding | Brown | Negative | 0.00 | Intact |
| 182 | Exterior A | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 183 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 184 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 185 | Exterior C | Wood | Sliding Door Frame | Tan | Negative | 0.00 | Intact |
| 186 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 187 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 188 | Exterior C | Cement Board | Siding | Tan | Negative | 0.03 | Intact |
| 189 | Exterior D | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 190 | Exterior D | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 191 | Exterior D | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 192 | Exterior D | Metal | Crawl Space Box | Tan Yellow | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------|------------|--------------------|-------|-------------------|----------------|-----------|
| 193 | Standardize | --- | --- | --- | --- | --- | --- |
| 194 | Calibrate | Test Paint | --- | Red | Positive | 1.04 | Intact |
| 195 | Calibrate | Test Paint | --- | Red | Positive | 1.03 | Intact |
| 196 | Calibrate | Test Paint | --- | Red | Positive | 1.08 | Intact |
| Building D - Unit 102 | | | | | | | |
| 197 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 198 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 199 | Living Room A | Wood | Rolling door | White | Negative | 0.00 | Intact |
| 200 | Living Room B | Gypsum | Wall | White | Negative | 0.06 | Intact |
| 201 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 202 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 203 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 204 | Kitchen | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 205 | Kitchen A | Gypsum | Wall | White | Negative | Inconclusive * | Intact |
| 206 | Kitchen B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 207 | Kitchen C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 208 | Kitchen D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 209 | Kitchen A | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 210 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 211 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 212 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 213 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 214 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 215 | Bathroom D | Wood | Door | White | Negative | 0.00 | Intact |
| 216 | Bathroom D | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 217 | Bedroom | Gypsum | Ceiling | White | Negative | Inconclusive * | Intact |
| 218 | Bedroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 219 | Bedroom B | Gypsum | Wall | White | Negative | Inconclusive * | Intact |
| 220 | Bedroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 221 | Bedroom C | Gypsum | Window Frame | White | Negative | 0.00 | Intact |
| 222 | Bedroom D | Gypsum | Wall | White | Negative | Inconclusive * | Intact |
| 223 | Bedroom A | Wood | Door | White | Negative | 0.00 | Intact |
| 224 | Bedroom A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 225 | Hall/Foyer | Metal | Door | White | Negative | 0.00 | Intact |
| 226 | Hall/Foyer | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 227 | Hall/Foyer | Gypsum | Wall | White | Negative | Inconclusive * | Intact |
| 228 | Hall/Foyer | Gypsum | Wall | White | Negative | 0.03 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|---------------------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| Building C - Unit 104 | | | | | | | |
| 229 | Kitchen | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 230 | Kitchen A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 231 | Kitchen B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 232 | Kitchen C | Gypsum | Cabinet | White | Negative | 0.00 | Intact |
| 233 | Kitchen D | Wood | Covebase | White | Negative | 0.00 | Intact |
| 234 | Kitchen D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 235 | Kitchen D | Gypsum | Wall | White | Negative | 0.00 | --- |
| 236 | Living Room/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 237 | Living Room/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 238 | Living Room/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 239 | Living Room/Dining Room B | Wood | Covebase | White | Negative | 0.00 | Intact |
| 240 | Living Room/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 241 | Living Room/Dining Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 242 | Living Room/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 243 | Bedroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 244 | Bedroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 245 | Bedroom A | Wood | Rolling door | White | Negative | 0.00 | Intact |
| 246 | Bedroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 247 | Bedroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 248 | Bedroom C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 249 | Bedroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 250 | Bedroom D | Wood | Door | White | Negative | 0.00 | Intact |
| 251 | Bedroom D | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 252 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 253 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 254 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 255 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 256 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 257 | Bathroom D | Wood | Door | White | Negative | 0.00 | Intact |
| 258 | Bathroom D | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 259 | Exterior A | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 260 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |
| 261 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 262 | Exterior A | Metal | Door | Green | Negative | 0.00 | Intact |
| 263 | Exterior D | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 264 | Exterior D | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 265 | Exterior D | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 266 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|----------------|----------------------|------------------|------------------|--------------|--------------------------|--------------------|------------------|
| 267 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 268 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 269 | Exterior C | Metal | Corner Trim | White | Negative | 0.00 | Intact |

* Paint Chips Analyzed with AAS

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|----------------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 1 | Standardize | --- | --- | --- | --- | --- | --- |
| 2 | Calibrate | Test Paint | --- | Red | --- | --- | --- |
| 3 | Calibrate | Test Paint | --- | Red | Positive | 1.10 | Intact |
| 4 | Calibrate | Test Paint | --- | Red | Positive | 1.09 | Intact |
| 5 | Calibrate | Test Paint | --- | Red | Positive | 1.08 | Intact |
| Building D - Unit 102 | | | | | | | |
| 6 | Exterior C | Cement Board | Column | White | Negative | 0.00 | Intact |
| 7 | Exterior C | Metal | Soffit | White | Negative | 0.00 | Intact |
| 8 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 9 | Exterior A | Metal | Door | Tan | Negative | 0.00 | Intact |
| 10 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |
| 11 | Exterior A | Metal | Gutter | White | Negative | 0.00 | Intact |
| 12 | Exterior A | Metal | Downspout | White | Negative | 0.00 | Intact |
| 13 | Exterior A | Cement Board | Trim at Roofline | White | Negative | 0.00 | Intact |
| 14 | Exterior A | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| Building B - Unit 102 | | | | | | | |
| 15 | Kitchen/Dinig Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 16 | Kitchen/Dinig Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 17 | Kitchen/Dinig Room B | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 18 | Kitchen/Dinig Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 19 | Kitchen/Dinig Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 20 | Kitchen/Dinig Room D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 21 | Kitchen/Dinig Room B | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 22 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 23 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 24 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 25 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 26 | Living Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 27 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 28 | Living Room D | Metal | Door | Tan | Negative | 0.00 | Intact |
| 29 | Living Room D | Wood | Door Frame | Tan | Negative | 0.00 | Intact |
| 30 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 31 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 32 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 33 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 34 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 35 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 36 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 37 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 38 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 39 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 40 | Bedroom 1 B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 41 | Bedroom 1 B | Wood | Door Frame | Brown | Negative | 0.01 | Intact |
| 42 | Bedroom 1 B | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 43 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 44 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 45 | Bedroom 1 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 46 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 47 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 48 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 49 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 50 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 51 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 52 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 53 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 54 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 55 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 56 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 57 | Hall C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 58 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 59 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 60 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 61 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 62 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 63 | Exterior C | Cement Board | Soffit | Tan | Negative | 0.00 | Intact |
| 64 | Exterior C | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 65 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 66 | Exterior C | Cement Board | Siding | Gray | Negative | 0.00 | Intact |
| 67 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 68 | Exterior A | Cement Board | Square Siding | Brown | Negative | 0.00 | Intact |
| 69 | Exterior A | Cement Board | Soffit | Gray | Negative | 0.00 | Intact |
| 70 | Exterior A | Cement Board | Siding | Tan | Negative | 0.00 | Intact |
| 71 | Exterior A | Metal | Gutter | White | Negative | 0.00 | Intact |
| 72 | Exterior A | Metal | Downspout | White | Negative | 0.00 | Intact |
| Building A - Unit 102 | | | | | | | |
| 73 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.01 | Intact |
| 74 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 75 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|-----------------------|-----------|--------------|-------|-------------------|-------------|-----------|
| 76 | Kitchen/Dining Room B | Metal | Wall Hatch | White | Negative | 0.00 | Intact |
| 77 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 78 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 79 | Kitchen/Dining Room D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 80 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 81 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 82 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 83 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 84 | Living Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 85 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 86 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 87 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.09 | Intact |
| 88 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 89 | Bedroom 1 B | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 90 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.04 | Intact |
| 91 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 92 | Bedroom 1 D | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 93 | Bedroom 1 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 94 | Bedroom 1 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 95 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 96 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 97 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 98 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 99 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 100 | Bedroom 2 B | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 101 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.03 | Intact |
| 102 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 103 | Bedroom 2 D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 104 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 105 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 106 | Bathroom A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 107 | Bathroom A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 108 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 109 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 110 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 111 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 112 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 113 | Hall C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 114 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|-------------------------------|-----------------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 115 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 116 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 117 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 118 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 119 | Exterior C | Cement Board | Soffit | Tan | Negative | 0.00 | Intact |
| 120 | Exterior C | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 121 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 122 | Exterior C | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 123 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.01 | Intact |
| 124 | Exterior A | Cement Board | Square Siding | Brown | Negative | 0.00 | Intact |
| 125 | Exterior A | Cement Board | Soffit | Tan | Negative | 0.00 | Intact |
| 126 | Exterior A | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 127 | Exterior A | Metal | Gutter | White | Negative | 0.00 | Intact |
| 128 | Exterior A | Metal | Downspout | White | Negative | 0.00 | Intact |
| 129 | Exterior A | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| Building BB - Unit 103 | | | | | | | |
| 130 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 131 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 132 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.02 | Intact |
| 133 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 134 | Kitchen/Dining Room D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 135 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 136 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 137 | Living Room A | Metal | Door | Tan | Negative | 0.00 | Intact |
| 138 | Living Room A | Wood | Door Frame | Tan | Negative | 0.00 | Intact |
| 139 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 140 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 141 | Living Room D | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 142 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 143 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 144 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 145 | Bathroom B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 146 | Bathroom B | Wood | Door Frame | Brown | Negative | 0.01 | Intact |
| 147 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 148 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 149 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 150 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 151 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 152 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|-------------------------------|---------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 153 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 154 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 155 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 156 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 157 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 158 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.01 | Intact |
| 159 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 160 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 161 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 162 | Bedroom 2 B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 163 | Bedroom 2 B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 164 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 165 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 166 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 167 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 168 | Hall B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 169 | Hall D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 170 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 171 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 172 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 173 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 174 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 175 | Exterior C | Cement Board | Soffit | Tan | Negative | 0.00 | Intact |
| 176 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 177 | Exterior C | Cement Board | Fish Scale Siding | Gray | Negative | 0.00 | Intact |
| 178 | Exterior C | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 179 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 180 | Exterior A | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 181 | Exterior A | Metal | Gutter | White | Negative | 0.00 | Intact |
| 182 | Exterior A | Metal | Downspout | White | Negative | 0.00 | Intact |
| 183 | Exterior A | Wood | Fence | Brown | Negative | 0.00 | Intact |
| 184 | Standardize | --- | --- | --- | --- | --- | --- |
| 185 | Calibrate | Test Paint | --- | Red | Negative | 1.05 | Intact |
| 186 | Calibrate | Test Paint | --- | Red | Negative | 1.19 | Intact |
| 187 | Calibrate | Test Paint | --- | Red | Negative | 1.09 | Intact |
| Building CC - Unit 103 | | | | | | | |
| 188 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 189 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 190 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|-----------------------|-----------|--------------------|-------|-------------------|-------------|-----------|
| 191 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 192 | Living Room D | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 193 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 194 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 195 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 196 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 197 | Kitchen/Dining Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 198 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 199 | Kitchen/Dining Room D | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 200 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 201 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 202 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 203 | Bathroom B | Wood | Door | Brown | Negative | 0.06 | Intact |
| 204 | Bathroom B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 205 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 206 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 207 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 208 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 209 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 210 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 211 | Bedroom 2 B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 212 | Bedroom 2 B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 213 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 214 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 215 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 216 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 217 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 218 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 219 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 220 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 221 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 222 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 223 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 224 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 225 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 226 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 227 | Hall D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 228 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 229 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|-------------------------------|-----------------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 230 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 231 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 232 | Stairwell C | Wood | Handrail | White | Negative | 0.00 | Intact |
| 233 | Exterior A | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 234 | Exterior A | Cement Board | Fish Scale Siding | Brown | Negative | 0.00 | Intact |
| 235 | Exterior A | Cement Board | Soffit | Green | Negative | 0.00 | --- |
| 236 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 237 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 238 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 239 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 240 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 241 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 242 | Exterior C | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 243 | Exterior A | Metal | Gas Meter Box | Brown | Negative | 0.79 | Intact |
| Building DD - Unit 103 | | | | | | | |
| 244 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 245 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 246 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 247 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 248 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 249 | Living Room D | Wood | Sliding Door | White | Negative | 0.00 | Intact |
| 250 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 251 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 252 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 253 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 254 | Kitchen/Dining Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 255 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 256 | Kitchen/Dining Room D | Wood | Cabinet | Brown | Negative | 0.00 | Intact |
| 257 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 258 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 259 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 260 | Bathroom B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 261 | Bathroom B | Wood | Door Frame | Brown | Negative | 0.01 | Intact |
| 262 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 263 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 264 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 265 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 266 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 267 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|------------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 268 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 269 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 270 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 271 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 272 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 273 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 274 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 275 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 276 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 277 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 278 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 279 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 280 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 281 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 282 | Exterior A | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 283 | Exterior A | Cement Board | Fish Scale Siding | Green | Negative | 0.00 | Intact |
| 284 | Exterior A | Cement Board | Soffit | Yellow | Negative | 0.00 | Intact |
| 285 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 286 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 287 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 288 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 289 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 290 | Exterior C | Cement Board | Sliding Door Frame | Tan | Negative | 0.00 | Intact |
| 291 | Exterior C | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 292 | Exterior A | Metal | Door | Yellow | Negative | 0.28 | Intact |
| 293 | Exterior A | Cement Board | Door Frame | Yellow | Negative | 0.32 | Intact |
| 294 | --- | --- | --- | --- | --- | --- | --- |
| 295 | Calibrate | Test Paint | --- | Red | Negative | 1.14 | Intact |
| 296 | Calibrate | Test Paint | --- | Red | Negative | 1.12 | Intact |
| 297 | Calibrate | Test Paint | --- | Red | Negative | 1.10 | Intact |
| Building Z - Unit 103 | | | | | | | |
| 298 | Kitchen/Dining | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 299 | Kitchen/Dining A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 300 | Kitchen/Dining B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 301 | Kitchen/Dining C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 302 | Kitchen/Dining C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 303 | Kitchen/Dining D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 304 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 305 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|-----------|--------------------|--------|-------------------|-------------|-----------|
| 306 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 307 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 308 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 309 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 310 | Living Room A | Metal | Door | Yellow | Negative | 0.00 | Intact |
| 311 | Living Room A | Wood | Door Frame | Yellow | Negative | 0.00 | Intact |
| 312 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 313 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 314 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 315 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 316 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 317 | Bathroom D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 318 | Bathroom D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 319 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 320 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 321 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 322 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 323 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 324 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 325 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 326 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 327 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 328 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 329 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 330 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 331 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 332 | Bedroom 2 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 333 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 334 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 335 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 336 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 337 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 338 | Hall B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 339 | Hall D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 340 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 341 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 342 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 343 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 344 | Stairwell C | Wood | Handrail | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|----------------|----------------------|------------------|-------------------|--------------|--------------------------|--------------------|------------------|
| 345 | Exterior C | Cement Board | Soffit | Green | Negative | 0.06 | Intact |
| 346 | Exterior C | Cement Board | Roof Trim | White | Negative | 0.06 | Intact |
| 347 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 348 | Exterior C | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 349 | Exterior A | Cement Board | Fish Scale Siding | Brown | Negative | 0.00 | Intact |
| 350 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 351 | Exterior A | Metal | Downspout | White | Negative | 0.00 | Intact |
| 352 | Exterior A | Metal | Door | Green | Negative | 0.00 | Intact |
| 353 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|------------|--------------------|-------|-------------------|-------------------|-----------|
| 1 | Standardize | --- | --- | --- | --- | --- | --- |
| 2 | Calibrate | Test Paint | --- | Red | Positive | Insufficient Time | Intact |
| 3 | Calibrate | Test Paint | --- | Red | Positive | 1.14 | Intact |
| 4 | Calibrate | Test Paint | --- | Red | Positive | 1.13 | Intact |
| 5 | Calibrate | Test Paint | --- | Red | Positive | 1.04 | Intact |
| Building V - Unit 102 | | | | | | | |
| 6 | Living Room | Gypsum | Ceiling | White | Negative | 0.02 | Intact |
| 7 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 8 | Living Room B | Gypsum | Wall | White | Negative | 0.02 | Intact |
| 9 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 10 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 11 | Living Room D | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 12 | Living Room A | Metal | Door | White | Negative | 0.00 | Intact |
| 13 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 14 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 15 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 16 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 17 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 18 | Kitchen/Dining Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 19 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 20 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 21 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 22 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 23 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 24 | Bathroom D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 25 | Bathroom D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 26 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 27 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 28 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 29 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 30 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 31 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 32 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 33 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 34 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 35 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.06 | Intact |
| 36 | Bedroom 2 A | Gypsum | Wall | Brown | Negative | 0.00 | Intact |
| 37 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 38 | Bedroom 2 A | Wood | Door | Brown | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 39 | Bedroom 2 B | Wood | Wall | Brown | Negative | 0.00 | Intact |
| 40 | Bedroom 2 C | Gypsum | Wall | Brown | Negative | 0.00 | Intact |
| 41 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 42 | Bedroom 2 D | Gypsum | Wall | Brown | Negative | 0.00 | Intact |
| 43 | Bedroom 3 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 44 | Bedroom 3 A | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 45 | Bedroom 3 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 46 | Bedroom 3 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 47 | Bedroom 3 B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 48 | Bedroom 3 B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 49 | Bedroom 3 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 50 | Bedroom 3 C | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 51 | Bedroom 3 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 52 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 53 | Hall B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 54 | Hall D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 55 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 56 | Stairwell D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 57 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 58 | Stairwell B | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 59 | Stairwell D | Wood | Handrail | White | Negative | 0.00 | Intact |
| 60 | Exterior A | Metal | Door | Yellow | Negative | 0.00 | Intact |
| 61 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |
| 62 | Exterior A | Cement Board | Square Siding | Green | Negative | 0.00 | Intact |
| 63 | Exterior A | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 64 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 65 | Exterior A | Cement Board | Soffit | White | Negative | 0.00 | Intact |
| 66 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 67 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 68 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 69 | Exterior C | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 70 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| Building W - Unit 102 | | | | | | | |
| 71 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 72 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.02 | Intact |
| 73 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 74 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 75 | Kitchen/Dining Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 76 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|-----------|--------------------|-------|-------------------|-------------|-----------|
| 77 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 78 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 79 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 80 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 81 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 82 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 83 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 84 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 85 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 86 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 87 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 88 | Bathroom D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 89 | Bathroom D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 90 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 91 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 92 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 93 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 94 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 95 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 96 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 97 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 98 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 99 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 100 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 101 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 102 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 103 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 104 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 105 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 106 | Bedroom 2 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 107 | Bedroom 2 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 108 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 109 | Hall B | Gypsum | Wall | Brown | Negative | 0.00 | Intact |
| 110 | Hall D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 111 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 112 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 113 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 114 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 115 | Stairwell C | Wood | Handrail | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|-------|-------------------|-------------|-----------|
| 116 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 117 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 118 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 119 | Exterior C | Cement Board | Soffit | Gray | Negative | 0.00 | Intact |
| 120 | Exterior A | Cement Board | Siding | Green | Negative | 0.00 | Intact |
| 121 | Exterior A | Cement Board | Fish Scale Siding | Brown | Negative | 0.00 | Intact |
| 122 | Exterior A | Metal | Door | Green | Negative | 0.00 | Intact |
| 123 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |
| 124 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 125 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| Building X - Unit 103 | | | | | | | |
| 126 | Kitchen/Dining Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 127 | Kitchen/Dining Room A | Gypsum | Wall | White | Negative | 0.02 | Intact |
| 128 | Kitchen/Dining Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 129 | Kitchen/Dining Room C | Gypsum | Wall | White | Negative | 0.06 | Intact |
| 130 | Kitchen/Dining Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 131 | Kitchen/Dining Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 132 | Living Room | Gypsum | Ceiling | White | Negative | 0.02 | Intact |
| 133 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 134 | Living Room B | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 135 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 136 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.01 | Intact |
| 137 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 138 | Living Room A | Metal | Door | White | Negative | 0.00 | Intact |
| 139 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 140 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 141 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 142 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 143 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 144 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 145 | Bathroom B | Wood | Door | Brown | Negative | 0.00 | Intact |
| 146 | Bathroom B | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 147 | Bedroom 1 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 148 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 149 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 150 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 151 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 152 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 153 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|------------------------------|-----------------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 154 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 155 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 156 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 157 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 158 | Bedroom 2 A | Gypsum | Rolling Door | White | Negative | 0.00 | Intact |
| 159 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 160 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 161 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 162 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 163 | Bedroom 2 D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 164 | Bedroom 2 D | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 165 | Hall B | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 166 | Hall D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 167 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 168 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 169 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 170 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 171 | Stairwell C | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 172 | Exterior A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 173 | Exterior A | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 174 | Exterior A | Cement Board | Fish Scale Siding | Green | Negative | 0.00 | Intact |
| 175 | Exterior A | Metal | Door | Green | Negative | 0.00 | Intact |
| 176 | Exterior A | Cement Board | Door Frame | White | Negative | 0.01 | Intact |
| 177 | Exterior A | Cement Board | Soffit | Green | Negative | 0.00 | Intact |
| 178 | Exterior A | Cement Board | Window Frame | White | Negative | 0.00 | Intact |
| 179 | Exterior C | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 180 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 181 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 182 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| Building Y - Unit 102 | | | | | | | |
| 183 | Kitchen/Dinign Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 184 | Kitchen/Dinign Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 185 | Kitchen/Dinign Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 186 | Kitchen/Dinign Room C | Gypsum | Wall | White | Negative | 0.01 | Intact |
| 187 | Kitchen/Dinign Room C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 188 | Kitchen/Dinign Room D | Gypsum | Wall | White | Negative | 0.04 | Intact |
| 189 | Living Room | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 190 | Living Room A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 191 | Living Room A | Metal | Door | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|---------|---------------|--------------|--------------------|--------|-------------------|-------------|-----------|
| 192 | Living Room A | Wood | Door Frame | White | Negative | 0.00 | Intact |
| 193 | Living Room B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 194 | Living Room C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 195 | Living Room C | Wood | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 196 | Living Room D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 197 | Bathroom | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 198 | Bathroom A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 199 | Bathroom B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 200 | Bathroom C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 201 | Bathroom D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 202 | Bathroom D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 203 | Bathroom D | Wood | Door | Brown | Negative | 0.00 | Intact |
| 204 | Bedroom 1 A | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 205 | Bedroom 1 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 206 | Bedroom 1 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 207 | Bedroom 1 A | Wood | Door | Brown | Negative | 0.00 | Intact |
| 208 | Bedroom 1 A | Wood | Door Frame | Brown | Negative | 0.00 | Intact |
| 209 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 210 | Bedroom 1 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 211 | Bedroom 1 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 212 | Bedroom 1 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 213 | Bedroom 1 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 214 | Bedroom 2 | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 215 | Bedroom 2 A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 216 | Bedroom 2 A | Wood | Rolling Door | Brown | Negative | 0.00 | Intact |
| 217 | Bedroom 2 B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 218 | Bedroom 2 C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 219 | Bedroom 2 C | Wood | Window Frame | White | Negative | 0.00 | Intact |
| 220 | Bedroom 2 D | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 221 | Hall | Gypsum | Ceiling | White | Negative | 0.00 | Intact |
| 222 | Hall A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 223 | Hall C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 224 | Stairwell A | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 225 | Stairwell B | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 226 | Stairwell C | Gypsum | Wall | White | Negative | 0.00 | Intact |
| 227 | Stairwell A | Wood | Handrail | Brown | Negative | 0.00 | Intact |
| 228 | Stairwell C | Wood | Handrail | White | Negative | 0.00 | Intact |
| 229 | Exterior A | Metal | Door | Yellow | Negative | 0.00 | Intact |
| 230 | Exterior A | Cement Board | Door Frame | White | Negative | 0.00 | Intact |

| Reading | Test Location | Substrate | Component | Color | Positive/Negative | XRF Reading | Condition |
|-----------------------------------|------------------|--------------|---------------------------------|--------|-------------------|-------------------|-----------|
| 231 | Exterior A | Cement Board | Fish Scale Siding | Green | Negative | 0.00 | Intact |
| 232 | Exterior A | Cement Board | Porch Column | White | Negative | 0.00 | Intact |
| 233 | Exterior A | Cement Board | Soffit | Yellow | Negative | Insufficient Time | Intact |
| 234 | Exterior A | Cement Board | Soffit (Re-test of Reading 233) | Yellow | Negative | 0.00 | Intact |
| 235 | Exterior A | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| 236 | Exterior C | Cement Board | Siding | Yellow | Negative | 0.00 | Intact |
| 237 | Exterior C | Cement Board | Sliding Door Frame | White | Negative | 0.00 | Intact |
| 238 | Exterior C | Metal | Gutter | White | Negative | 0.00 | Intact |
| 239 | Exterior C | Metal | Downspout | White | Negative | 0.00 | Intact |
| 240 | Exterior C | Cement Board | Skirt | White | Negative | 0.00 | Intact |
| North Playground Equipment | | | | | | | |
| 241 | North Playground | Metal | Column | White | Negative | 0.00 | Intact |
| 242 | North Playground | Metal | Balance Beam | Red | Negative | 0.00 | Intact |
| 243 | North Playground | Metal | Deck | Brown | Negative | 0.05 | Intact |
| 244 | North Playground | Metal | Zip Track | Red | Negative | 0.00 | Intact |
| 245 | North Playground | Wood | Bench | Brown | Negative | 0.00 | Intact |
| South Playground Equipment | | | | | | | |
| 246 | South Playground | Wood | Bench | Brown | Negative | 0.00 | Intact |
| 247 | South Playground | Metal | Column | White | Negative | 0.00 | Intact |
| 248 | South Playground | Metal | Deck | Brown | Negative | 0.05 | Intact |
| 249 | South Playground | Metal | Leaf Step | Red | Negative | 0.00 | Intact |
| 250 | South Playground | Metal | Pole | Red | Negative | 0.00 | Intact |

**EMSL Analytical, Inc.**

3317 3rd Ave S, Suite D 2nd floor, Seattle, WA 98134

Phone/Fax: 2062696310 / (206) 900-8789

<http://www.emsl.com>seattlelab@emsl.com

EMSL Order: 511702540

CustomerID: PBSE51

CustomerPO:

ProjectID:

Attn: **Mark Hiley**
PBS Engineering & Environmental, Inc.
2517 Eastlake Ave. East Ste. 100
Seattle, WA 98102

Phone: (206) 233-9639
 Fax: (206) 762-4780
 Received: 09/20/17 3:56 PM
 Collected:

Project: **Project #40573.140, Cascade Homes****Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)***

| <i>Client SampleDescription</i> | <i>Collected</i> | <i>Analyzed</i> | <i>RDL</i> | <i>Lead Concentration</i> |
|---------------------------------|------------------|--|------------|---------------------------|
| Pb1 511702540-0001 | | 9/21/2017 Site: White/Kitchen/A. Wall--9/20/17, Reading 205/ Unit D102 | 0.010 % wt | <0.010 % wt |
| Pb2 511702540-0002 | | 9/21/2017 Site: 1 White, 2 Tan/Bedroom/Ceiling--9/20/17, Reading 217/ Unit D102 | 0.010 % wt | <0.010 % wt |
| Pb3 511702540-0003 | | 9/21/2017 Site: 1 White, 2 Tan/Bedroom/B. Wall--9/20/17, Reading 219/ Unit D102 | 0.010 % wt | <0.010 % wt |
| Pb4 511702540-0004 | | 9/21/2017 Site: 1 White, 2 Tan/Bedroom/D. Wall--9/20/17, Reading 222/ Unit D102 | 0.010 % wt | <0.010 % wt |
| Pb5 511702540-0005 | | 9/21/2017 Site: White/Hall Foyer/B. Wall--9/20/17, Reading 227/ Unit D102 | 0.010 % wt | 0.028 % wt |

Lauren Kerber, Laboratory Manager
 or other approved signatory

*Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.010 % wt based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Seattle, WA

Initial report from 09/21/2017 15:45:33

TAB 2
Certifications

STATE OF WASHINGTON

Department of Commerce

Lead-Based Paint Abatement Firm

PBS Engineering & Environmental Inc.

*Has fulfilled the certification requirements of
WAC 365-230
and has been certified to conduct lead-based
paint activities.*

Certification #

178

Issuance Date

05/24/2017

Expiration Date

09/03/2019



STATE OF WASHINGTON

Department of Commerce Lead-Based Paint Program

Janet J. Murphy

Has fulfilled the certification requirements of Washington Administrative code (WAC) 365-230 and has been certified to conduct lead-based paint activities pursuant to WAC 365-230-200 as a:

Risk Assessor

Certification #

0258

Issuance Date

3/23/2016

Expiration Date

3/8/2019



AIHA Laboratory Accreditation Programs, LLC

acknowledges that

EMSL Analytical, Inc.

3317 3rd Avenue S, Suite D, Seattle, WA 98134

Laboratory ID: 167337

along with all premises from which key activities are performed, as listed above, has fulfilled the requirements of the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC accreditation to the ISO/IEC 17025:2005 international standard, *General Requirements for the Competence of Testing and Calibration Laboratories* in the following:

LABORATORY ACCREDITATION PROGRAMS

- INDUSTRIAL HYGIENE
- ENVIRONMENTAL LEAD
- ENVIRONMENTAL MICROBIOLOGY
- FOOD
- UNIQUE SCOPES

- Accreditation Expires: June 01, 2019
- Accreditation Expires: December 01, 2018
- Accreditation Expires:
- Accreditation Expires:

Specific Field(s) of Testing (FoT)/Method(s) within each Accreditation Program for which the above named laboratory maintains accreditation is outlined on the attached **Scope of Accreditation**. Continued accreditation is contingent upon successful on-going compliance with ISO/IEC 17025:2005 and AIHA-LAP, LLC requirements. This certificate is not valid without the attached **Scope of Accreditation**. Please review the AIHA-LAP, LLC website (www.aihaaccreditedlabs.org) for the most current Scope.

William Walsh, CIH
Chairperson, Analytical Accreditation Board

Revision 15: 03/30/2016

Cheryl O. Morton
Managing Director, AIHA Laboratory Accreditation Programs, LLC

Date Issued: 05/31/2017



AIHA Laboratory Accreditation Programs, LLC SCOPE OF ACCREDITATION

EMSL Analytical, Inc.

3317 3rd Avenue S, Suite D, Seattle, WA 98134

Laboratory ID: **167337**

Issue Date: 05/31/2017

The laboratory is approved for those specific field(s) of testing/methods listed in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(s) of testing/Methods, since these can change due to proficiency status, suspension and/or withdrawal of accreditation.

The EPA recognizes the AIHA-LAP, LLC ELLAP program as meeting the requirements of the National Lead Laboratory Accreditation Program (NLLAP) established under Title X of the Residential Lead-Based Paint Hazard Reduction Act of 1992 and includes paint, soil and dust wipe analysis. Air and composited wipes analyses are not included as part of the NLLAP.

Environmental Lead Laboratory Accreditation Program (ELLAP)

Initial Accreditation Date: 06/01/2017

| Field of Testing (FoT) | Technology sub-type/ Detector | Method | Method Description <i>(for internal methods only)</i> |
|-----------------------------|----------------------------------|------------------|--|
| Paint | | EPA SW-846 3050B | |
| | | EPA SW-846 3051A | |
| | | EPA SW-846 7000B | |
| Soil | | EPA SW-846 3050B | |
| | | EPA SW-846 3051A | |
| | | EPA SW-846 7000B | |
| Settled Dust by Wipe | | EPA SW-846 3050B | |
| | | EPA SW-846 3051A | |
| | | EPA SW-846 7000B | |
| Airborne Dust | | NIOSH 7082 | |

A complete listing of currently accredited Environmental Lead laboratories is available on the AIHA-LAP, LLC website at: <http://www.aihaaccreditedlabs.org>