Lead-Based Paint Inspection Report

Valli Kee
23401 104th Avenue SE
Kent, Washington

Prepared for:
Deborah McCaslin
King County Housing
700 Andover Park West, Suite C
Seattle, Washington 98188

February 22, 2018
PBS Project No. 40573.154

PBS
2517 EASTLAKE AVENUE EAST
SUITE 100
SEATTLE, WA 98102
206.233.9639 MAIN
866.727.0140 FAX
PBSUSA.COM

LEAD-BASED PAINT INSPECTION REPORT
Valli Kee
23401 104th Avenue SE
Kent, WA 98031

For

King County Housing Authority
700 Andover Park West, Suite C
Seattle, Washington 98188

This report is for the exclusive use of the client and is not to be photographed, photocopied, or similarly reproduced, in total or in part, without the express written consent of the client and/or PBS Engineering and Environmental Inc.

Prepared by:

PBS Engineering and Environmental Inc.
2517 Eastlake Avenue East Suite 100
Seattle, Washington 98102

© 2017 PBS Engineering and Environmental Inc.

TABLE OF CONTENTS

1 IDENTIFYING INFORMATION 1

2 LEAD-BASED PAINT INSPECTION 2

2.1 Site Information 2

2.2 Lead-Based Paint Inspection and Sampling 2

2.2.1 XRF Sampling 2

2.2.2 Bulk Paint-Chip Sampling 3

2.3 Components with Lead-Based Paint 3

2.4 Deteriorated Lead-Based Paint Surfaces 3

SUPPORTING DATA

TAB 1: XRF Data Sheets

TAB 2: Certifications

1 IDENTIFYING INFORMATION

BUILDING DATA
Valli Kee
23401 104th Avenue SE
Kent, WA 98031

CLIENT DATA
King County Housing Authority
700 Andover Park West, Suite C
Seattle, WA 98188
Attn: Ms. Deborah McCaslin

SCOPE OF ASSESSMENT
PBS Engineering and Environmental, Inc. (PBS) conducted a lead-based paint inspection at Valli Kee on January 22 - 25, 2018, in accordance with the U.S. Department Housing and Urban Development (HUD), Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing.

CERTIFICATIONS

Risk Assessor
Janet Murphy
State of Washington
Department of Community, Trade and Economic Development
Risk Assessor Certification No: 0258, Expiration Date: 3/8/2019

Janet Murphy

Signature

February 22, 2018
Date

Firm
PBS Engineering and Environmental
2517 Eastlake Avenue East
Seattle, Washington 98102
Telephone: 206.223.9639

Certification No: 129143
Expiration Date: 7/31/2018

2 LEAD-BASED PAINT INSPECTION

2.1 Site Information

Valli Kee consists of 32 residential buildings with 115 units and separate buildings for the maintenance shop, management offices, laundry and community services. The buildings are of wood construction with gypsum interior walls and ceilings. The exterior is cement board siding and trim. Residential units are one, two, three and four bedrooms with a bathroom, kitchen/dining room and living room area. The buildings are in good condition.

Architectural finishes are uniform throughout. The majority of the interior components are painted. Walls are painted gypsum wallboard. Doors are painted wood or metal. Door and window trim are painted medium density fiberboard (MDF) or cement board. The exterior window frames are vinyl with cement board trim.

2.2 Lead-Based Paint Inspection and Sampling

Based on information provided by KCHA, Valli Kee was constructed in 1968. All exterior wood siding was replaced in 2014 and replaced with painted cement board. The Community Services Building (Building 26) was built in 2012 and the Management Office Building (Building 26A) were substantially renovated in 2014. All residential buildings and units were found to have a similar construction and painting history. Based on Table 7.3 in Chapter 7 of the HUD Guidelines, 26 units at the site were included in PBS's inspection. Additionally, PBS inspected the Management Office Building, common laundry (Building 16) and the playground.

2.2.1 XRF Sampling

The presence of lead in paint was determined through x-ray fluorescence spectroscopy. A handheld Niton X-Ray Fluorescence Analyzer (XRF), Model XLP-300A Serial # 102877 operating in lead paint mode was used to perform a surface by surface lead paint inspection of each painted surface in the selected units and other building areas. Calibration was checked based on the requirements of the Performance Characteristic Sheet for the XRF Analyzer. All calibration readings were within the tolerance for this instrument.

HUD and the Environmental Protection Agency (EPA) have set 1.0 milligrams per square centimeter (mg/cm^2) as the threshold limit for lead-based paint as determined through X-Ray Fluorescence (XRF) testing. HUD and EPA have set 5,000 parts per million (ppm) or 0.5 percent by atomic absorption spectroscopy (AAS) laboratory analysis as the threshold limit for lead-based paint. Paint that is known to contain lead levels less than those described above does not have to be evaluated, although all deteriorated paint (paint surfaces in poor condition) should be repaired because it may contain lower levels of lead that may contribute to lead dust or lead contaminated soil hazards.

The "Side" information presented on the XRF data sheets is in relation to the side of the rooms or building exteriors where the unit address is located. The inspector/risk assessor used the address side of each residence as the basis to establish side "A". Sides B, C, and D follow in clockwise rotation.

Please refer to the XRF Sample Data Table located in Tab 1 for a complete list of XRF samples.

2.2.2 Bulk Paint-Chip Sampling

Bulk paint chip verification samples were collected when there was an inconclusive result with the XRF. Inconclusive results were not recorded during the Valli Kee inspection.

2.3 Components with Lead-Based Paint

None of the paint tested contained lead above the HUD level of 1.0 mg/cm^2 by XRF.

2.4 Deteriorated Lead-Based Paint Surfaces

Lead-based paint was not identified at the subject property. Painted surfaces were evaluated to be in an intact condition.

TAB 1

XRF Data Sheets

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1	SHUTTER CAL										6.23
2	NIST Standard				RED	VALLI KEE				Positive	1
3	NIST STANDARD	PAINT			RED	VALLI KEE				Positive	1
4	NIST STANDARD	PAINT			RED	VALLI KEE				Positive	1
5	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BLDG 1 UNIT 4	Negative	< LOD
6	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BLDG 1 UNIT 4	Negative	< LOD
7	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BLDG 1 UNIT 4	Negative	< LOD
8	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BLDG 1 UNIT 4	Negative	< LOD
9	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BLDG 1 UNIT 4	Negative	< LOD
10	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BLDG 1 UNIT 4	Negative	< LOD
11	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BLDG 1 UNIT 4	Negative	< LOD
12	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
13	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
14	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
15	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
16	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
17	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
18	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
19	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 1 UNIT 4	Negative	< LOD
20	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 1 UNIT 4	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
21	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 1 UNIT 4	Negative	< LOD
22	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 1 UNIT 4	Negative	< LOD
23	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 1 UNIT 4	Negative	< LOD
24	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 1 UNIT 4	Negative	< LOD
25	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 1 UNIT 4	Negative	< LOD
26	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 1 UNIT 4	Negative	< LOD
27	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
28	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
29	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
30	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
31	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
32	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
33	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
34	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
35	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 1 UNIT 4	Negative	< LOD
36	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD
37	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD
38	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD
39	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Null	< LOD
40	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
41	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD
42	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD
43	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD
44	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 1 UNIT 4	Negative	< LOD
45	SIDING	CEMENT BOARD	A	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
46	SOFFIT	CEMENT BOARD	A	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
47	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
48	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
49	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
50	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
51	SIDING	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
52	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
53	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
54	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
55	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BLDG 1 UNIT 4	Negative	< LOD
56	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	kitchen	BLDG 2 UNIT 8	Negative	< LOD
57	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	kitchen	BLDG 2 UNIT 8	Negative	< LOD
58	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	kitchen	BLDG 2 UNIT 8	Negative	< LOD
59	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	kitchen	BLDG 2 UNIT 8	Negative	< LOD
60	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	kitchen	BLDG 2 UNIT 8	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
61	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	kitchen	BLDG 2 UNIT 8	Negative	< LOD
62	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	kitchen	BLDG 2 UNIT 8	Negative	< LOD
63	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
64	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
65	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
66	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
67	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
68	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
69	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
70	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BLDG 2 UNIT 8	Negative	< LOD
71	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 2 UNIT 8	Negative	< LOD
72	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 2 UNIT 8	Negative	< LOD
73	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 2 UNIT 8	Negative	< LOD
74	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 2 UNIT 8	Negative	< LOD
75	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 2 UNIT 8	Negative	< LOD
76	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 2 UNIT 8	Negative	< LOD
77	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BLDG 2 UNIT 8	Negative	< LOD
78	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
79	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
80	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
81	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
82	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
83	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
84	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
85	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
86	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
87	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BLDG 2 UNIT 8	Negative	< LOD
88	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
89	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
90	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
91	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
92	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
93	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
94	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
95	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BLDG 2 UNIT 8	Negative	< LOD
96	SIDING	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD
97	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD
98	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD
99	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD
100	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
101	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD
102	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD
103	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BLDG 2 UNIT 8	Negative	< LOD
104	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 4 UNIT 14	Negative	< LOD
105	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 4 UNIT 14	Negative	< LOD
106	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 4 UNIT 14	Negative	< LOD
107	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 4 UNIT 14	Negative	< LOD
108	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 4 UNIT 14	Negative	< LOD
109	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 4 UNIT 14	Negative	< LOD
110	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 4 UNIT 14	Negative	< LOD
111	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 4 UNIT 14	Negative	< LOD
112	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 4 UNIT 14	Negative	< LOD
113	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 4 UNIT 14	Null	< LOD
114	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 4 UNIT 14	Negative	< LOD
115	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 4 UNIT 14	Negative	< LOD
116	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 4 UNIT 14	Negative	< LOD
117	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
118	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
119	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
120	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
121	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
122	WALL	DRYWALL	D	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
123	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
124	DOOR FRAME	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
125	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 4 UNIT 14	Negative	< LOD
126	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 4 UNIT 14	Negative	< LOD
127	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 4 UNIT 14	Negative	< LOD
128	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 4 UNIT 14	Negative	< LOD
129	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 4 UNIT 14	Negative	< LOD
130	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 4 UNIT 14	Negative	< LOD
131											6.64
132										Negative	< LOD
133	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 4 UNINT 14	Negative	< LOD
134	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 4 UNINT 14	Negative	< LOD
135	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
136	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
137	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
138	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
139	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
140	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
141	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
142	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
143	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 4 UNINT 14	Negative	< LOD
144	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
145	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
146	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
147	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
148	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
149	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
150	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
151	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
152	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 4 UNINT 14	Negative	< LOD
153	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
154	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
155	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
156	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
157	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
158	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
159	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
160	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
161	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
162	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 4 UNINT 14	Negative	< LOD
163	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
164	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
165	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
166	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
167	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
168	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
169	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
170	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
171	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
172	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
173	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
174	WINDOW FRAME	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
175	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
176	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNINT 14	Negative	< LOD
177	CEILING	DRYWALL		INTACT	BEIGE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD
178	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD
179	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD
180	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
181	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD
182	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD
183											5.97
184										Negative	< LOD
185	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD
186	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 3 UNIT 12	Negative	< LOD
187	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 3 UNIT 12	Negative	< LOD
188	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 3 UNIT 12	Negative	< LOD
189	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 3 UNIT 12	Negative	< LOD
190	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 3 UNIT 12	Negative	< LOD
191	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY ROOM	BUILDING 3 UNIT 12	Negative	< LOD
192	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
193	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
194	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
195	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
196	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
197	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
198	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
199	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD
200	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 3 UNIT 12	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
201	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
202	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
203	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
204	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
205	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
206	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
207	ROLL DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
208	ROLL DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 3 UNIT 12	Negative	< LOD
209	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
210	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
211	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
212	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
213	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
214	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
215	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
216	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
217	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 3 UNIT 12	Negative	< LOD
218	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
219	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
220	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
221	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
222	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
223	WINDOW SIll	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
224	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
225	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
226	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 3 UNIT 12	Negative	< LOD
227	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
228	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
229	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
230	SIDING	CEMENT BOARD	A	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
231	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
232	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
233	SIDING	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
234	WINDOW FRAME	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
235	WINDOW FRAME	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
236	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
237	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
238	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
239	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 31 UNIT 308	Negative	< LOD
240	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 31 UNIT 308	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
241	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 31 UNIT 308	Negative	< LOD
242	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 31 UNIT 308	Negative	< LOD
243	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 31 UNIT 308	Negative	< LOD
244	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 31 UNIT 308	Negative	< LOD
245	DOOR FRAME	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 31 UNIT 308	Negative	< LOD
246	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 31 UNIT 308	Negative	< LOD
247	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 31 UNIT 308	Negative	< LOD
248	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 31 UNIT 308	Negative	< LOD
249	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 31 UNIT 308	Negative	< LOD
250	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 31 UNIT 308	Negative	< LOD
251	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 31 UNIT 308	Negative	< LOD
252	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
253	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
254	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
255	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
256	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
257	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
258	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
259	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD
260	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 31 UNIT 308	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
261	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 31 UNIT 308	Negative	< LOD
262	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 31 UNIT 308	Negative	< LOD
263	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 31 UNIT 308	Negative	< LOD
264	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 31 UNIT 308	Negative	< LOD
265	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 31 UNIT 308	Negative	< LOD
266	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 31 UNIT 308	Null	< LOD
267	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 31 UNIT 308	Negative	< LOD
268	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
269	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
270	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
271	SIDING	CEMENT BOARD	B	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
272	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
273	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
274	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
275	SIDING	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
276	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
277	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
278	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
279	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
280	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 32 UNIT 312	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
281	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 32 UNIT 312	Negative	< LOD
282	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 32 UNIT 312	Negative	< LOD
283	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 32 UNIT 312	Negative	< LOD
284	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 32 UNIT 312	Negative	< LOD
285	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 32 UNIT 312	Negative	< LOD
286	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 32 UNIT 312	Negative	< LOD
287	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 32 UNIT 312	Negative	< LOD
288	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 32 UNIT 312	Negative	< LOD
289	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 32 UNIT 312	Negative	< LOD
290	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 32 UNIT 312	Negative	< LOD
291	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 32 UNIT 312	Negative	< LOD
292	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 32 UNIT 312	Negative	< LOD
293	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
294	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
295	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
296	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
297	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
298	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
299	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
300	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
301	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
302	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 32 UNIT 312	Negative	< LOD
303	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 32 UNIT 312	Negative	< LOD
304	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 32 UNIT 312	Negative	< LOD
305	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 32 UNIT 312	Negative	< LOD
306	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 32 UNIT 312	Negative	< LOD
307	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 32 UNIT 312	Negative	< LOD
308											6.62
309	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
310	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
311	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
312	WINDOW FRAME	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
313	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
314	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
315	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
316	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
317	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
318	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
319	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 33 UNIT 305	Negative	< LOD
320	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 33 UNIT 305	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
321	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 33 UNIT 305	Negative	< LOD
322	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 33 UNIT 305	Negative	< LOD
323	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 33 UNIT 305	Negative	< LOD
324	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 33 UNIT 305	Negative	< LOD
325	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 33 UNIT 305	Negative	< LOD
326	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
327	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
328	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
329	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
330	WALL	DRYWALL	D	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
331	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
332	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
333	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
334	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
335	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 33 UNIT 305	Negative	< LOD
336	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
337	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
338	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
339	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
340	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
341	ROLL DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
342	ROLL DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
343	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
344	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 1	BUILDING 33 UNIT 305	Negative	< LOD
345	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
346	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
347	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
348	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
349	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
350	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
351	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
352	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
353	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	SECOND	BEDROOM 2	BUILDING 33 UNIT 305	Negative	< LOD
354	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	SECOND	STAIR	BUILDING 33 UNIT 305	Negative	< LOD
355	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	SECOND	STAIR	BUILDING 33 UNIT 305	Negative	< LOD
356	HAND RAIL	WOOD	C	INTACT	WHITE	VALLI KEE	SECOND	STAIR	BUILDING 33 UNIT 305	Negative	< LOD
357	RISER	WOOD	C	INTACT	WHITE	VALLI KEE	SECOND	STAIR	BUILDING 33 UNIT 305	Negative	< LOD
358	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	SECOND	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
359	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	SECOND	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
360	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	SECOND	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
361	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	SECOND	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
362	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	SECOND	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
363	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	SECOND	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
364	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	SECOND	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
365	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
366	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
367	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
368	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
369	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
370	WINDOW SILL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
371	WINDOW FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
372	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
373	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
374	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	BATHROOM	BUILDING 33 UNIT 305	Negative	< LOD
375	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
376	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
377	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
378	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
379	SIDING	CEMENT BOARD	B	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
380	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
381	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
382	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
383	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
384	COVER AROUND GAS METERS	WOOD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 33 UNIT 305	Negative	< LOD
385	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 LAUNDRY ROOM	Negative	< LOD
386	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 LAUNDRY ROOM	Negative	< LOD
387	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 LAUNDRY ROOM	Negative	< LOD
388	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 LAUNDRY ROOM	Negative	< LOD
389	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 LAUNDRY ROOM	Negative	< LOD
390	DOOR JAM	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 LAUNDRY ROOM	Negative	< LOD
391	CEILING	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
392	CEILING	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
393	CEILING	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
394	CEILING	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
395	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
396	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
397	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
398	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
399	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
400	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 16 UNIT 53	Negative	< LOD
401	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 16 UNIT 53	Negative	< LOD
402	WALL	DRYWALL	A	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 16 UNIT 53	Negative	< LOD
403	WALL	DRYWALL	B	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 16 UNIT 53	Negative	< LOD
404	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 16 UNIT 53	Negative	< LOD
405	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 16 UNIT 53	Negative	< LOD
406	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 16 UNIT 53	Negative	< LOD
407	WINDOW FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 16 UNIT 53	Negative	< LOD
408	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 16 UNIT 53	Negative	< LOD
409	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 16 UNIT 53	Negative	< LOD
410	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 16 UNIT 53	Negative	< LOD
411	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 16 UNIT 53	Negative	< LOD
412	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 16 UNIT 53	Negative	< LOD
413	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 16 UNIT 53	Negative	< LOD
414	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 16 UNIT 53	Negative	< LOD
415	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
416	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
417	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
418	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
419	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
420	WINDOW FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
421	WINDOW SILL	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
422	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
423	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
424	SIDING	CEMENT BOARD	A	INTACT	TAN	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
425	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
426	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
427	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	BEDROOM	BUILDING 16 UNIT 53	Negative	< LOD
428	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
429	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
430	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
431	SIDING	CEMENT BOARD	A	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
432	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
433	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
434	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
435	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
436	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 15 UNIT 52	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
437	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 15 UNIT 52	Negative	< LOD
438	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 15 UNIT 52	Negative	< LOD
439	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 15 UNIT 52	Negative	< LOD
440	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 15 UNIT 52	Negative	< LOD
441	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 15 UNIT 52	Negative	< LOD
442	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 15 UNIT 52	Negative	< LOD
443	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 15 UNIT 52	Negative	< LOD
444	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 15 UNIT 52	Negative	< LOD
445	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 15 UNIT 52	Negative	< LOD
446	WINDOW FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 15 UNIT 52	Null	< LOD
447	WINDOW SILL	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 15 UNIT 52	Negative	< LOD
448	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 15 UNIT 52	Negative	< LOD
449	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 15 UNIT 52	Negative	< LOD
450	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 15 UNIT 52	Negative	< LOD
451	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 15 UNIT 52	Negative	< LOD
452	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 15 UNIT 52	Negative	< LOD
453	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 15 UNIT 52	Null	< LOD
454	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 15 UNIT 52	Negative	< LOD
455	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 15 UNIT 52	Negative	< LOD
456	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 15 UNIT 52	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
457	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 15 UNIT 52	Negative	< LOD
458	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 15 UNIT 52	Negative	< LOD
459	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 15 UNIT 52	Negative	< LOD
460	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
461	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
462	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
463	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
464	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
465	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
466	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
467	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
468	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
469											5.91
470	NIST STANDARD	PAINT				VALLI KEE				Negative	0.9
471	NIST STANDARD	PAINT				VALLI KEE				Positive	1.2
472	NIST STANDARD	PAINT				VALLI KEE				Positive	1.1
473	NIST STANDARD	PAINT				VALLI KEE				Negative	0.9
474	NIST STANDARD	PAINT				VALLI KEE				Negative	0.9
475	NIST STANDARD	PAINT				VALLI KEE				Null	1
476	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 27 UNIT 83	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
477	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 27 UNIT 83	Negative	< LOD
478	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 27 UNIT 83	Negative	< LOD
479	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 27 UNIT 83	Negative	< LOD
480	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 27 UNIT 83	Negative	< LOD
481	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 27 UNIT 83	Negative	< LOD
482	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 27 UNIT 83	Negative	< LOD
483	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 27 UNIT 83	Negative	< LOD
484	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 27 UNIT 83	Negative	< LOD
485	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 27 UNIT 83	Negative	< LOD
486	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 27 UNIT 83	Negative	< LOD
487	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 27 UNIT 83	Negative	< LOD
488	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 27 UNIT 83	Negative	< LOD
489	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 27 UNIT 83	Negative	< LOD
490	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
491	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
492	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
493	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
494	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
495	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
496	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
497	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
498	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
499	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOMB1	BUILDING 27 UNIT 83	Negative	< LOD
500	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
501	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
502	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
503	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Null	< LOD
504	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
505	ROLL DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
506	ROLL DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
507	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
508	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
509	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
510	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 27 UNIT 83	Negative	< LOD
511	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 27 UNIT 83	Negative	< LOD
512	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 27 UNIT 83	Negative	< LOD
513	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 27 UNIT 83	Negative	< LOD
514	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 27 UNIT 83	Negative	< LOD
515	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 27 UNIT 83	Negative	< LOD
516	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 27 UNIT 83	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
517	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 27 UNIT 83	Negative	< LOD
518	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
519	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
520	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
521	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
522	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
523	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
524	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
525	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
526	CEILING	DRYWALL		INTACT	BEIGE	VALLI KEE	FIRST	KITCHEN	BUILDING 28 UNIT 87	Negative	< LOD
527	WALL	DRYWALL	A	INTACT	BEIGE	VALLI KEE	FIRST	KITCHEN	BUILDING 28 UNIT 87	Negative	< LOD
528	WALL	DRYWALL	B	INTACT	BEIGE	VALLI KEE	FIRST	KITCHEN	BUILDING 28 UNIT 87	Negative	< LOD
529	WALL	DRYWALL	C	INTACT	BEIGE	VALLI KEE	FIRST	KITCHEN	BUILDING 28 UNIT 87	Negative	< LOD
530	WALL	DRYWALL	D	INTACT	BEIGE	VALLI KEE	FIRST	KITCHEN	BUILDING 28 UNIT 87	Negative	< LOD
531	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 28 UNIT 87	Negative	< LOD
532	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 28 UNIT 87	Negative	< LOD
533	CEILING	METAL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD
534	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD
535	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD
536	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
537	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD
538	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD
539	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD
540	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 28 UNIT 87	Negative	< LOD
541	CHIMNEY	METAL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 28 UNIT 87	Negative	< LOD
542	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 28 UNIT 87	Negative	< LOD
543	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 28 UNIT 87	Negative	< LOD
544	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 28 UNIT 87	Negative	< LOD
545	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 28 UNIT 87	Negative	< LOD
546	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 28 UNIT 87	Negative	< LOD
547	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 28 UNIT 87	Negative	< LOD
548	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
549	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
550	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
551	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
552	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
553	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
554	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
555	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD
556	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 28 UNIT 87	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
557	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 28 UNIT 87	Negative	< LOD
558	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 28 UNIT 87	Negative	< LOD
559	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 28 UNIT 87	Negative	< LOD
560	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 28 UNIT 87	Negative	< LOD
561	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 28 UNIT 87	Negative	< LOD
562	WINDOW SILL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 28 UNIT 87	Negative	< LOD
563	FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 28 UNIT 87	Negative	< LOD
564	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
565	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
566	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
567	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
568	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
569	ROLL DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
570	ROLL DOOR JAM	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
571	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
572	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
573	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 28 UNIT 87	Negative	< LOD
574	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
575	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
576	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
577	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
578	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
579	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
580	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
581	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
582	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 28 UNIT 87	Negative	< LOD
583	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
584	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
585	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
586	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
587	SIDING	CEMENT BOARD	A	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
588	SIDING	CEMENT BOARD	B	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
589	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
590	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
591	WINDOW FRAME	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
592	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
593	SIDING	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
594	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
595	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
596	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
597	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
598	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
599	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
600	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
601	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
602	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
603	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 29 UNIT 93	Negative	< LOD
604	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 29 UNIT 93	Negative	< LOD
605	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 29 UNIT 93	Negative	< LOD
606	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 29 UNIT 93	Negative	< LOD
607	WALL	DRYWALL	LEFT	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 29 UNIT 93	Negative	< LOD
608	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 29 UNIT 93	Negative	< LOD
609	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 29 UNIT 93	Negative	< LOD
610	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
611	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
612	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
613	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
614	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Null	< LOD
615	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD
616	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 29 UNIT 93	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
617	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
618	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
619	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
620	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
621	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
622	ROLL DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
623	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
624	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
625	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
626	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 29 UNIT 93	Negative	< LOD
627	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
628	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
629	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
630	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
631	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
632	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
633	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
634	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
635	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD
636	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
637	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 29 UNIT 93	Null	< LOD
638	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
639	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
640	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
641	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
642	SIDING	CEMENT BOARD	A	INTACT	GREEN	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
643	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
644	SIDING	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
645	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
646	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
647	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
648	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
649	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
650	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
651	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 29 UNIT 93	Negative	< LOD
652	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 17 UNIT 57	Negative	< LOD
653	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 17 UNIT 57	Negative	< LOD
654	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 17 UNIT 57	Negative	< LOD
655	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 17 UNIT 57	Negative	< LOD
656	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 17 UNIT 57	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
657	WINDOW SILL	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 17 UNIT 57	Negative	< LOD
658	WINDOW FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 17 UNIT 57	Negative	< LOD
659	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 17 UNIT 57	Negative	< LOD
660	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 17 UNIT 57	Negative	< LOD
661	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 17 UNIT 57	Negative	< LOD
662	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 17 UNIT 57	Negative	< LOD
663	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 17 UNIT 57	Negative	< LOD
664	WINDOW FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 17 UNIT 57	Negative	< LOD
665	SLIDING DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 17 UNIT 57	Negative	< LOD
666	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
667	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
668	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
669	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
670	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
671	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
672	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
673	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
674	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 17 UNIT 57	Negative	< LOD
675	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
676	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
677	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
678	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
679	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
680	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
681	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Null	< LOD
682	ROLL DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
683	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
684	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 17 UNIT 57	Negative	< LOD
685	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
686	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
687	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
688	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
689	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
690	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
691	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
692	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
693	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
694	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
695	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
696	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
697	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
698	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
699	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
700	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
701	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
702	WINDOW FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
703	WINDOW SILL	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
704	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
705	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 18 UNIT 60	Negative	< LOD
706	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
707	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
708	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
709	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
710	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
711	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
712	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
713	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
714	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
715	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
716	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
717	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 18 UNIT 60	Negative	< LOD
718	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 18 UNIT 60	Negative	< LOD
719	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 18 UNIT 60	Negative	< LOD
720	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 18 UNIT 60	Negative	< LOD
721	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 18 UNIT 60	Negative	< LOD
722	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 18 UNIT 60	Negative	< LOD
723	DOOR	WOOD		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 18 UNIT 60	Negative	< LOD
724	DOOR FRAME	WOOD		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 18 UNIT 60	Negative	< LOD
725	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 18 UNIT 60	Negative	< LOD
726	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 18 UNIT 60	Negative	< LOD
727	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 18 UNIT 60	Negative	< LOD
728	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 18 UNIT 60	Negative	< LOD
729	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 18 UNIT 60	Negative	< LOD
730	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 18 UNIT 60	Negative	< LOD
731	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 18 UNIT 60	Negative	< LOD
732	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
733	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
734	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
735	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
736	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
737	WINDOW FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
738	WINDOW SILL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
739	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
740	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 18 UNIT 60	Negative	< LOD
741	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 18 UNIT 60	Negative	< LOD
742	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 18 UNIT 60	Negative	< LOD
743	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 18 UNIT 60	Negative	< LOD
744	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 18 UNIT 60	Negative	< LOD
745	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 18 UNIT 60	Negative	< LOD
746	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 18 UNIT 60	Negative	< LOD
747	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 18 UNIT 60	Negative	< LOD
748	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
749	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
750	SIDING	CEMENT BOARD	A	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
751	SIDING	CEMENT BOARD	B	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
752	SIDING	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
753	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
754	TRIM	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
755	SHUTTER CAL										6.58
756	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
757	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Null	< LOD
758	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD
759	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD
760	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD
761	WINDOW FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD
762	WINDOW SILL	WOOD	B	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Null	< LOD
763	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD
764	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD
765	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	SECOND	KITCHEN	BUILDING 25 UNIT 82	Negative	< LOD
766	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 25 UNIT 82	Negative	< LOD
767	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 25 UNIT 82	Negative	< LOD
768	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 25 UNIT 82	Negative	< LOD
769	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 25 UNIT 82	Negative	< LOD
770	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 25 UNIT 82	Negative	< LOD
771	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD
772	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD
773	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD
774	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD
775	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD
776	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
777	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD
778	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 25 UNIT 82	Negative	< LOD
779	SHUTTER CAL										5.97
780	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 25 UNIT 82	Negative	< LOD
781	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 25 UNIT 82	Negative	< LOD
782	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 25 UNIT 82	Negative	< LOD
783	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 25 UNIT 82	Negative	< LOD
784	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 25 UNIT 82	Negative	< LOD
785	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 25 UNIT 82	Negative	< LOD
786	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 25 UNIT 82	Negative	< LOD
787	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 25 UNIT 82	Negative	< LOD
788	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 25 UNIT 82	Negative	< LOD
789	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 25 UNIT 82	Negative	< LOD
790	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
791	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
792	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
793	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
794	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
795	WINDOW FRAME	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
796	WINDOW SILL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
797	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
798	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 25 UNIT 82	Negative	< LOD
799	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
800	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Null	< LOD
801	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
802	SIDING	CEMENT BOARD	B	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
803	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
804	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
805	WINDOW FRAME	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
806	SIDING	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
807	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
808	SIDING	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
809	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
810	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
811	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
812	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 25 UNIT 82	Negative	< LOD
813	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 25 UNIT 82	Negative	< LOD
814	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 25 UNIT 82	Negative	< LOD
815	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 25 UNIT 82	Negative	< LOD
816	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 25 UNIT 82	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
817	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 25 UNIT 82	Negative	< LOD
818	DOOR FRAJE	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 25 UNIT 82	Negative	< LOD
819	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 24 UNIT 79	Negative	< LOD
820	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 24 UNIT 79	Negative	< LOD
821	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 24 UNIT 79	Negative	< LOD
822	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 24 UNIT 79	Negative	< LOD
823	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 24 UNIT 79	Negative	< LOD
824	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 24 UNIT 79	Negative	< LOD
825	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 24 UNIT 79	Negative	< LOD
826	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 24 UNIT 79	Negative	< LOD
827	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 24 UNIT 79	Negative	< LOD
828	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 24 UNIT 79	Negative	< LOD
829	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
830	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
831	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
832	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
833	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
834	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
835	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
836	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
837	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 24 UNIT 79	Negative	< LOD
838	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 24 UNIT 79	Negative	< LOD
839	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 24 UNIT 79	Negative	< LOD
840	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 24 UNIT 79	Negative	< LOD
841	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 24 UNIT 79	Negative	< LOD
842	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 24 UNIT 79	Negative	< LOD
843	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 24 UNIT 79	Negative	< LOD
844	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 24 UNIT 79	Negative	< LOD
845	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 24 UNIT 79	Negative	< LOD
846	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 24 UNIT 79	Null	< LOD
847	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 24 UNIT 79	Negative	< LOD
848	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 24 UNIT 79	Negative	< LOD
849	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 24 UNIT 79	Negative	< LOD
850	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
851	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
852	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
853	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
854	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
855	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
856	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
857	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
858	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 24 UNIT 79	Negative	< LOD
859	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
860	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
861	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
862	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
863	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
864	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
865	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
866	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
867	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 24 UNIT 79	Negative	< LOD
868	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
869	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
870	TRIM	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
871	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
872	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
873	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
874	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
875	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
876	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
877	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 24 UNIT 79	Negative	< LOD
878	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 20 UNIT 64	Negative	< LOD
879	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 20 UNIT 64	Negative	< LOD
880	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 20 UNIT 64	Negative	< LOD
881	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 20 UNIT 64	Negative	< LOD
882	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 20 UNIT 64	Negative	< LOD
883	WINDOW FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 20 UNIT 64	Negative	< LOD
884	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 20 UNIT 64	Negative	< LOD
885	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 20 UNIT 64	Negative	< LOD
886	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 20 UNIT 64	Negative	< LOD
887	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 20 UNIT 64	Negative	< LOD
888	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 20 UNIT 64	Negative	< LOD
889	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 20 UNIT 64	Negative	< LOD
890	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 20 UNIT 64	Negative	< LOD
891	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 20 UNIT 64	Negative	< LOD
892	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 20 UNIT 64	Negative	< LOD
893	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 20 UNIT 64	Negative	< LOD
894	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 20 UNIT 64	Negative	< LOD
895	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 20 UNIT 64	Negative	< LOD
896	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 20 UNIT 64	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
897	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROM 1	BUILDING 20 UNIT 64	Negative	< LOD
898	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROM 1	BUILDING 20 UNIT 64	Negative	< LOD
899	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROM 1	BUILDING 20 UNIT 64	Negative	< LOD
900	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROM 1	BUILDING 20 UNIT 64	Negative	< LOD
901	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROM 1	BUILDING 20 UNIT 64	Negative	< LOD
902	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
903	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
904	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
905	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
906	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
907	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
908	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
909	SLIDING DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
910	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
911	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 20 UNIT 64	Negative	< LOD
912	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 20 UNIT 64	Negative	< LOD
913	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 20 UNIT 64	Negative	< LOD
914	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 20 UNIT 64	Negative	< LOD
915	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 20 UNIT 64	Negative	< LOD
916	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 20 UNIT 64	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
917	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 20 UNIT 64	Negative	< LOD
918	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 20 UNIT 64	Negative	< LOD
919	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
920	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
921	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
922	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
923	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
924	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
925	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
926	ROLL DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 20 UNIT 64	Negative	< LOD
927	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
928	SOFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
929	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
930	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
931	SIDING	CEMENT BOARD	A	INTACT	ORANGE	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
932	SIDING	CEMENT BOARD	A	INTACT	TAN	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
933	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
934	SIDING	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
935	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD
936	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
937	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXRERIOR	BUILDING 20 UNIT 64	Null	< LOD
938	SHUTTER CAL										6.29
939	NIST STANDARD	PAINT		INTACT	RED	VALLI KEE	FIRST			Negative	0.9
940	NIST STANDARD	PAINT		INTACT	RED	VALLI KEE	FIRST			Positive	1
941	NIST STANDARD	PAINT		INTACT	RED	VALLI KEE	FIRST			Negative	0.9
942	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BKILDING 19 UNIT 61	Negative	< LOD
943	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BKILDING 19 UNIT 61	Negative	< LOD
944	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BKILDING 19 UNIT 61	Negative	< LOD
945	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BKILDING 19 UNIT 61	Negative	< LOD
946	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BKILDING 19 UNIT 61	Negative	< LOD
947	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BKILDING 19 UNIT 61	Negative	< LOD
948	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BKILDING 19 UNIT 61	Negative	< LOD
949	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BKILDING 19 UNIT 61	Negative	< LOD
950	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BKILDING 19 UNIT 61	Negative	< LOD
951	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BKILDING 19 UNIT 61	Negative	< LOD
952	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BKILDING 19 UNIT 61	Negative	< LOD
953	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BKILDING 19 UNIT 61	Negative	< LOD
954	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
955	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
956	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
957	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
958	WALL	DRYWALL	D	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
959	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
960	DOOR FRAME	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
961	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
962	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
963	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
964	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BKILDING 19 UNIT 61	Negative	< LOD
965	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
966	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
967	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
968	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
969	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
970	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
971	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
972	ROLL DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BKILDING 19 UNIT 61	Negative	< LOD
973	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BKILDING 19 UNIT 61	Negative	< LOD
974	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BKILDING 19 UNIT 61	Negative	< LOD
975	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BKILDING 19 UNIT 61	Negative	< LOD
976	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BKILDING 19 UNIT 61	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
977	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BKILDING 19 UNIT 61	Negative	< LOD
978	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BKILDING 19 UNIT 61	Negative	< LOD
979	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BKILDING 19 UNIT 61	Negative	< LOD
980	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BKILDING 19 UNIT 61	Negative	< LOD
981	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BKILDING 19 UNIT 61	Negative	< LOD
982	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BKILDING 19 UNIT 61	Negative	< LOD
983	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BKILDING 19 UNIT 61	Negative	< LOD
984	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BKILDING 19 UNIT 61	Negative	< LOD
985	WINDOW FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BKILDING 19 UNIT 61	Negative	< LOD
986	WINDOW SILL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BKILDING 19 UNIT 61	Negative	< LOD
987	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BKILDING 19 UNIT 61	Negative	< LOD
988	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BKILDING 19 UNIT 61	Negative	< LOD
989	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BKILDING 19 UNIT 61	Negative	< LOD
990	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BKILDING 19 UNIT 61	Negative	< LOD
991	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BKILDING 19 UNIT 61	Negative	< LOD
992	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BKILDING 19 UNIT 61	Negative	< LOD
993	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BKILDING 19 UNIT 61	Negative	< LOD
994	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
995	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
996	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
997	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
998	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
999	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
1000	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
1001	SIDING	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
1002	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
1003	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
1004	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BKILDING 19 UNIT 61	Negative	< LOD
1005	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 22 UNIT 69	Negative	< LOD
1006	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 22 UNIT 69	Negative	< LOD
1007	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 22 UNIT 69	Negative	< LOD
1008	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 22 UNIT 69	Negative	< LOD
1009	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 22 UNIT 69	Negative	< LOD
1010	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 22 UNIT 69	Negative	< LOD
1011	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 22 UNIT 69	Negative	< LOD
1012	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 22 UNIT 69	Negative	< LOD
1013	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 22 UNIT 69	Negative	< LOD
1014	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 22 UNIT 69	Negative	< LOD
1015	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 22 UNIT 69	Negative	< LOD
1016	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 22 UNIT 69	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1017	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1018	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1019	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1020	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1021	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1022	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1023	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1024	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1025	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 22 UNIT 69	Negative	< LOD
1026	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 22 UNIT 69	Negative	< LOD
1027	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 22 UNIT 69	Negative	< LOD
1028	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 22 UNIT 69	Negative	< LOD
1029	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 22 UNIT 69	Negative	< LOD
1030	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 22 UNIT 69	Negative	< LOD
1031	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 22 UNIT 69	Negative	< LOD
1032	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 22 UNIT 69	Negative	< LOD
1033	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1034	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1035	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1036	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1037	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1038	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1039	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1040	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1041	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 22 UNIT 69	Negative	< LOD
1042	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 22 UNIT 69	Negative	< LOD
1043	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 22 UNIT 69	Negative	< LOD
1044	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 22 UNIT 69	Negative	< LOD
1045	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 22 UNIT 69	Negative	< LOD
1046	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 22 UNIT 69	Negative	< LOD
1047	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 22 UNIT 69	Negative	< LOD
1048	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 22 UNIT 69	Negative	< LOD
1049	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 22 UNIT 69	Negative	< LOD
1050	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 22 UNIT 69	Negative	< LOD
1051	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 22 UNIT 69	Negative	< LOD
1052	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 22 UNIT 69	Negative	< LOD
1053	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 22 UNIT 69	Negative	< LOD
1054	WINDOW FRAME	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 22 UNIT 69	Negative	< LOD
1055	WINDOW SILL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 22 UNIT 69	Negative	< LOD
1056	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1057	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1058	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1059	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1060	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1061	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1062	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1063	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1064	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1065	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1066	SIDING	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1067	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1068	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1069	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1070	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 11 UNIT 37	Negative	< LOD
1071	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 11 UNIT 37	Negative	< LOD
1072	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 11 UNIT 37	Negative	< LOD
1073	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 11 UNIT 37	Negative	< LOD
1074	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 11 UNIT 37	Negative	< LOD
1075	WINDOW FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 11 UNIT 37	Negative	< LOD
1076	WINDOW SILL	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 11 UNIT 37	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1077	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1078	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1079	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1080	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1081	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1082	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1083	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1084	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Negative	< LOD
1085	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 11 UNIT 37	Null	< LOD
1086	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 11 UNIT 37	Negative	< LOD
1087	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 11 UNIT 37	Negative	< LOD
1088	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 11 UNIT 37	Negative	< LOD
1089	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 11 UNIT 37	Negative	< LOD
1090	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 11 UNIT 37	Negative	< LOD
1091	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 11 UNIT 37	Negative	< LOD
1092	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 11 UNIT 37	Negative	< LOD
1093	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1094	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1095	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1096	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1097	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1098	SLIDING DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1099	SLIDING DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1100	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1101	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 11 UNIT 37	Negative	< LOD
1102	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 11 UNIT 37	Negative	< LOD
1103	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 11 UNIT 37	Negative	< LOD
1104	SHUTTER CAL										6.36
1105	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 11 UNIT 37	Negative	< LOD
1106	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 11 UNIT 37	Negative	< LOD
1107	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 11 UNIT 37	Negative	< LOD
1108	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 11 UNIT 37	Negative	< LOD
1109	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 11 UNIT 37	Negative	< LOD
1110	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 11 UNIT 37	Negative	< LOD
1111	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 11 UNIT 37	Negative	< LOD
1112	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 11 UNIT 37	Negative	< LOD
1113	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 11 UNIT 37	Negative	< LOD
1114	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 11 UNIT 37	Negative	< LOD
1115	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1116	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1117	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1118	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1119	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1120	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1121	SIDING	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1122	WINDOW FRAME	CEMENT BOARD	A	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1123	WINDOW FRAME	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1124	WINDOW FRAME	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1125	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1126	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1127	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1128	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1129	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1130	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1131	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1132	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1133	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1134	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1135	WINDOW FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1136	WINDOW SILL	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1137	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1138	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 12 UNIT 40	Negative	< LOD
1139	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 12 UNIT 40	Negative	< LOD
1140	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 12 UNIT 40	Negative	< LOD
1141	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 12 UNIT 40	Negative	< LOD
1142	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 12 UNIT 40	Negative	< LOD
1143	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 12 UNIT 40	Negative	< LOD
1144	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 12 UNIT 40	Negative	< LOD
1145	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1146	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1147	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1148	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1149	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1150	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1151	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1152	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 12 UNIT 40	Negative	< LOD
1153	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 12 UNIT 40	Negative	< LOD
1154	WALL	DRYWALL	A	INTACT	BLUE	VALLI KEE	FIRST	BATHROOM	BUILDING 12 UNIT 40	Negative	< LOD
1155	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 12 UNIT 40	Negative	< LOD
1156	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 12 UNIT 40	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1157	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 12 UNIT 40	Negative	< LOD
1158	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 12 UNIT 40	Negative	< LOD
1159	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 12 UNIT 40	Negative	< LOD
1160	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 12 UNIT 40	Negative	< LOD
1161	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 12 UNIT 40	Negative	< LOD
1162	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 12 UNIT 40	Negative	< LOD
1163	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 12 UNIT 40	Negative	< LOD
1164	WALL	DRYWALL	D	INTACT	PINK	VALLI KEE	FIRST	BEDROOM 1	BUILDING 12 UNIT 40	Negative	< LOD
1165	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 12 UNIT 40	Negative	< LOD
1166	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 12 UNIT 40	Negative	< LOD
1167	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1168	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1169	WALL	DRYWALL	B	INTACT	GREEN	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1170	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1171	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1172	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1173	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1174	ROLL DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1175	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD
1176	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 12 UNIT 40	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1177	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1178	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1179	WALL	DRYWALL	B	INTACT	GRAY	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1180	WALL	DRYWALL	C	INTACT	GRAY	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1181	WALL	DRYWALL	LEFT	INTACT	GREEN	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1182	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1183	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1184	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1185	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 12 UNIT 40	Negative	< LOD
1186	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1187	DOOR	METAL	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1188	DOOR FRAME	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1189	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1190	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1191	SIDING	CEMENT BOARD	A	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1192	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1193	SIDING	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1194	WINDOW FRAME	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1195	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1196	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1197	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1198	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 14 UNIT 45	Negative	< LOD
1199	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 14 UNIT 45	Negative	< LOD
1200	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 14 UNIT 45	Negative	< LOD
1201	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 14 UNIT 45	Negative	< LOD
1202	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 14 UNIT 45	Negative	< LOD
1203	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 14 UNIT 45	Negative	< LOD
1204	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 14 UNIT 45	Negative	< LOD
1205	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 14 UNIT 45	Negative	< LOD
1206	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 14 UNIT 45	Negative	< LOD
1207	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 14 UNIT 45	Negative	< LOD
1208	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 14 UNIT 45	Negative	< LOD
1209	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 14 UNIT 45	Negative	< LOD
1210	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1211	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1212	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1213	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1214	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1215	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1216	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1217	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1218	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 14 UNIT 45	Negative	< LOD
1219	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 14 UNIT 45	Negative	< LOD
1220	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 14 UNIT 45	Negative	< LOD
1221	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 14 UNIT 45	Negative	< LOD
1222	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 14 UNIT 45	Negative	< LOD
1223	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 14 UNIT 45	Negative	< LOD
1224	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 14 UNIT 45	Negative	< LOD
1225	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 14 UNIT 45	Negative	< LOD
1226	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	0.7
1227	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1228	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1229	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1230	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1231	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1232	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1233	ROLL DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1234	ROLL DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 14 UNIT 45	Negative	< LOD
1235	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1236	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1237	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1238	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1239	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1240	WINDOW FRAME	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1241	WINDOW SILL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1242	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1243	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 14 UNIT 45	Negative	< LOD
1244	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Null	< LOD
1245	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1246	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1247	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1248	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1249	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1250	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1251	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1252	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 14 UNIT 45	Negative	< LOD
1253	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1254	DOOR	METAL	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1255	DOOR FRAME	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1256	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1257	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1258	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1259	TRIM	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1260	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1261	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1262	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1263	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1264	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1265	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 13 UNIT 41	Negative	< LOD
1266	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 13 UNIT 41	Negative	< LOD
1267	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 13 UNIT 41	Negative	< LOD
1268	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 13 UNIT 41	Negative	< LOD
1269	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 13 UNIT 41	Null	< LOD
1270	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 13 UNIT 41	Negative	< LOD
1271	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 13 UNIT 41	Negative	< LOD
1272	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 13 UNIT 41	Negative	< LOD
1273	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 13 UNIT 41	Negative	< LOD
1274	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 13 UNIT 41	Negative	< LOD
1275	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 13 UNIT 41	Negative	< LOD
1276	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 13 UNIT 41	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1277	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1278	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1279	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1280	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1281	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1282	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1283	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1284	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1285	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1286	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 13 UNIT 41	Negative	< LOD
1287	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 13 UNIT 41	Negative	< LOD
1288	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 13 UNIT 41	Negative	< LOD
1289	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 13 UNIT 41	Negative	< LOD
1290	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 13 UNIT 41	Negative	< LOD
1291	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 13 UNIT 41	Negative	< LOD
1292	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 13 UNIT 41	Negative	< LOD
1293	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 13 UNIT 41	Negative	< LOD
1294	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 13 UNIT 41	Negative	< LOD
1295	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 13 UNIT 41	Negative	< LOD
1296	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 13 UNIT 41	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1297	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 13 UNIT 41	Negative	< LOD
1298	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 13 UNIT 41	Negative	< LOD
1299	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1300	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1301	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1302	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1303	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1304	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1305	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1306	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1307	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 13 UNIT 41	Negative	< LOD
1308	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 13 UNIT 41	Negative	< LOD
1309	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 13 UNIT 41	Negative	< LOD
1310	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 13 UNIT 41	Negative	< LOD
1311	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 13 UNIT 41	Negative	< LOD
1312	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 13 UNIT 41	Negative	< LOD
1313	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 13 UNIT 41	Negative	< LOD
1314	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 13 UNIT 41	Negative	< LOD
1315	HEAT VENT	METAL		INTACT	TAN	VALLI KEE	FIRST	BATHROOM	BUILDING 13 UNIT 41	Negative	< LOD
1316	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1317	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1318	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1319	DOOR	METAL	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1320	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1321	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1322	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1323	TRIM	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1324	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1325	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1326	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1327	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1328	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1329	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1330	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1331	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1332	WINDOW FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1333	WINDOW SILL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1334	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1335	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 7 UNIT 26	Negative	< LOD
1336	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 7 UNIT 26	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1337	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 7 UNIT 26	Negative	< LOD
1338	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 7 UNIT 26	Negative	< LOD
1339	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 7 UNIT 26	Negative	< LOD
1340	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 7 UNIT 26	Negative	< LOD
1341	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1342	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1343	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1344	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1345	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1346	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1347	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1348	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1349	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1350	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 7 UNIT 26	Negative	< LOD
1351	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 7 UNIT 26	Negative	< LOD
1352	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 7 UNIT 26	Negative	< LOD
1353	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 7 UNIT 26	Negative	< LOD
1354	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 7 UNIT 26	Negative	< LOD
1355	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 7 UNIT 26	Negative	< LOD
1356	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 7 UNIT 26	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1357	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 7 UNIT 26	Negative	< LOD
1358	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1359	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1360	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1361	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	0.6
1362	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1363	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1364	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1365	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1366	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1367	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1368	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1369	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1370	WINDOW FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1371	WINDOW SILL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1372	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1373	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 7 UNIT 26	Negative	< LOD
1374	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD
1375	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD
1376	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1377	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Null	< LOD
1378	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD
1379	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD
1380	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD
1381	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD
1382	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 7 UNIT 26	Negative	< LOD
1383	SHUTTER CAL										5.81
1384	NIST STANDARD	PAINT			RED	VALLI KEE				Positive	1.1
1385	NIST STANDARD	PAINT			RED	VALLI KEE				Positive	1.1
1386	NIST STANDARD	PAINT			RED	VALLI KEE				Positive	1.1
1387	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Null	< LOD
1388	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1389	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1390	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1391	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1392	SIDING	CEMENT BOARD	B	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1393	SIDING	CEMENT BOARD	C	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1394	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1395	SIDING	CEMENT BOARD	D	INTACT	YELLOW	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1396	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1397	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1398	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 8 UNIT 28	Negative	< LOD
1399	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 8 UNIT 28	Negative	< LOD
1400	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 8 UNIT 28	Negative	< LOD
1401	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 8 UNIT 28	Negative	< LOD
1402	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 8 UNIT 28	Negative	< LOD
1403	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 8 UNIT 28	Negative	< LOD
1404	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	KITCHEN	BUILDING 8 UNIT 28	Negative	< LOD
1405	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 8 UNIT 28	Negative	< LOD
1406	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 8 UNIT 28	Negative	< LOD
1407	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 8 UNIT 28	Negative	< LOD
1408	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 8 UNIT 28	Negative	< LOD
1409	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 8 UNIT 28	Negative	< LOD
1410	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1411	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1412	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1413	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1414	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1415	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1416	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1417	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1418	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1419	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1420	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1421	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1422	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1423	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 8 UNIT 28	Negative	< LOD
1424	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1425	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1426	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1427	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1428	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1429	WINDOW SILL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1430	WINDOW FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1431	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1432	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 8 UNIT 28	Negative	< LOD
1433	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1434	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1435	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1436	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1437	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1438	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1439	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1440	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1441	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1442	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 8 UNIT 28	Negative	< LOD
1443	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 8 UNIT 28	Negative	< LOD
1444	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 8 UNIT 28	Negative	< LOD
1445	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 8 UNIT 28	Negative	< LOD
1446	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 8 UNIT 28	Negative	< LOD
1447	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 8 UNIT 28	Negative	< LOD
1448	DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 8 UNIT 28	Negative	< LOD
1449	DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 8 UNIT 28	Negative	< LOD
1450	DOOR	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1451	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1452	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1453	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 8 UNIT 28	Negative	< LOD
1454	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1455	DOOR	METAL	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1456	DOOR FRAME	CE	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1457	SIDING	CE	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1458	SIDING	CE	A	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1459	SIDING	CE	A	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1460	SIDING	CE	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1461	SIDING	CE	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Null	< LOD
1462	TRIM	CE	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1463	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1464	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1465	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1466	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1467	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1468	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1469	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1470	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 10 UNIT 36	Negative	< LOD
1471	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 10 UNIT 36	Negative	< LOD
1472	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 10 UNIT 36	Negative	< LOD
1473	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 10 UNIT 36	Negative	< LOD
1474	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 10 UNIT 36	Negative	< LOD
1475	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LAUNDRY	BUILDING 10 UNIT 36	Negative	< LOD
1476	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1477	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1478	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1479	WALL	DRYWALL	C	INTACT	TAN	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1480	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1481	SLIDING DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	LIVING ROOM	BUILDING 10 UNIT 36	Negative	< LOD
1482	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1483	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1484	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1485	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1486	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1487	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1488	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1489	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1490	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1491	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 1	BUILDING 10 UNIT 36	Negative	< LOD
1492	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1493	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1494	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1495	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1496	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1497	ROLL DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1498	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1499	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1500	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1501	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1502	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1503	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1504	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1505	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1506	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1507	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1508	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1509	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1510	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1511	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1512	ROLL DOOR	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1513	ROLL DOOR FRAME	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1514	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1515	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 2	BUILDING 10 UNIT 36	Negative	< LOD
1516	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 10 UNIT 36	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1517	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 10 UNIT 36	Negative	< LOD
1518	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 10 UNIT 36	Negative	< LOD
1519	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 10 UNIT 36	Negative	< LOD
1520	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 10 UNIT 36	Negative	< LOD
1521	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 10 UNIT 36	Negative	< LOD
1522	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 3	BUILDING 10 UNIT 36	Negative	< LOD
1523	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1524	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1525	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1526	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1527	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1528	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1529	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1530	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1531	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BEDROOM 4	BUILDING 10 UNIT 36	Negative	< LOD
1532	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	HALF BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1533	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	HALF BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1534	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	HALF BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1535	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	HALF BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1536	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	HALF BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1537	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	HALF BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1538	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	HALF BATHROOM	BUILDING 10 UNIT 36	Negative	< LOD
1539	DOOR	METAL	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1540	DOOR FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1541	WINDOW FRAME	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1542	SOFFIT	CEMENT BOARD	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1543	SIDING	CEMENT BOARD	A	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1544	SIDING	CEMENT BOARD	B	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1545	SIDING	CEMENT BOARD	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1546	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1547	WINDOW FRAME	CEMENT BOARD	C	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1548	SIDING	CEMENT BOARD	C	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1549	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1550	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1551	SIDING	CEMENT BOARD	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1552	SIDING	CEMENT BOARD	D	INTACT	ORANGE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1553	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1554	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1555	POLE	METAL		INTACT	BLUE	VALLI KEE		PLAYGROUND	NEXT TO COMMUNTY CENTER	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1556	POLE	METAL		INTACT	RED	VALLI KEE		PLAYGROUND	NEXT TO COMMUNTY CENTER	Negative	< LOD
1557	POLE	METAL		INTACT	WHITE	VALLI KEE		PLAYGROUND	NEXT TO COMMUNTY CENTER	Negative	< LOD
1558	SHUTTER CAL										5.89
1559	POLE	METAL		INTACT	YELLOW	VALLI KEE		PLAYGROUND	NEXT TO COMMUNIT CENTER	Negative	< LOD
1560	POLE	METAL		INTACT	PURPLE	VALLI KEE		PLAYGROUND	NEXT TO COMMUNIT CENTER	Negative	< LOD
1561	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1562	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1563	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1564	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1565	DOOR FRAME	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1566	COVEBASE	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1567	COVEBASE	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1568	COVEBASE	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1569	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1570	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1571	WINDOW FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD
1572	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM	MANAGEMENT OFFICE	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1573	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1574	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1575	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1576	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1577	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM RESTROOM	MANAGEMENT OFFICE	Negative	3.8
1578	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1579	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	RECEPTION ROOM RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1580	WALL	WOOD	A	INTACT	Gray	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1581	WALL	WOOD	B	INTACT	Gray	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	4.5
1582	WALL	WOOD	C	INTACT	GRAY	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1583	WALL	WOOD	D	INTACT	Gray	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1584	WINDOW FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1585	WINDOW SILL	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1586	DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1587	DOOR FRAME	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1588	COVEBASE	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1589	COVEBASE	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	4.4
1590	COVEBASE	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	2.1
1591	COVEBASE	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	RESIDENCE SERVICES OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1592	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	BREAK ROOM	MANAGEMENT OFFICE	Negative	< LOD
1593	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	BREAK ROOM	MANAGEMENT OFFICE	Negative	< LOD
1594	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	BREAK ROOM	MANAGEMENT OFFICE	Negative	< LOD
1595	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	BREAK ROOM	MANAGEMENT OFFICE	Negative	< LOD
1596	ROLL DOOR	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	BREAK ROOM	MANAGEMENT OFFICE	Negative	< LOD
1597	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	WORK ROOM HALL	MANAGEMENT OFFICE	Negative	< LOD
1598	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	WORK ROOM HALL	MANAGEMENT OFFICE	Negative	< LOD
1599	WALL	DRYWALL	B	INTACT	ORANGE	VALLI KEE	FIRST	WORK ROOM HALL	MANAGEMENT OFFICE	Negative	< LOD
1600	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	WORK ROOM HALL	MANAGEMENT OFFICE	Negative	< LOD
1601	WALL	DRYWALL	A	INTACT	TAN	VALLI KEE	FIRST	MANAGERS OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1602	WALL	DRYWALL	B	INTACT	TAN	VALLI KEE	FIRST	MANAGERS OFFICE	MANAGEMENT OFFICE	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1603	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	MANAGERS OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1604	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	MANAGERS OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1605	WINDOW SILL	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	MANAGERS OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1606	DOOR FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	MANAGERS OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1607	DOOR	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	MANAGERS OFFICE	MANAGEMENT OFFICE	Negative	< LOD
1608	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1609	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1610	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1611	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1612	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1613	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1614	WINDOW FRAME	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1615	WINDOW SILL	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1616	COVEBASE	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1617	COVEBASE	WOOD	B	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1618	COVEBASE	WOOD	C	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1619	COVEBASE	WOOD	D	INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1620	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	CONFRENCE ROOM	MANAGEMENT OFFICE	Negative	< LOD
1621	CEILING	DRYWALL		INTACT	WHITE	VALLI KEE	FIRST	EMPLOYEE RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1622	WALL	DRYWALL	A	INTACT	WHITE	VALLI KEE	FIRST	EMPLOYEE RESTROOM	MANAGEMENT OFFICE	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1623	WALL	DRYWALL	B	INTACT	WHITE	VALLI KEE	FIRST	EMPLOYEE RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1624	WALL	DRYWALL	C	INTACT	WHITE	VALLI KEE	FIRST	EMPLOYEE RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1625	WALL	DRYWALL	D	INTACT	WHITE	VALLI KEE	FIRST	EMPLOYEE RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1626	DOOR	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	EMPLOYEE RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1627	DOOR FRAME	WOOD	A	INTACT	WHITE	VALLI KEE	FIRST	EMPLOYEE RESTROOM	MANAGEMENT OFFICE	Negative	< LOD
1628	SIDING	CEMENT BOARD	A	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1629	SIDING	CEMENT BOARD	A	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1630	TRIM	CEMENT BOARD	A	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1631	WINDOW FRAME	CEMENT BOARD	A	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1632	FENCE	METAL	A	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1633	DOWNSPOUT	METAL	A	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1634	SIDING	CEMENT BOARD	B	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1635	SIDING	CEMENT BOARD	B	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1636	SIDING	CEMENT BOARD	C	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1637	SIDING	CEMENT BOARD	C	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1638	SIDING	CEMENT BOARD	C	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1639	DOWNSPOUT	CEMENT BOARD	C	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1640	ROLL DOOR	METAL	C	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1641	DOOR	METAL	C	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1642	DOOR FRAME	CEMENT BOARD	C	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1643	WINDOW FRAME	CEMENT BOARD	C	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1644	SIDING	CEMENT BOARD	D	INTACT	BLACK	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1645	SIDING	CEMENT BOARD	D	INTACT	BROWN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1646	SIDING	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1647	SOFFIT	CEMENT BOARD	D	INTACT	TAN	VALLI KEE	FIRST	EXTERIOR	MANAGEMENT OFFICE	Negative	< LOD
1648	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1649	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 10 UNIT 36	Negative	< LOD
1650	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1651	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 11 UNIT 37	Negative	< LOD
1652	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1653	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 12 UNIT 40	Negative	< LOD
1654	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1655	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 13 UNIT 41	Negative	< LOD
1656	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1657	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1658	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1659	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 14 UNIT 45	Negative	< LOD
1660	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1661	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 7 UNIT 26	Negative	< LOD
1662	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1663	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 8 UNIT 28	Negative	< LOD
1664	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 20 UNIT 64	Negative	< LOD
1665	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 20 UNIT 64	Negative	< LOD
1666	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 19 UNIT 61	Negative	< LOD
1667	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 19 UNIT 61	Negative	< LOD
1668	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
1669	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 18 UNIT 60	Negative	< LOD
1670	GUTTER	METAL	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
1671	DOWNSPOUT	METAL	D	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 17 UNIT 57	Negative	< LOD
1672	DOWNSPOUT	METAL	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
1673	DOWNSPOUT	METAL	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
1674	GUTTER	METAL	B	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 16 UNIT 53	Negative	< LOD
1675	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
1676	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 15 UNIT 52	Negative	< LOD
1677	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNIT 14	Negative	< LOD
1678	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 4 UNIT 14	Negative	< LOD
1679	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
1680	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
1681	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 2 UNIT 8	Negative	< LOD
1682	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 2 UNIT 8	Negative	< LOD

Reading	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Location	Positive/ Negative	XRF Reading
1683	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 1 UNIT 4	Negative	< LOD
1684	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 1 UNIT 4	Negative	< LOD
1685	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
1686	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 3 UNIT 12	Negative	< LOD
1687	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
1688	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 31 UNIT 308	Negative	< LOD
1689	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
1690	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 32 UNIT 312	Negative	< LOD
1691	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
1692	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 28 UNIT 87	Negative	< LOD
1693	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
1694	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 27 UNIT 83	Negative	< LOD
1695	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
1696	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 25 UNIT 82	Negative	< LOD
1697	DOWNSPOUT	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD
1698	GUTTER	METAL	A	INTACT	WHITE	VALLI KEE	FIRST	EXTERIOR	BUILDING 22 UNIT 69	Negative	< LOD

TAB 2

Certification

STATE OF WASHINGTON

Department of Commerce

Lead-Based Paint Program

Janet J. Murphy

Has fulfilled the certification requirements of Washington Administrative code (WAC) 365-230 and has been certified to conduct lead-based paint activities pursuant to WAC 365-230-200 as a:

Risk Assessor

Certification #	Issuance Date	Expiration Date
0258	3/23/2016	3/8/2019

STATE OF WASHINGTON

Department of Commerce

Lead-Based Paint Abatement Firm

PBS Engineering & Environmental Inc.

Has fulfilled the certification requirements of
WAC 365-230
and has been certified to conduct lead-based
paint activities.

Certification #	Issuance Date	Expiration Date
178	05/24/2017	09/03/2019