

Lead-Based Paint Inspection Report

Ballinger Homes
2200 NE 201st Place
Shoreline, Washington

Prepared for:
Deborah McCaslin
King County Housing
700 Andover Park West, Suite C
Seattle, Washington 98188

February 23, 2018
PBS Project No. 40573.151



2517 EASTLAKE AVENUE EAST
SUITE 100
SEATTLE, WA 98102
206.233.9639 MAIN
866.727.0140 FAX
PBSUSA.COM

LEAD-BASED PAINT INSPECTION REPORT

Ballinger Homes
2200 NE 201st Place
Shoreline, WA 98155

For

King County Housing Authority
700 Andover Park West, Suite C
Seattle, Washington 98188

This report is for the exclusive use of the client and is not to be photographed, photocopied, or similarly reproduced, in total or in part, without the express written consent of the client and/or PBS Engineering and Environmental Inc.

Prepared by:

PBS Engineering and Environmental Inc.
2517 Eastlake Avenue East Suite 100
Seattle, Washington 98102



TABLE OF CONTENTS

| | |
|--|----------|
| 1 IDENTIFYING INFORMATION..... | 1 |
| 2 LEAD-BASED PAINT INSPECTION..... | 2 |
| 2.1 Site Information..... | 2 |
| 2.2 Lead-Based Paint Inspection and Sampling | 2 |
| 2.2.1 XRF Sampling..... | 2 |
| 2.2.2 Bulk Paint-Chip Sampling | 3 |
| 2.3 Components with Lead-Based Paint..... | 3 |
| 2.4 Deteriorated Lead-Based Paint Surfaces..... | 3 |

SUPPORTING DATA

TAB 1: XRF Data Sheets

TAB 2: Certifications

1 IDENTIFYING INFORMATION

BUILDING DATA

Ballinger Homes
2200 201st Place
Shoreline, WA 98155

CLIENT DATA

King County Housing Authority
700 Andover Park West, Suite C
Seattle, WA 98188
Attn: Ms. Deborah McCaslin

SCOPE OF ASSESSMENT

PBS Engineering and Environmental, Inc. (PBS) conducted a lead-based paint inspection at Ballinger Homes on February 13 – 16, 2018, in accordance with the U.S. Department Housing and Urban Development (HUD), Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing.

CERTIFICATIONS

Risk Assessor

Janet Murphy
State of Washington
Department of Community, Trade and Economic Development
Risk Assessor Certification No: 0258, Expiration Date: 3/8/2019



Signature

February 23, 2018

Date

Firm

PBS Engineering and Environmental
2517 Eastlake Avenue East
Seattle, Washington 98102
Telephone: 206.223.9639

Certification No: 129143
Expiration Date: 7/31/2018

2 LEAD-BASED PAINT INSPECTION

2.1 Site Information

Ballinger Homes consist of 24 residential buildings with 110 units and separate buildings for the maintenance shop, management offices, laundry and Family Support Center. The buildings are of wood construction with gypsum interior walls and ceilings. The exterior is vinyl siding and trim. Residential units are one, two, three, four and five bedrooms with a bathroom, kitchen/dining room, and living room area. The buildings are in good condition.

Architectural finishes are uniform throughout. The majority of the interior components are painted. Walls are painted gypsum wallboard. Doors are painted wood or metal. Door and window frames are painted medium density particle board (MDF) or vinyl. The exterior window frames are vinyl.

2.2 Lead-Based Paint Inspection and Sampling

Based on information provided by KCHA, Ballinger Homes was constructed in the 1969. All exterior wood siding was replaced in 2003 with vinyl siding and trim. Residential unit interiors were also substantially renovated in 2003. Based on Table 7.3 in Chapter 7 of the HUD Guidelines, 26 units at the site were included in PBS's inspection. Additionally, PBS inspected the Family Support Center, Laundry, Tenant Reception area and playground.

2.2.1 XRF Sampling

The presence of lead in paint was determined through x-ray fluorescence spectroscopy. A handheld Niton X-Ray Fluorescence Analyzer (XRF), Model XLP-300A Serial # 102877 operating in lead paint mode was used to perform a surface by surface lead paint inspection of each painted surface in the selected units and other building areas. Calibration was checked based on the requirements of the Performance Characteristic Sheet for the XRF Analyzer. All calibration readings were within the tolerance for this instrument.

HUD and the Environmental Protection Agency (EPA) have set 1.0 milligrams per square centimeter (mg/cm^2) as the threshold limit for lead-based paint as determined through X-Ray Fluorescence (XRF) testing. HUD and EPA have set 5,000 parts per million (ppm) or 0.5 percent by atomic absorption spectroscopy (AAS) laboratory analysis as the threshold limit for lead-based paint. Paint that is known to contain lead levels less than those described above does not have to be evaluated, although all deteriorated paint (paint surfaces in poor condition) should be repaired because it may contain lower levels of lead that may contribute to lead dust or lead contaminated soil hazards.

The "Side" information presented on the XRF data sheets is in relation to the side of the rooms or building exteriors where the unit address is located. The inspector/risk assessor used the address side of each residence as the basis to establish side "A". Sides B, C, and D follow in clockwise rotation.

Please refer to the XRF Sample Data Table located in Tab 1 for a complete list of XRF samples.

2.2.2 Bulk Paint-Chip Sampling

Bulk paint chip verification samples were collected when there was an inconclusive result with the XRF. Inconclusive results were not recorded during the Ballinger Homes inspection.

2.3 Components with Lead-Based Paint

None of the paint tested contained lead above the HUD level of 1.0 mg/cm² by XRF.

2.4 Deteriorated Lead-Based Paint Surfaces

Lead-based paint was not identified at the subject property. Painted surfaces were evaluated to be in an intact condition.

TAB 1

XRF Data Sheets

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------|-----------|------|-----------|-------|-----------------|-------|--------------|----------|-----------------------|----------------|
| 1 | SHUTTER CAL | | | | | BALLINGER HOMES | | | | Positive | 6.53 |
| 2 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 3 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 4 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1.1 |
| 5 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 6 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 7 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 8 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 9 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 10 | DOOR | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 11 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 12 | CLOSET ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 13 | CLOSET DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 133 | Negative | <LOD |
| 14 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 133 | Negative | <LOD |
| 15 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 133 | Negative | <LOD |
| 16 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 133 | Negative | <LOD |
| 17 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 133 | Negative | <LOD |
| 18 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 133 | Negative | <LOD |
| 19 | SLIDING DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 133 | Negative | <LOD |
| 20 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 133 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------|-----------|------|-----------|--------|-----------------|--------|--------------|----------|-----------------------|----------------|
| 21 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 133 | Negative | <LOD |
| 22 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 133 | Negative | <LOD |
| 23 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 133 | Negative | <LOD |
| 24 | STAIR RAIL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIR | UNIT 133 | Negative | <LOD |
| 25 | RISER | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIR | UNIT 133 | Negative | <LOD |
| 26 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIR | UNIT 133 | Negative | <LOD |
| 27 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIR | UNIT 133 | Negative | <LOD |
| 28 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIR | UNIT 133 | Negative | <LOD |
| 29 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 30 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 31 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 32 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 33 | COVEBASE | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 34 | COVEBASE | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 35 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 36 | COVEBASE | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 37 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 38 | WINDOW FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 39 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 40 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------|-----------|------|-----------|-------|--------------------|--------|-----------|----------|-----------------------|----------------|
| 41 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 42 | ROLL DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 133 | Negative | <LOD |
| 43 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 44 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 45 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 46 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 47 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 48 | DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 49 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 50 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 51 | ROLL DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 52 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 53 | COVEBASE | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 54 | COVEBASE | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 55 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 56 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 57 | COVEBASE | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 133 | Negative | <LOD |
| 58 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 133 | Negative | <LOD |
| 59 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 133 | Negative | <LOD |
| 60 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 133 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|--------------|----------|-----------------------|----------------|
| 61 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 133 | Negative | <LOD |
| 62 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 133 | Negative | <LOD |
| 63 | CEILING | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 133 | Negative | <LOD |
| 64 | CEILING | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 133 | Negative | <LOD |
| 65 | CEILING | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 133 | Negative | <LOD |
| 66 | COVEBASE | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 133 | Negative | <LOD |
| 67 | COVEBASE | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 133 | Negative | <LOD |
| 68 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 133 | Negative | <LOD |
| 69 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 133 | Negative | <LOD |
| 70 | DOOR JAM | METAL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 133 | Negative | <LOD |
| 71 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 126 | Negative | <LOD |
| 72 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 126 | Negative | <LOD |
| 73 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 126 | Negative | <LOD |
| 74 | CEILING | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 126 | Negative | <LOD |
| 75 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 126 | Negative | <LOD |
| 76 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 126 | Negative | <LOD |
| 77 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 126 | Negative | <LOD |
| 78 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 126 | Negative | <LOD |
| 79 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 126 | Negative | <LOD |
| 80 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 126 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 81 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 126 | Negative | <LOD |
| 82 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 126 | Negative | <LOD |
| 83 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 126 | Negative | <LOD |
| 84 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 126 | Negative | <LOD |
| 85 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 126 | Negative | <LOD |
| 86 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 126 | Negative | <LOD |
| 87 | ROLL DOOR | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 126 | Negative | <LOD |
| 88 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 126 | Negative | <LOD |
| 89 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 126 | Negative | <LOD |
| 90 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 126 | Negative | <LOD |
| 91 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 126 | Negative | <LOD |
| 92 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 126 | Negative | <LOD |
| 93 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | FIRST | BATHROOM | UNIT 126 | Negative | <LOD |
| 94 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | FIRST | BATHROOM | UNIT 126 | Negative | <LOD |
| 95 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 96 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 97 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 98 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 99 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 100 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------------|-----------|------|-----------|-------|-----------------|-------|-----------|----------|-----------------------|----------------|
| 101 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 102 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 103 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 126 | Negative | <LOD |
| 104 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 126 | Negative | <LOD |
| 105 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 126 | Negative | <LOD |
| 106 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 125 | Negative | <LOD |
| 107 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 125 | Negative | <LOD |
| 108 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 125 | Negative | <LOD |
| 109 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 125 | Negative | <LOD |
| 110 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 125 | Negative | <LOD |
| 111 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 125 | Negative | <LOD |
| 112 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 125 | Negative | <LOD |
| 113 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | UNIT 125 | Negative | <LOD |
| 114 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |
| 115 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |
| 116 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |
| 117 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |
| 118 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |
| 119 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |
| 120 | ROLL DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------|-----------|------|-----------|-------|--------------------|-------|-------------|----------|-----------------------|----------------|
| 121 | ROLL DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 125 | Negative | <LOD |
| 122 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 123 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 124 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 125 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 126 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 127 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 128 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 129 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 125 | Negative | <LOD |
| 130 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 125 | Negative | <LOD |
| 131 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 125 | Negative | <LOD |
| 132 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 125 | Negative | <LOD |
| 133 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 125 | Negative | <LOD |
| 134 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 125 | Negative | <LOD |
| 135 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 125 | Negative | <LOD |
| 136 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 125 | Negative | <LOD |
| 137 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 125 | Negative | <LOD |
| 138 | DOOR | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 125 | Negative | <LOD |
| 139 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 125 | Negative | <LOD |
| 140 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 128 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 141 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 128 | Negative | <LOD |
| 142 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 128 | Negative | <LOD |
| 143 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 128 | Negative | <LOD |
| 144 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 128 | Negative | <LOD |
| 145 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 128 | Negative | <LOD |
| 146 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 128 | Negative | <LOD |
| 147 | WINDOW SILL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 128 | Negative | <LOD |
| 148 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 128 | Negative | <LOD |
| 149 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 128 | Negative | <LOD |
| 150 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 128 | Negative | <LOD |
| 151 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 128 | Negative | <LOD |
| 152 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 128 | Negative | <LOD |
| 153 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 128 | Negative | <LOD |
| 154 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 128 | Negative | <LOD |
| 155 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 128 | Negative | <LOD |
| 156 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 128 | Negative | <LOD |
| 157 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 128 | Negative | <LOD |
| 158 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 128 | Negative | <LOD |
| 159 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |
| 160 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------------|-----------|------|-----------|--------|--------------------|-------|-------------|----------|-----------------------|----------------|
| 161 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |
| 162 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |
| 163 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |
| 164 | DOOR | WOOD | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |
| 165 | DOOR FRAME | WOOD | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |
| 166 | FREE STANDING CABINET | WOOD | | INTACT | YELLOW | BALLINGER HOMES | FIRST | BATHROOM | UNIT 128 | Negative | <LOD |
| 167 | DOOR | METAL | | INTACT | RED | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 128 | Negative | <LOD |
| 168 | DOOR FRAME | METAL | | INTACT | RED | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 128 | Negative | <LOD |
| 169 | DOOR | METAL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 128 | Negative | <LOD |
| 170 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 119 | Negative | <LOD |
| 171 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 119 | Negative | <LOD |
| 172 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 119 | Negative | <LOD |
| 173 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 119 | Negative | <LOD |
| 174 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 119 | Negative | <LOD |
| 175 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 119 | Negative | <LOD |
| 176 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 119 | Negative | <LOD |
| 177 | WINDOW SILL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 119 | Negative | <LOD |
| 178 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 119 | Negative | <LOD |
| 179 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 119 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 180 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 119 | Negative | <LOD |
| 181 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 119 | Negative | <LOD |
| 182 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 119 | Negative | <LOD |
| 183 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 184 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 185 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 186 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 187 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 188 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 189 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 190 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 119 | Negative | <LOD |
| 191 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 192 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 193 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 194 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 195 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 196 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 197 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 198 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |
| 199 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 119 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 200 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 120 | Negative | <LOD |
| 201 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 120 | Negative | <LOD |
| 202 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 120 | Negative | <LOD |
| 203 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 120 | Negative | <LOD |
| 204 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 120 | Negative | <LOD |
| 205 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 120 | Negative | <LOD |
| 206 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 120 | Negative | <LOD |
| 207 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 120 | Negative | <LOD |
| 208 | WINDOW FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 120 | Negative | <LOD |
| 209 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 120 | Negative | <LOD |
| 210 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 120 | Negative | <LOD |
| 211 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 120 | Negative | <LOD |
| 212 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 120 | Negative | <LOD |
| 213 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 120 | Negative | <LOD |
| 214 | CEILING | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |
| 215 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |
| 216 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |
| 217 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |
| 218 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |
| 219 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 220 | DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |
| 221 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 120 | Negative | <LOD |
| 222 | CEILING | DRYWALL | AM | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 223 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 224 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 225 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 226 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 227 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 228 | WINDOW FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 229 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 230 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 120 | Negative | <LOD |
| 231 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 120 | Negative | <LOD |
| 232 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 120 | Negative | <LOD |
| 233 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 121 | Negative | <LOD |
| 234 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 121 | Negative | <LOD |
| 235 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 121 | Negative | <LOD |
| 236 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 121 | Negative | <LOD |
| 237 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 121 | Negative | <LOD |
| 238 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 121 | Negative | <LOD |
| 239 | WINDOW SILL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 121 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 240 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 121 | Negative | <LOD |
| 241 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 121 | Negative | <LOD |
| 242 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 121 | Negative | <LOD |
| 243 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 121 | Negative | <LOD |
| 244 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 121 | Negative | <LOD |
| 245 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 121 | Negative | <LOD |
| 246 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 247 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 248 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 249 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 250 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 251 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 252 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 253 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 254 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 121 | Negative | <LOD |
| 255 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 121 | Negative | <LOD |
| 256 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 121 | Negative | <LOD |
| 257 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 121 | Negative | <LOD |
| 258 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 121 | Negative | <LOD |
| 259 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 121 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 260 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 121 | Negative | <LOD |
| 261 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 121 | Negative | <LOD |
| 262 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 121 | Negative | <LOD |
| 263 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 122 | Negative | <LOD |
| 264 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 122 | Negative | <LOD |
| 265 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 122 | Negative | <LOD |
| 266 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 122 | Negative | <LOD |
| 267 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 122 | Negative | <LOD |
| 268 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 122 | Negative | <LOD |
| 269 | DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 122 | Negative | <LOD |
| 270 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 122 | Negative | <LOD |
| 271 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 122 | Negative | <LOD |
| 272 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 122 | Negative | <LOD |
| 273 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 122 | Negative | <LOD |
| 274 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 122 | Negative | <LOD |
| 275 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 122 | Negative | <LOD |
| 276 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 122 | Negative | <LOD |
| 277 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 122 | Negative | <LOD |
| 278 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 122 | Negative | <LOD |
| 279 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 122 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 280 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 122 | Negative | <LOD |
| 281 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 122 | Negative | <LOD |
| 282 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 122 | Negative | <LOD |
| 283 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 122 | Negative | <LOD |
| 284 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 122 | Negative | <LOD |
| 285 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 122 | Negative | <LOD |
| 286 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 122 | Negative | <LOD |
| 287 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 122 | Negative | <LOD |
| 288 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 122 | Negative | <LOD |
| 289 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 122 | Negative | <LOD |
| 290 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 122 | Negative | <LOD |
| 291 | DOOR FRAME | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 122 | Negative | <LOD |
| 292 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 123 | Negative | <LOD |
| 293 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 123 | Negative | <LOD |
| 294 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 123 | Negative | <LOD |
| 295 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 123 | Negative | <LOD |
| 296 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 123 | Negative | <LOD |
| 297 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 123 | Negative | <LOD |
| 298 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 123 | Negative | <LOD |
| 299 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 123 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 300 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 123 | Negative | <LOD |
| 301 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 123 | Negative | <LOD |
| 302 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 123 | Negative | <LOD |
| 303 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 123 | Negative | <LOD |
| 304 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 123 | Negative | <LOD |
| 305 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 123 | Negative | <LOD |
| 306 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 123 | Negative | <LOD |
| 307 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 123 | Negative | <LOD |
| 308 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 123 | Negative | <LOD |
| 309 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 123 | Negative | <LOD |
| 310 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 123 | Negative | <LOD |
| 311 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM 1 | UNIT 123 | Negative | <LOD |
| 312 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |
| 313 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |
| 314 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |
| 315 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |
| 316 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |
| 317 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |
| 318 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |
| 319 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 123 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|---------------|-----------|------|-----------|-------|-----------------|-------|------------------------------------|----------|-----------------------|----------------|
| 320 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 123 | Negative | <LOD |
| 321 | DOOR FRAME | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 123 | Negative | <LOD |
| 322 | SHINGLES | VINYL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 123 | Negative | <LOD |
| 323 | GAS METER BOX | METAL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 123 | Negative | <LOD |
| 324 | DOOR | METAL | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 123 | Negative | <LOD |
| 325 | SHINGLES | WOOD | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 123 | Negative | <LOD |
| 326 | WALL | DRYWALL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER | UNIT 123 | Negative | <LOD |
| 327 | WALL | DRYWALL | B | INTACT | GREEN | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER | UNIT 123 | Negative | <LOD |
| 328 | WALL | DRYWALL | C | INTACT | GREEN | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER | UNIT 123 | Negative | <LOD |
| 329 | WALL | DRYWALL | D | INTACT | GREEN | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER | UNIT 123 | Negative | <LOD |
| 330 | DOOR | METAL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER | UNIT 123 | Negative | <LOD |
| 331 | DOOR FRAME | METAL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER | UNIT 123 | Negative | <LOD |
| 332 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER WOMENS RV | UNIT 123 | Negative | <LOD |
| 333 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER WOMENS RV | UNIT 123 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------|-----------|------|-----------|--------|--------------------|-------|--|----------|-----------------------|----------------|
| 334 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER WOMENS RV | | Negative | <LOD |
| 335 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER WOMENS RV | | Negative | <LOD |
| 336 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER WOMENS RV | | Negative | <LOD |
| 337 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER MENS RR | | Negative | <LOD |
| 338 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER MENS RR | | Negative | <LOD |
| 339 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER MENS RR | | Negative | <LOD |
| 340 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER MENS RR | | Negative | <LOD |
| 341 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | FAMILY SUPPORT CENTER MENS RR | | Negative | <LOD |
| 342 | POLE | METAL | | INTACT | ORANGE | BALLINGER HOMES | FIRST | PLAYGROUND | | Negative | <LOD |
| 343 | RAILS | METAL | | INTACT | BLUE | BALLINGER HOMES | FIRST | PLAYGROUND | | Negative | <LOD |
| 344 | RAILS | METAL | | INTACT | GREEN | BALLINGER HOMES | FIRST | PLAYGROUND | | Negative | <LOD |
| 345 | DECK | METAL | | INTACT | BROWN | BALLINGER HOMES | FIRST | PLAYGROUND | | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|----------------------|-----------|------|-----------|--------|-----------------|-------|------------|-----------------------|-----------------------|----------------|
| 346 | SQUIRREL | METAL | | INTACT | BROWN | BALLINGER HOMES | FIRST | PLAYGROUND | | Negative | <LOD |
| 347 | HORSE | METAL | | INTACT | YELLOW | BALLINGER HOMES | FIRST | PLAYGROUND | | Negative | <LOD |
| 348 | DECK | METAL | | INTACT | BROWN | BALLINGER HOMES | FIRST | PLAYGROUND | | Negative | <LOD |
| 349 | FOUNDATION | CONCRETE | C | INTACT | BROWN | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 350 | FOUNDATION | CONCRETE | D | INTACT | BROWN | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 351 | GAS METER BOX | METAL | D | INTACT | GRAY | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 352 | ELECTRIC PANEL COVER | METAL | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 353 | DOOR | METAL | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 354 | GARAGE DOOR | WOOD | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 355 | HAND RAILS | WOOD | D | INTACT | BROWN | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 356 | DECK | WOOD | D | INTACT | BROWN | BALLINGER HOMES | FIRST | EXTERIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 357 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LAUNDRY | FAMILY SUPPORT CENTER | Negative | <LOD |
| 358 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LAUNDRY | FAMILY SUPPORT CENTER | Negative | <LOD |
| 359 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LAUNDRY | FAMILY SUPPORT CENTER | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|-------|-----------------------|-----------------------|-----------------------|----------------|
| 360 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LAUNDRY | FAMILY SUPPORT CENTER | Negative | <LOD |
| 361 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LAUNDRY | FAMILY SUPPORT CENTER | Negative | <LOD |
| 362 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LAUNDRY | FAMILY SUPPORT CENTER | Negative | <LOD |
| 363 | WINDOW SILL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LAUNDRY | FAMILY SUPPORT CENTER | Negative | <LOD |
| 364 | WALL | DRYWALL | A | INTACT | GRAY | BALLINGER HOMES | FIRST | TENANT RECEPTION AREA | FAMILY SUPPORT CENTER | Negative | <LOD |
| 365 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | TENANT RECEPTION AREA | FAMILY SUPPORT CENTER | Negative | <LOD |
| 366 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | TENANT RECEPTION AREA | FAMILY SUPPORT CENTER | Negative | <LOD |
| 367 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | TENANT RECEPTION AREA | FAMILY SUPPORT CENTER | Negative | <LOD |
| 368 | WALL | DRYWALL | A | INTACT | GRAY | BALLINGER HOMES | FIRST | FOYER | FAMILY SUPPORT CENTER | Negative | <LOD |
| 369 | WALL | DRYWALL | B | INTACT | GRAY | BALLINGER HOMES | FIRST | FOYER | FAMILY SUPPORT CENTER | Negative | <LOD |
| 370 | WALL | DRYWALL | C | INTACT | GRAY | BALLINGER HOMES | FIRST | FOYER | FAMILY SUPPORT CENTER | Negative | <LOD |
| 371 | WALL | DRYWALL | C | INTACT | GRAY | BALLINGER HOMES | FIRST | FOYER | FAMILY SUPPORT CENTER | Negative | <LOD |
| 372 | WALL | DRYWALL | D | INTACT | GRAY | BALLINGER HOMES | FIRST | FOYER | FAMILY SUPPORT CENTER | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|--------|-----------------|-------|-------------|-----------------------|-----------------------|----------------|
| 373 | DOOR | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | FAMILY SUPPORT CENTER | Negative | <LOD |
| 374 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | FOYER | FAMILY SUPPORT CENTER | Negative | <LOD |
| 375 | HAND RAIL | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTEIOR | FAMILY SUPPORT CENTER | Negative | <LOD |
| 376 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 124 | Negative | <LOD |
| 377 | WALL | DRYWALL | A | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 124 | Negative | <LOD |
| 378 | WALL | DRYWALL | C | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 124 | Negative | <LOD |
| 379 | WALL | DRYWALL | D | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 124 | Negative | <LOD |
| 380 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 124 | Negative | <LOD |
| 381 | WALL | DRYWALL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 124 | Negative | <LOD |
| 382 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 124 | Negative | <LOD |
| 383 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 124 | Negative | <LOD |
| 384 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 124 | Negative | <LOD |
| 385 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 124 | Negative | <LOD |
| 386 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 124 | Negative | <LOD |
| 387 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 124 | Negative | <LOD |
| 388 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |
| 389 | WALL | DRYWALL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |
| 390 | WALL | DRYWALL | B | INTACT | GREEN | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|---------------|-----------|------|-----------|-------|-----------------|-------|------------|----------|-----------------------|----------------|
| 391 | WALL | DRYWALL | C | INTACT | GREEN | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |
| 392 | WALL | DRYWALL | D | INTACT | GREEN | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |
| 393 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |
| 394 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |
| 395 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BED ROOM 1 | UNIT 124 | Negative | <LOD |
| 396 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 397 | WALL | DRYWALL | A | INTACT | TAN | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 398 | WALL | DRYWALL | B | INTACT | TAN | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 399 | WALL | DRYWALL | B | INTACT | TAN | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 400 | WALL | DRYWALL | C | INTACT | TAN | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 401 | WALL | DRYWALL | D | INTACT | TAN | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 402 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 403 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 124 | Negative | <LOD |
| 404 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 124 | Negative | <LOD |
| 405 | DOOR FRAME | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 124 | Negative | <LOD |
| 406 | SHINGLES | WOOD | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 124 | Negative | <LOD |
| 407 | AC UNIT PANEL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 124 | Negative | <LOD |
| 408 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 127 | Negative | <LOD |
| 409 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 127 | Negative | <LOD |
| 410 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 127 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|--------------------|-------|-------------|----------|-----------------------|----------------|
| 411 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 127 | Negative | <LOD |
| 412 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 127 | Negative | <LOD |
| 413 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 127 | Negative | <LOD |
| 414 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 127 | Negative | <LOD |
| 415 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 127 | Negative | <LOD |
| 416 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 127 | Negative | <LOD |
| 417 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 127 | Negative | <LOD |
| 418 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 127 | Negative | <LOD |
| 419 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 420 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 421 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 422 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 423 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 424 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 425 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 426 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BEDROOM | UNIT 127 | Negative | <LOD |
| 427 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 127 | Negative | <LOD |
| 428 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 127 | Negative | <LOD |
| 429 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 127 | Negative | <LOD |
| 430 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 127 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|---------------|-----------|------|-----------|-------|-----------------|-------|-------------|----------|-----------------------|----------------|
| 431 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 127 | Negative | <LOD |
| 432 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 127 | Negative | <LOD |
| 433 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | BATHROOM | UNIT 127 | Negative | <LOD |
| 434 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 127 | Negative | <LOD |
| 435 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 127 | Negative | <LOD |
| 436 | SHUTTER CAL | | | | | | | | | | 5.81 |
| 437 | SHUTTER CAL | | | | | | | | | | 6.06 |
| 438 | NIST STANDARD | | | INTACT | RED | BALLINGER HOMES | | | | Positive | 1 |
| 439 | NIST STANDARD | | | INTACT | RED | BALLINGER HOMES | | | | Positive | 1 |
| 440 | NIST STANDARD | | | INTACT | RED | BALLINGER HOMES | | | | Negative | 0.9 |
| 441 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 442 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 443 | DOOR | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 444 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 445 | ROLL DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 446 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 447 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 448 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 115 | Negative | <LOD |
| 449 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 115 | Negative | <LOD |
| 450 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 115 | Negative | <LOD |
| 451 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 115 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 452 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 115 | Negative | <LOD |
| 453 | WINDOW FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 115 | Negative | <LOD |
| 454 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 115 | Negative | <LOD |
| 455 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 115 | Negative | <LOD |
| 456 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 115 | Negative | <LOD |
| 457 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 115 | Negative | <LOD |
| 458 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 115 | Negative | <LOD |
| 459 | SLIDING GLASS DOOR FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 115 | Negative | <LOD |
| 460 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 115 | Negative | <LOD |
| 461 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 115 | Negative | <LOD |
| 462 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 115 | Negative | <LOD |
| 463 | RISER | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 115 | Negative | <LOD |
| 464 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |
| 465 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |
| 466 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |
| 467 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |
| 468 | COVEBASE | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |
| 469 | COVEBASE | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |
| 470 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|--------------------|--------|-----------|----------|-----------------------|----------------|
| 471 | COVEBASE | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 115 | Negative | <LOD |
| 472 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 115 | Negative | <LOD |
| 473 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 115 | Negative | <LOD |
| 474 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 115 | Negative | <LOD |
| 475 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 115 | Negative | <LOD |
| 476 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 115 | Negative | <LOD |
| 477 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 115 | Negative | <LOD |
| 478 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 115 | Negative | <LOD |
| 479 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 480 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 481 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 482 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 483 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 484 | ROLL DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 485 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 486 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 115 | Negative | <LOD |
| 487 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 488 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 489 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 490 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------------|-----------|------|-----------|-------|--------------------|--------|-------------|----------|-----------------------|----------------|
| 491 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 492 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 493 | WINDOW FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 494 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 495 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 115 | Negative | <LOD |
| 496 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 115 | Negative | <LOD |
| 497 | DOOR FRAME | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 115 | Negative | <LOD |
| 498 | FENCE | WOOD | C | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 115 | Negative | <LOD |
| 499 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 113 | Negative | <LOD |
| 500 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 113 | Negative | <LOD |
| 501 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 113 | Negative | <LOD |
| 502 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 113 | Negative | <LOD |
| 503 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 113 | Negative | <LOD |
| 504 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 113 | Negative | <LOD |
| 505 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 113 | Negative | <LOD |
| 506 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 113 | Negative | <LOD |
| 507 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 113 | Negative | <LOD |
| 508 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 113 | Negative | <LOD |
| 509 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 113 | Negative | <LOD |
| 510 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 113 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 511 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 113 | Negative | <LOD |
| 512 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 113 | Negative | <LOD |
| 513 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 113 | Negative | <LOD |
| 514 | RISER | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 113 | Negative | <LOD |
| 515 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 113 | Negative | <LOD |
| 516 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 113 | Negative | <LOD |
| 517 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 113 | Negative | <LOD |
| 518 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 113 | Negative | <LOD |
| 519 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 113 | Negative | <LOD |
| 520 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 113 | Negative | <LOD |
| 521 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 113 | Negative | <LOD |
| 522 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 113 | Negative | <LOD |
| 523 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 113 | Negative | <LOD |
| 524 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 113 | Negative | <LOD |
| 525 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 113 | Negative | <LOD |
| 526 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |
| 527 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |
| 528 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |
| 529 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |
| 530 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 531 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |
| 532 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |
| 533 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 113 | Negative | <LOD |
| 534 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 535 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 536 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 537 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 538 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 539 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 540 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 541 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 113 | Negative | <LOD |
| 542 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 113 | Negative | <LOD |
| 543 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 113 | Negative | <LOD |
| 544 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 118 | Negative | <LOD |
| 545 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 118 | Negative | <LOD |
| 546 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 118 | Negative | <LOD |
| 547 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 118 | Negative | <LOD |
| 548 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 118 | Negative | <LOD |
| 549 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 118 | Negative | <LOD |
| 550 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 118 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 551 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 118 | Negative | <LOD |
| 552 | WINDOW SILL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 118 | Negative | <LOD |
| 553 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 118 | Negative | <LOD |
| 554 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 118 | Negative | <LOD |
| 555 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 118 | Negative | <LOD |
| 556 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 118 | Negative | <LOD |
| 557 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 118 | Negative | <LOD |
| 558 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 118 | Negative | <LOD |
| 559 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 118 | Negative | <LOD |
| 560 | HANDRAIL | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 118 | Negative | <LOD |
| 561 | RISER | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 118 | Negative | <LOD |
| 562 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 118 | Negative | <LOD |
| 563 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 118 | Negative | <LOD |
| 564 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 118 | Negative | <LOD |
| 565 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 118 | Negative | <LOD |
| 566 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 118 | Negative | <LOD |
| 567 | COVEBASE | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 118 | Negative | <LOD |
| 568 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 118 | Negative | <LOD |
| 569 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 118 | Negative | <LOD |
| 570 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 118 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 571 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 118 | Negative | <LOD |
| 572 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 118 | Negative | <LOD |
| 573 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 118 | Negative | <LOD |
| 574 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 118 | Negative | <LOD |
| 575 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 576 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 577 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 578 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 579 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 580 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 581 | DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 582 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 118 | Negative | <LOD |
| 583 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 118 | Negative | <LOD |
| 584 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 118 | Negative | <LOD |
| 585 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 118 | Negative | <LOD |
| 586 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 118 | Negative | <LOD |
| 587 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 118 | Negative | <LOD |
| 588 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 118 | Negative | <LOD |
| 589 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 118 | Negative | <LOD |
| 590 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|--------------------|--------|-------------|----------|-----------------------|----------------|
| 591 | DOOR FRAME | METAL | A | INTACT | GREEN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |
| 592 | DOOR | METAL | D | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |
| 593 | SHINGLES | VINYL | A | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |
| 594 | SHINGLES | VINYL | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |
| 595 | SHINGLES | VINYL | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |
| 596 | SHINGLES | VINYL | C | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |
| 597 | SHINGLES | VINYL | D | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 118 | Negative | <LOD |
| 598 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 112 | Negative | <LOD |
| 599 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 112 | Negative | <LOD |
| 600 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 112 | Negative | <LOD |
| 601 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 112 | Negative | <LOD |
| 602 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 112 | Negative | <LOD |
| 603 | DOOR FRAME | WOOD | A | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 112 | Negative | <LOD |
| 604 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 112 | Negative | <LOD |
| 605 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 112 | Negative | <LOD |
| 606 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 112 | Negative | <LOD |
| 607 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 112 | Negative | <LOD |
| 608 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 112 | Negative | <LOD |
| 609 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 112 | Negative | <LOD |
| 610 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 112 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 611 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 112 | Negative | <LOD |
| 612 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 112 | Negative | <LOD |
| 613 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 112 | Negative | <LOD |
| 614 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 112 | Negative | <LOD |
| 615 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 112 | Negative | <LOD |
| 616 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 112 | Negative | <LOD |
| 617 | RISER | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 112 | Negative | <LOD |
| 618 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 619 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 620 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 621 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 622 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 623 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 624 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 625 | COVEBASE | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 626 | COVEBASE | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 112 | Negative | <LOD |
| 627 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 628 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 629 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 630 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 631 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 632 | WINDOW SILL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 633 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 634 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 635 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 636 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 637 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 638 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 639 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 640 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 641 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 112 | Negative | <LOD |
| 642 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 112 | Negative | <LOD |
| 643 | DOOR FRAME | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 112 | Negative | <LOD |
| 644 | DOOR | METAL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 112 | Negative | <LOD |
| 645 | SHINGLES | VINYL | C | INTACT | TAN | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 112 | Negative | <LOD |
| 646 | SHINGLES | VINYL | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 112 | Negative | <LOD |
| 647 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 104 | Negative | <LOD |
| 648 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 104 | Negative | <LOD |
| 649 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 104 | Negative | <LOD |
| 650 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 104 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|--------------|----------|-----------------------|----------------|
| 651 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 104 | Negative | <LOD |
| 652 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 104 | Negative | <LOD |
| 653 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 104 | Negative | <LOD |
| 654 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 104 | Negative | <LOD |
| 655 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINNING ROOM | UNIT 104 | Negative | <LOD |
| 656 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 104 | Negative | <LOD |
| 657 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 104 | Negative | <LOD |
| 658 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 104 | Negative | <LOD |
| 659 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 104 | Negative | <LOD |
| 660 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 104 | Negative | <LOD |
| 661 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 104 | Negative | <LOD |
| 662 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 104 | Negative | <LOD |
| 663 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 104 | Negative | <LOD |
| 664 | HANDRAIL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 104 | Negative | <LOD |
| 665 | RISER | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 104 | Negative | <LOD |
| 666 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 667 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 668 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 669 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 670 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------------|-----------|------|-----------|-------|--------------------|--------|-----------|----------|-----------------------|----------------|
| 671 | COVEBASE | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 672 | COVEBASE | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 673 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 674 | COVEBASE | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 104 | Negative | <LOD |
| 675 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 104 | Negative | <LOD |
| 676 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 104 | Negative | <LOD |
| 677 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 104 | Negative | <LOD |
| 678 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 104 | Negative | <LOD |
| 679 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 104 | Negative | <LOD |
| 680 | DOOR | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 104 | Negative | <LOD |
| 681 | DOOR FRAME | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 104 | Negative | <LOD |
| 682 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 683 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 684 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 685 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 686 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 687 | PIPE CHASE DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 688 | PIPE CHASE DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 689 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 690 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------------|-----------|------|-----------|--------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 691 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 692 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 104 | Negative | <LOD |
| 693 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | 0.2 |
| 694 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | <LOD |
| 695 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | 0.12 |
| 696 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | <LOD |
| 697 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | <LOD |
| 698 | CLOSET ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | <LOD |
| 699 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | <LOD |
| 700 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | <LOD |
| 701 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 104 | Negative | <LOD |
| 702 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 104 | Negative | <LOD |
| 703 | DOOR FRAME | METAL | A | INTACT | RED | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 104 | Negative | <LOD |
| 704 | FENCING | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 104 | Negative | <LOD |
| 705 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 104 | Negative | <LOD |
| 706 | SHINGLES | VINYL | C | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 104 | Negative | <LOD |
| 707 | SHINGLES | VINYL | D | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 104 | Negative | <LOD |
| 708 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 101 | Negative | <LOD |
| 709 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | FIRST | KITCHEN | UNIT 101 | Negative | <LOD |
| 710 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | FIRST | KITCHEN | UNIT 101 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|--------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 711 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | FIRST | KITCHEN | UNIT 101 | Negative | <LOD |
| 712 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 101 | Negative | <LOD |
| 713 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 101 | Negative | <LOD |
| 714 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 101 | Negative | <LOD |
| 715 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 101 | Negative | <LOD |
| 716 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 101 | Negative | <LOD |
| 717 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 718 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 719 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 720 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 721 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 722 | WINDOW SILL | WOOD | A | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 723 | DOOR | METAL | A | INTACT | YELLOW | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 724 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 101 | Negative | <LOD |
| 725 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | FIRST | STAIRWRL | UNIT 101 | Negative | <LOD |
| 726 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | FIRST | STAIRWRL | UNIT 101 | Negative | <LOD |
| 727 | HANDRAIL | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWRL | UNIT 101 | Negative | <LOD |
| 728 | RISER | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWRL | UNIT 101 | Negative | <LOD |
| 729 | CEILING | DRYWALL | | INTACT | YELLOW | BALLINGER HOMES | SECOND | HALL | UNIT 101 | Negative | <LOD |
| 730 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | SECOND | HALL | UNIT 101 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------|-----------|------|-----------|--------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 731 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | SECOND | HALL | UNIT 101 | Negative | <LOD |
| 732 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | SECOND | HALL | UNIT 101 | Negative | 0.7 |
| 733 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | SECOND | HALL | UNIT 101 | Negative | <LOD |
| 734 | CEILING | DRYWALL | | INTACT | YELLOW | BALLINGER HOMES | SECOND | BATHROOM | UNIT 101 | Negative | <LOD |
| 735 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | SECOND | BATHROOM | UNIT 101 | Negative | <LOD |
| 736 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | SECOND | BATHROOM | UNIT 101 | Negative | <LOD |
| 737 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | SECOND | BATHROOM | UNIT 101 | Negative | <LOD |
| 738 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | SECOND | BATHROOM | UNIT 101 | Negative | <LOD |
| 739 | DOOR | WOOD | D | INTACT | YELLOW | BALLINGER HOMES | SECOND | BATHROOM | UNIT 101 | Negative | <LOD |
| 740 | DOOR FRAME | WOOD | D | INTACT | YELLOW | BALLINGER HOMES | SECOND | BATHROOM | UNIT 101 | Negative | <LOD |
| 741 | CEILING | DRYWALL | | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 742 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 743 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 744 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 745 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 746 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 747 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 748 | WINGOW FRAME | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 101 | Negative | <LOD |
| 749 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 750 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------------------|-----------|------|-----------|--------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 751 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 752 | WALL | DRYWALL | C | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 753 | WALL | DRYWALL | D | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 754 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 755 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 756 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 757 | WINDOW SILL | WOOD | C | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 758 | PIPE CHASE DOOR | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 759 | PIPE CHASE DOOR FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 101 | Negative | <LOD |
| 760 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 101 | Negative | <LOD |
| 761 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 101 | Negative | <LOD |
| 762 | SHINGLES | WOOD | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 101 | Negative | <LOD |
| 763 | SHINGLES | WOOD | C | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 101 | Negative | <LOD |
| 764 | SHUTTER CAL | | | | | | | | | | 5.84 |
| 765 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 766 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 767 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 768 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 159 | Negative | <LOD |
| 769 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 159 | Negative | <LOD |
| 770 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 159 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 771 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 159 | Negative | <LOD |
| 772 | DOOR | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 159 | Negative | <LOD |
| 773 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 159 | Negative | <LOD |
| 774 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 159 | Negative | <LOD |
| 775 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 159 | Negative | <LOD |
| 776 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 159 | Negative | <LOD |
| 777 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 159 | Negative | <LOD |
| 778 | WINDOW FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 159 | Negative | <LOD |
| 779 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 159 | Negative | <LOD |
| 780 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 159 | Negative | <LOD |
| 781 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 159 | Negative | <LOD |
| 782 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 159 | Negative | <LOD |
| 783 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 159 | Negative | <LOD |
| 784 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 159 | Negative | <LOD |
| 785 | SLIDING DOOR FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 159 | Negative | <LOD |
| 786 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 159 | Negative | <LOD |
| 787 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 159 | Negative | <LOD |
| 788 | HANDRAIL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 159 | Negative | <LOD |
| 789 | RISER | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 159 | Negative | <LOD |
| 790 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 159 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 791 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 159 | Negative | <LOD |
| 792 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 159 | Negative | <LOD |
| 793 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 159 | Negative | <LOD |
| 794 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 159 | Negative | <LOD |
| 795 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 159 | Negative | <LOD |
| 796 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 159 | Negative | <LOD |
| 797 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 159 | Negative | <LOD |
| 798 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 159 | Negative | <LOD |
| 799 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 159 | Negative | <LOD |
| 800 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 159 | Negative | <LOD |
| 801 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 159 | Negative | <LOD |
| 802 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 803 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 804 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 805 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 806 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 807 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 808 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 809 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 159 | Negative | <LOD |
| 810 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 811 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 812 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 813 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 814 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 815 | DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 816 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 817 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 818 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 159 | Negative | <LOD |
| 819 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 159 | Negative | <LOD |
| 820 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 159 | Negative | <LOD |
| 821 | DOOR | METAL | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 159 | Negative | <LOD |
| 822 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 159 | Negative | <LOD |
| 823 | DOOR FRAME | METAL | A | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 159 | Negative | <LOD |
| 824 | SHINGLES | VINYL | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 159 | Negative | <LOD |
| 825 | SHINGLES | VINYL | C | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 159 | Negative | <LOD |
| 826 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 163 | Negative | <LOD |
| 827 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 163 | Negative | <LOD |
| 828 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 163 | Negative | <LOD |
| 829 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 163 | Negative | <LOD |
| 830 | DOOR | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 163 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 831 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 163 | Negative | <LOD |
| 832 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 163 | Negative | <LOD |
| 833 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 163 | Negative | <LOD |
| 834 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 163 | Negative | <LOD |
| 835 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 163 | Negative | <LOD |
| 836 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 163 | Negative | <LOD |
| 837 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 163 | Negative | <LOD |
| 838 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 163 | Negative | <LOD |
| 839 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 163 | Negative | <LOD |
| 840 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 163 | Negative | <LOD |
| 841 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 163 | Negative | <LOD |
| 842 | SLIDING DOOR FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 163 | Negative | <LOD |
| 843 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 163 | Negative | <LOD |
| 844 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 163 | Negative | <LOD |
| 845 | HANDRAIL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 163 | Negative | <LOD |
| 846 | RISER | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 163 | Negative | <LOD |
| 847 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 848 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 849 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 850 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 851 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 852 | COVEBASE | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 853 | COVEBASE | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 854 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 855 | COVEBASE | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 163 | Negative | <LOD |
| 856 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 163 | Negative | <LOD |
| 857 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 163 | Negative | <LOD |
| 858 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 163 | Negative | <LOD |
| 859 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 163 | Negative | <LOD |
| 860 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 163 | Negative | <LOD |
| 861 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 163 | Negative | <LOD |
| 862 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 163 | Negative | <LOD |
| 863 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |
| 864 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |
| 865 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |
| 866 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |
| 867 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |
| 868 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |
| 869 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |
| 870 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 163 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|--------------------|--------|-------------|----------|-----------------------|----------------|
| 871 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 872 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 873 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 874 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 875 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 876 | DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 877 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 878 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 163 | Negative | <LOD |
| 879 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 163 | Negative | <LOD |
| 880 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 163 | Negative | <LOD |
| 881 | SHINGLES | VINYL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 163 | Negative | <LOD |
| 882 | SHINGLES | VINYL | C | INTACT | TAN | BALLINGER HOMES | FIRST | EXTEIOR | UNIT 163 | Negative | <LOD |
| 883 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 166 | Negative | <LOD |
| 884 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 166 | Negative | <LOD |
| 885 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 166 | Negative | <LOD |
| 886 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 166 | Negative | <LOD |
| 887 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 166 | Negative | <LOD |
| 888 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 166 | Negative | <LOD |
| 889 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 166 | Negative | <LOD |
| 890 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 166 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 891 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 166 | Negative | <LOD |
| 892 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 166 | Negative | <LOD |
| 893 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 166 | Negative | <LOD |
| 894 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 166 | Negative | <LOD |
| 895 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 166 | Negative | <LOD |
| 896 | SLIDING DOOR FRAME | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 166 | Negative | <LOD |
| 897 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 166 | Negative | <LOD |
| 898 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 166 | Negative | <LOD |
| 899 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 166 | Negative | <LOD |
| 900 | RISER | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 166 | Negative | <LOD |
| 901 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 902 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 903 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 904 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 905 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 906 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 907 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 908 | COVEBASE | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 909 | COVEBASE | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 166 | Negative | <LOD |
| 910 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 166 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------------------|-----------|------|-----------|-------|--------------------|--------|-----------|----------|-----------------------|----------------|
| 911 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 166 | Negative | <LOD |
| 912 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 166 | Negative | <LOD |
| 913 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 166 | Negative | <LOD |
| 914 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 166 | Negative | <LOD |
| 915 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 166 | Negative | <LOD |
| 916 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 166 | Negative | <LOD |
| 917 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 918 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 919 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 920 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 921 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 922 | PIPE CHASE DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 923 | PIPE CHASE DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 924 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 925 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 926 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 166 | Negative | <LOD |
| 927 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |
| 928 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |
| 929 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |
| 930 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 931 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |
| 932 | DOOR | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |
| 933 | DOOR FRAME | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |
| 934 | DOOR FRAME | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 166 | Negative | <LOD |
| 935 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 166 | Negative | <LOD |
| 936 | DOOR FRAME | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 166 | Negative | <LOD |
| 937 | FOUNDATION | CONCRETE | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 166 | Negative | <LOD |
| 938 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 162 | Negative | <LOD |
| 939 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 162 | Negative | <LOD |
| 940 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 162 | Negative | <LOD |
| 941 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 162 | Negative | <LOD |
| 942 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 162 | Negative | <LOD |
| 943 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 162 | Negative | <LOD |
| 944 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 162 | Negative | <LOD |
| 945 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 162 | Negative | <LOD |
| 946 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 162 | Negative | <LOD |
| 947 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 162 | Negative | <LOD |
| 948 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 162 | Negative | <LOD |
| 949 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 162 | Negative | <LOD |
| 950 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 162 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 951 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 162 | Negative | <LOD |
| 952 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 162 | Negative | <LOD |
| 953 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 162 | Negative | <LOD |
| 954 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 162 | Negative | <LOD |
| 955 | RISER | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 162 | Negative | <LOD |
| 956 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 162 | Negative | <LOD |
| 957 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 162 | Negative | <LOD |
| 958 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 162 | Negative | <LOD |
| 959 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 162 | Negative | <LOD |
| 960 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 162 | Negative | <LOD |
| 961 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 162 | Negative | <LOD |
| 962 | COVEBASE | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 162 | Negative | <LOD |
| 963 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 162 | Negative | <LOD |
| 964 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 162 | Negative | <LOD |
| 965 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 162 | Negative | <LOD |
| 966 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 162 | Negative | <LOD |
| 967 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 162 | Negative | <LOD |
| 968 | DOOR | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 162 | Negative | <LOD |
| 969 | DOOR FRAME | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 162 | Negative | <LOD |
| 970 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 971 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |
| 972 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |
| 973 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |
| 974 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |
| 975 | DOOR | DRYWALL | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |
| 976 | DOOR FRAME | DRYWALL | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |
| 977 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 162 | Negative | <LOD |
| 978 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 162 | Negative | <LOD |
| 979 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 162 | Negative | <LOD |
| 980 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 162 | Negative | <LOD |
| 981 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 162 | Negative | <LOD |
| 982 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 162 | Negative | <LOD |
| 983 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 162 | Negative | <LOD |
| 984 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 162 | Negative | <LOD |
| 985 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 162 | Negative | <LOD |
| 986 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 162 | Negative | <LOD |
| 987 | DOOR | METAL | A | INTACT | BEIGE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 162 | Negative | <LOD |
| 988 | DOOR | METAL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 162 | Negative | <LOD |
| 989 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 167 | Negative | <LOD |
| 990 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 167 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 991 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 167 | Negative | <LOD |
| 992 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 167 | Negative | <LOD |
| 993 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 167 | Negative | <LOD |
| 994 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 167 | Negative | <LOD |
| 995 | ROLL DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 167 | Negative | <LOD |
| 996 | CEILING | DRYWALL | BM | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 167 | Negative | <LOD |
| 997 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 167 | Negative | <LOD |
| 998 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 167 | Negative | <LOD |
| 999 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 167 | Negative | <LOD |
| 1000 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 167 | Negative | <LOD |
| 1001 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 167 | Negative | <LOD |
| 1002 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 167 | Negative | <LOD |
| 1003 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 167 | Negative | <LOD |
| 1004 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 167 | Negative | <LOD |
| 1005 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 167 | Negative | <LOD |
| 1006 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 167 | Negative | <LOD |
| 1007 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 167 | Negative | <LOD |
| 1008 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 167 | Negative | <LOD |
| 1009 | RISER | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 167 | Negative | <LOD |
| 1010 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1011 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1012 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1013 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1014 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1015 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1016 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1017 | COVEBASE | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1018 | COVEBASE | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 167 | Negative | <LOD |
| 1019 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1020 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1021 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1022 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1023 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1024 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1025 | DOOR | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1026 | DOOR FRAME | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 167 | Negative | <LOD |
| 1027 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |
| 1028 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |
| 1029 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |
| 1030 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1031 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |
| 1032 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |
| 1033 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |
| 1034 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 167 | Negative | <LOD |
| 1035 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1036 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1037 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1038 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1039 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1040 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1041 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1042 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 167 | Negative | <LOD |
| 1043 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 167 | Negative | <LOD |
| 1044 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 167 | Negative | <LOD |
| 1045 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 167 | Negative | <LOD |
| 1046 | DOOR | METAL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 167 | Negative | <LOD |
| 1047 | CEILING | DRYWALL | | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 177 | Negative | <LOD |
| 1048 | WALL | DRYWALL | A | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 177 | Negative | <LOD |
| 1049 | WALL | DRYWALL | B | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 177 | Negative | <LOD |
| 1050 | WALL | DRYWALL | D | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 177 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 1051 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 177 | Negative | <LOD |
| 1052 | CEILING | DRYWALL | | INTACT | TAN | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 177 | Negative | <LOD |
| 1053 | WALL | DRYWALL | C | INTACT | TAN | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 177 | Negative | <LOD |
| 1054 | WALL | DRYWALL | D | INTACT | TAN | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 177 | Negative | <LOD |
| 1055 | WINDOW SILL | WOOD | D | INTACT | TAN | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 177 | Negative | <LOD |
| 1056 | CEILING | DRYWALL | | INTACT | TAN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 177 | Negative | <LOD |
| 1057 | WALL | DRYWALL | A | INTACT | TAN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 177 | Negative | <LOD |
| 1058 | WALL | DRYWALL | B | INTACT | TAN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 177 | Negative | <LOD |
| 1059 | WALL | DRYWALL | C | INTACT | TAN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 177 | Negative | <LOD |
| 1060 | WALL | DRYWALL | D | INTACT | TAN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 177 | Negative | <LOD |
| 1061 | WALL | DRYWALL | A | INTACT | TAN | BALLINGER HOMES | FIRST | STAIRS | UNIT 177 | Negative | <LOD |
| 1062 | WALL | DRYWALL | C | INTACT | TAN | BALLINGER HOMES | FIRST | STAIRS | UNIT 177 | Negative | <LOD |
| 1063 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRS | UNIT 177 | Negative | <LOD |
| 1064 | RISER | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRS | UNIT 177 | Negative | <LOD |
| 1065 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1066 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1067 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1068 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1069 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1070 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1071 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1072 | COVEBASE | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1073 | COVEBASE | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 177 | Negative | <LOD |
| 1074 | CEILING | DRYWALL | | INTACT | TAN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 177 | Negative | <LOD |
| 1075 | WALL | DRYWALL | A | INTACT | TAN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 177 | Negative | <LOD |
| 1076 | WALL | DRYWALL | B | INTACT | TAN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 177 | Negative | <LOD |
| 1077 | WALL | DRYWALL | C | INTACT | TAN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 177 | Negative | <LOD |
| 1078 | WALL | DRYWALL | D | INTACT | TAN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 177 | Negative | <LOD |
| 1079 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 177 | Negative | <LOD |
| 1080 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 177 | Negative | <LOD |
| 1081 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1082 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1083 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1084 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1085 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1086 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1087 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1088 | WINDOW SILL | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 177 | Negative | <LOD |
| 1089 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |
| 1090 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|---------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1091 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |
| 1092 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |
| 1093 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |
| 1094 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |
| 1095 | DOOR | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |
| 1096 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 177 | Negative | <LOD |
| 1097 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 177 | Negative | <LOD |
| 1098 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 177 | Negative | <LOD |
| 1099 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 177 | Negative | <LOD |
| 1100 | DOOR | METAL | B | INTACT | TAN | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 177 | Negative | <LOD |
| 1101 | SHUTTER CAL | | | | | BALLINGER HOMES | | | | | 6.68 |
| 1102 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 1103 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 1104 | NIST STANDARD | | | | RED | BALLINGER HOMES | | | | Positive | 1 |
| 1105 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 103 | Negative | <LOD |
| 1106 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 103 | Negative | <LOD |
| 1107 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 103 | Negative | <LOD |
| 1108 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 103 | Negative | <LOD |
| 1109 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 103 | Negative | <LOD |
| 1110 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | KITCHEN | UNIT 103 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 1111 | ROLL DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 103 | Negative | <LOD |
| 1112 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 103 | Negative | <LOD |
| 1113 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 103 | Negative | <LOD |
| 1114 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 103 | Negative | <LOD |
| 1115 | WINDOW FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 103 | Negative | <LOD |
| 1116 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 103 | Negative | <LOD |
| 1117 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 103 | Negative | <LOD |
| 1118 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 103 | Negative | <LOD |
| 1119 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 103 | Negative | <LOD |
| 1120 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 103 | Negative | <LOD |
| 1121 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 103 | Negative | <LOD |
| 1122 | DOOR FRAME | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 103 | Negative | <LOD |
| 1123 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 103 | Negative | <LOD |
| 1124 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 103 | Negative | <LOD |
| 1125 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 103 | Negative | <LOD |
| 1126 | RISER | WOOD | C | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 103 | Negative | <LOD |
| 1127 | CEILING | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1128 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1129 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1130 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1131 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1132 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1133 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1134 | COVEBASE | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1135 | COVEBASE | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | HALL | UNIT 103 | Negative | <LOD |
| 1136 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 103 | Negative | <LOD |
| 1137 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 103 | Negative | <LOD |
| 1138 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 103 | Negative | <LOD |
| 1139 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 103 | Negative | <LOD |
| 1140 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 103 | Negative | <LOD |
| 1141 | DOOR | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 103 | Negative | <LOD |
| 1142 | DOOR FRAME | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BATHROOM | UNIT 103 | Negative | <LOD |
| 1143 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1144 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1145 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1146 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1147 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1148 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1149 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1150 | DOOR | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1151 | DOOR FRAME | WOOD | D | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 103 | Negative | <LOD |
| 1152 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1153 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1154 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1155 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1156 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1157 | ROLL DOOR | WOOD | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1158 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1159 | DOOR | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1160 | DOOR FRAME | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 103 | Negative | <LOD |
| 1161 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1162 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1163 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1164 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1165 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1166 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1167 | DOOR | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1168 | DOOR FRAME | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 103 | Negative | <LOD |
| 1169 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 103 | Negative | <LOD |
| 1170 | DOOR FRAME | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 103 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|--------------|-----------|------|-----------|-------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 1171 | DOOR | METAL | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 103 | Negative | <LOD |
| 1172 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 103 | Negative | <LOD |
| 1173 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 102 | Negative | <LOD |
| 1174 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 102 | Negative | <LOD |
| 1175 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 102 | Negative | <LOD |
| 1176 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 102 | Negative | <LOD |
| 1177 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 102 | Negative | <LOD |
| 1178 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 102 | Negative | <LOD |
| 1179 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 102 | Negative | <LOD |
| 1180 | WINDOW FRAME | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 102 | Negative | <LOD |
| 1181 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 102 | Negative | <LOD |
| 1182 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 102 | Negative | <LOD |
| 1183 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 102 | Negative | <LOD |
| 1184 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 102 | Negative | <LOD |
| 1185 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 102 | Negative | <LOD |
| 1186 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 102 | Negative | <LOD |
| 1187 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 102 | Negative | <LOD |
| 1188 | HANDRAIL | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 102 | Negative | <LOD |
| 1189 | RISER | WOOD | A | INTACT | BROWN | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 102 | Negative | <LOD |
| 1190 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1191 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1192 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1193 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1194 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1195 | COVEBASE | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1196 | COVEBASE | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1197 | COVEBASE | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1198 | COVEBASE | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | HALL | UNIT 102 | Negative | <LOD |
| 1199 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 102 | Negative | <LOD |
| 1200 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 102 | Negative | <LOD |
| 1201 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 102 | Negative | <LOD |
| 1202 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 102 | Negative | <LOD |
| 1203 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 102 | Negative | <LOD |
| 1204 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 102 | Negative | <LOD |
| 1205 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 102 | Negative | <LOD |
| 1206 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1207 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1208 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1209 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1210 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1211 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1212 | ROLL DOOR | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1213 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1214 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 102 | Negative | <LOD |
| 1215 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1216 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1217 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1218 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1219 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1220 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1221 | DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1222 | DOOR FRAME | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1223 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 102 | Negative | <LOD |
| 1224 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1225 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1226 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1227 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1228 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1229 | ROLL DOOR | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1230 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|--------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 1231 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1232 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1233 | COVEBASE | WOOD | A | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1234 | COVEBASE | WOOD | B | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1235 | COVEBASE | WOOD | C | INTACT | BROWN | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 102 | Negative | <LOD |
| 1236 | DOOR | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1237 | DOOR FRAME | METAL | A | INTACT | RED | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1238 | DOOR | METAL | D | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1239 | SHINGLES | VINYL | A | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1240 | SHINGLES | VINYL | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1241 | SHINGLES | VINYL | C | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1242 | SHINGLES | VINYL | D | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1243 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 202 | Negative | <LOD |
| 1244 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | FIRST | KITCHEN | UNIT 202 | Negative | <LOD |
| 1245 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | FIRST | KITCHEN | UNIT 202 | Negative | <LOD |
| 1246 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 202 | Negative | <LOD |
| 1247 | DOOR | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 202 | Negative | <LOD |
| 1248 | ROLL DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | FIRST | KITCHEN | UNIT 202 | Negative | <LOD |
| 1249 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 202 | Negative | <LOD |
| 1250 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 202 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|--------|-----------------|--------|-------------|----------|-----------------------|----------------|
| 1251 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 202 | Negative | <LOD |
| 1252 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | FIRST | DINING ROOM | UNIT 202 | Negative | <LOD |
| 1253 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 202 | Negative | <LOD |
| 1254 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 202 | Negative | <LOD |
| 1255 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 202 | Negative | <LOD |
| 1256 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 202 | Negative | <LOD |
| 1257 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | FIRST | LIVING ROOM | UNIT 202 | Negative | <LOD |
| 1258 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1259 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1260 | HANDRAIL | WOOD | A | PEELING | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1261 | RISER | WOOD | C | PEELING | WHITE | BALLINGER HOMES | FIRST | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1262 | CEILING | DRYWALL | | PEELING | WHITE | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1263 | WALL | DRYWALL | A | PEELING | YELLOW | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1264 | WALL | DRYWALL | B | PEELING | YELLOW | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1265 | WALL | DRYWALL | C | PEELING | YELLOW | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1266 | WALL | DRYWALL | C | PEELING | YELLOW | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1267 | WALL | DRYWALL | D | PEELING | YELLOW | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1268 | COVEBASE | WOOD | A | PEELING | WHITE | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1269 | COVEBASE | WOOD | B | PEELING | WHITE | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1270 | COVEBASE | WOOD | C | PEELING | WHITE | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|--------|-----------------|--------|-----------|----------|-----------------------|----------------|
| 1271 | COVEBASE | WOOD | D | PEELING | WHITE | BALLINGER HOMES | SECOND | STAIRWELL | UNIT 202 | Negative | <LOD |
| 1272 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 202 | Negative | <LOD |
| 1273 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 202 | Negative | <LOD |
| 1274 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 202 | Negative | <LOD |
| 1275 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 202 | Negative | <LOD |
| 1276 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 202 | Negative | <LOD |
| 1277 | DOOR | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 202 | Negative | <LOD |
| 1278 | DOOR FRAME | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BATHROOM | UNIT 202 | Negative | <LOD |
| 1279 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 202 | Negative | <LOD |
| 1280 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 202 | Negative | <LOD |
| 1281 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 202 | Negative | <LOD |
| 1282 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 202 | Negative | <LOD |
| 1283 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 202 | Negative | <LOD |
| 1284 | WINDOW SILL | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 1 | UNIT 202 | Negative | <LOD |
| 1285 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1286 | WALL | DRYWALL | A | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1287 | WALL | DRYWALL | B | INTACT | YELLOW | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1288 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1289 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1290 | ROLL DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-------------|-----------|------|-----------|-------|--------------------|--------|-----------|----------|-----------------------|----------------|
| 1291 | DOOR | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1292 | DOOR FRAME | WOOD | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1293 | WINDOW SILL | WOOD | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 2 | UNIT 202 | Negative | <LOD |
| 1294 | CEILING | DRYWALL | | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1295 | WALL | DRYWALL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1296 | WALL | DRYWALL | B | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1297 | WALL | DRYWALL | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1298 | WALL | DRYWALL | D | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1299 | WINDOW SILL | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1300 | DOOR | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1301 | DOOR FRAME | WOOD | A | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1302 | ROLL DOOR | WOOD | C | INTACT | WHITE | BALLINGER HOMES | SECOND | BEDROOM 3 | UNIT 202 | Negative | <LOD |
| 1303 | DOOR | METAL | A | INTACT | GREEN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1304 | DOOR FRAME | METAL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1305 | DOOR | METAL | A | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1306 | DOOR | METAL | D | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1307 | SIDING | VINYL | B | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1308 | SIDING | VINYL | C | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1309 | SIDING | VINYL | D | INTACT | TAN | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1310 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------|-----------|------|-----------|-------|--------------------|--------|----------|----------|-----------------------|----------------|
| 1311 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | SECOND | EXTERIOR | UNIT 202 | Negative | <LOD |
| 1312 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1313 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 102 | Negative | <LOD |
| 1314 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 103 | Negative | <LOD |
| 1315 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 103 | Negative | <LOD |
| 1316 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 177 | Negative | <LOD |
| 1317 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 177 | Negative | <LOD |
| 1318 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 167 | Negative | <LOD |
| 1319 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 167 | Negative | <LOD |
| 1320 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 162 | Negative | <LOD |
| 1321 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 162 | Negative | <LOD |
| 1322 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 166 | Negative | <LOD |
| 1323 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 166 | Negative | <LOD |
| 1324 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 163 | Negative | <LOD |
| 1325 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 163 | Negative | <LOD |
| 1326 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 159 | Negative | <LOD |
| 1327 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 159 | Negative | <LOD |
| 1328 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 159 | Negative | <LOD |
| 1329 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 101 | Negative | <LOD |
| 1330 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 101 | Negative | <LOD |

| Reading | Component | Substrate | Side | Condition | Color | Site | Floor | Room | Location | Positive/ Negative | XRF Reading |
|---------|-----------|-----------|------|-----------|-------|--------------------|-------|----------|----------|-----------------------|----------------|
| 1331 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 104 | Negative | <LOD |
| 1332 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 112 | Negative | <LOD |
| 1333 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 112 | Negative | <LOD |
| 1334 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 118 | Negative | <LOD |
| 1335 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 118 | Negative | <LOD |
| 1336 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 113 | Negative | <LOD |
| 1337 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 113 | Negative | <LOD |
| 1338 | GUTTER | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 120 | Negative | <LOD |
| 1339 | SOFFIT | METAL | A | INTACT | WHITE | BALLINGER HOMES | FIRST | EXTERIOR | UNIT 120 | Negative | 0.6 |

TAB 2
Certification



STATE OF WASHINGTON

Department of Commerce
Lead-Based Paint Program

Janet J. Murphy

Has fulfilled the certification requirements of Washington Administrative code (WAC) 365-230 and has been certified to conduct lead-based paint activities pursuant to WAC 365-230-200 as a:

Risk Assessor

| <u>Certification #</u> | <u>Issuance Date</u> | <u>Expiration Date</u> |
|------------------------|----------------------|------------------------|
| 0258 | 3/23/2016 | 3/8/2019 |

STATE OF WASHINGTON

Department of Commerce

Lead-Based Paint Abatement Firm

PBS Engineering & Environmental Inc.

*Has fulfilled the certification requirements of
WAC 365-230
and has been certified to conduct lead-based
paint activities.*

Certification #

178

Issuance Date

05/24/2017

Expiration Date

09/03/2019