

Lead-Based Paint Inspection Report

Firwood Circle
314 37th Street SE
Auburn, Washington

Prepared for:
Deborah McCaslin
King County Housing
700 Andover Park West, Suite C
Seattle, Washington 98188

November 30, 2017
PBS Project No. 40573.141



2517 EASTLAKE AVENUE EAST
SUITE 100
SEATTLE, WA 98102
206.233.9639 MAIN
866.727.0140 FAX
PBSUSA.COM

LEAD-BASED PAINT INSPECTION REPORT

Firwood Circle
314 37th Street SE
Auburn, Washington

For

King County Housing Authority
700 Andover Park West, Suite C
Seattle, Washington 98188

This report is for the exclusive use of the client and is not to be photographed, photocopied, or similarly reproduced, in total or in part, without the express written consent of the client and/or PBS Engineering and Environmental Inc.

Prepared by:

PBS Engineering and Environmental Inc.
2517 Eastlake Avenue East Suite 100
Seattle, Washington 98102



TABLE OF CONTENTS

1 IDENTIFYING INFORMATION.....	1
2 LEAD-BASED PAINT INSPECTION.....	2
2.1 Site Information.....	2
2.2 Lead-Based Paint Inspection and Sampling.....	2
2.2.1 XRF Sampling.....	2
2.2.2 Bulk Paint-Chip Sampling.....	3
2.3 Components with Lead-Based Paint.....	3
2.4 Deteriorated Lead-Based Paint Surfaces.....	3

SUPPORTING DATA

TAB 1: XRF Data Sheets

TAB 2: Certifications

1 IDENTIFYING INFORMATION

BUILDING DATA

Firwood Circle
314 37th Street SE
Auburn, WA 98002

CLIENT DATA

King County Housing Authority
700 Andover Park West, Suite C
Seattle, WA 98188
Attn: Ms. Deborah McCaslin

SCOPE OF ASSESSMENT

PBS Engineering and Environmental, Inc. (PBS) conducted a lead-based paint inspection at Firwood Circle from November 13-14th and 20-21, 2017, in accordance with the U.S. Department Housing and Urban Development (HUD), Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing.

CERTIFICATIONS

Risk Assessor

Janet Murphy
State of Washington
Department of Community, Trade and Economic Development
Risk Assessor Certification No: 0258, Expiration Date: 3/8/2019



Signature

November 30, 2017

Date

Firm

PBS Engineering and Environmental
2517 Eastlake Avenue East
Seattle, Washington 98102
Telephone: 206.223.9639

Certification No: 129143
Expiration Date: 7/31/2018

2 LEAD-BASED PAINT INSPECTION

2.1 Site Information

Firwood Circle consists of 14 buildings with a total of 50 units. The buildings are of wood construction with gypsum interior walls and ceilings. The building exteriors consist of cement board siding with wood trim. Apartment units are one, two, three, four or five bedrooms with a bathroom and a kitchen/living room area. The buildings are in good condition. The exterior siding and trim were replaced 2017.

Architectural finishes are uniform throughout. The majority of the interior components are painted. Walls are painted gypsum wallboard. Ceilings are painted gypsum wallboard. Doors and doors frames are painted wood and metal. The window frames are vinyl.

2.2 Lead-Based Paint Inspection and Sampling

Based on discussions with KCHA staff and a review of King County Assessor records, Firwood Circle was constructed in 1971. All buildings and units were found to have a similar construction and painting history. Based on Table 7.3 in Chapter 7 of the HUD Guidelines, 22 of the 50 units at the site were included in PBS's inspection. PBS selected which of the units to be inspected by assigning each unit a number (1-50) and inputting the numbers into a random number generator until the 22 different units were selected. Additionally, PBS inspected the community center, restrooms, offices, classrooms and playground.

2.2.1 XRF Sampling

The presence of lead in paint was determined through x-ray fluorescence spectroscopy. A handheld INNOV-X Systems Inc. X-Ray Fluorescence Analyzer (XRF), Model α -4000 Serial # 6576 operating in lead paint mode was used to perform a surface by surface lead paint inspection of each painted surface in the selected units and other building areas. Calibration was checked based on the requirements of the Performance Characteristic Sheet for the XRF Analyzer. All calibration readings were within the tolerance for this instrument. No substrate correction is required with this instrument.

HUD and the Environmental Protection Agency (EPA) have set 1.0 milligrams per square centimeter (mg/cm^2) as the threshold limit for lead-based paint as determined through X-Ray Fluorescence (XRF) testing. HUD and EPA have set 5,000 parts per million (ppm) or 0.5 percent by atomic absorption spectroscopy (AAS) laboratory analysis as the threshold limit for lead-based paint. Paint that is known to contain lead levels less than those described above does not have to be evaluated, although all deteriorated paint (paint surfaces in poor condition) should be repaired because it may contain lower levels of lead that may contribute to lead dust or lead contaminated soil hazards.

The "Side" information presented on the XRF data sheets is in relation to the side of the rooms, or building exteriors where the street address is located. The inspector/risk assessor used the address side of each residence as the basis to establish side "A". Sides B, C, and D follow in clockwise rotation.

Please refer to the XRF Sample Data Table located in Tab 1 for a complete list of XRF samples.

2.2.2 Bulk Paint-Chip Sampling

Bulk paint chip verification samples were collected when there was an inconclusive result with the XRF. There were no inconclusive results with the XRF.

2.3 Components with Lead-Based Paint

None of the paint tested contained lead above the HUD standard of 1.0 mg/cm² lead by XRF.

2.4 Deteriorated Lead-Based Paint Surfaces

Lead-based paint was not identified at the subject property.

TAB 1

XRF Data Sheets

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
	Standardize				Negative	0.92	
	Calibrate				Positive	1.02	
	Calibrate				Negative	0.90	
	Calibrate				Positive	1.04	
	Calibrate				Negative	0.88	
	Calibrate				Positive	1.11	
Unit 219							
2	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
3	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
4	Living Room B	Gypsum Wallboard		White	Negative	0.00	Intact
5	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
6	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
7	Living Room B	Wood	Door Frame	White	Negative	0.00	Intact
8	Living Room B	Metal	Door	Gray	Negative	0.00	Intact
9	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
10	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
11	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
12	Kitchen/Dining Room C	Wood	Window Sill	White	Negative	0.00	Intact
13	Kitchen/Dining Room B	Wood	Cabinetry	Brown	Negative	0.00	Intact
14	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
15	1st Floor Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
16	1st Floor Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
17	1st Floor Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
18	1st Floor Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
19	1st Floor Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
20	1st Floor Bathroom B	Wood	Door	Brown	Negative	0.00	Intact
21	1st Floor Bathroom B	Wood	Door Frame	Brown	Negative	0.00	Intact
22	1st Floor Bedroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
23	1st Floor Bedroom A	Wood	Door	Brown	Negative	0.00	Intact
24	1st Floor Bedroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
25	1st Floor Bedroom A	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
26	1st Floor Bedroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
27	1st Floor Bedroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
28	1st Floor Bedroom C	Wood	Window Sill	White	Negative	0.00	Intact
29	1st Floor Bedroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
30	2nd Floor Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
31	2nd Floor Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
32	2nd Floor Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
33	2nd Floor Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
34	2nd Floor Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
35	2nd Floor Bathroom D	Wood	Cabinetry	Brown	Negative	0.00	Intact
36	2nd Floor Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
37	2nd Floor Bedroom 1 A	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
38	2nd Floor Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
39	2nd Floor Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
40	2nd Floor Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
41	2nd Floor Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
42	2nd Floor Bedroom 1 C	Gypsum Wallboard	Window Frame	White	Negative	0.00	Intact
43	2nd Floor Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
44	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
45	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
46	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
47	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
48	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
49	Bedroom 2 B	Wood	Window Sill	White	Negative	0.00	Intact
50	2nd floor Bedroom 3	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
51	2nd floor Bedroom 3 A	Gypsum Wallboard	Wall	Gray	Negative	0.00	Intact
52	2nd floor Bedroom 3 B	Gypsum Wallboard	Wall	Gray	Negative	0.00	Intact
53	2nd floor Bedroom 3 C	Gypsum Wallboard		Gray	Negative	0.00	Intact
54	2nd floor Bedroom 3 D	Gypsum Wallboard		Gray	Negative	0.00	Intact
55	2nd floor Bedroom 3 A	Wood	Window Sill	White	Negative	0.00	Intact
56	2nd floor Bedroom 3 C	Wood	Door	White	Negative	0.00	Intact
57	2nd floor Bedroom 3 C	Wood	Door Frame	White	Negative	0.00	Intact
58	2nd floor Bedroom 3 D	Wood	Closet Roll Door	White	Negative	0.00	Intact
59	Hall/Stair A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
60	Hall/Stair B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
61	Hall/Stair C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
62	Hall/Stair D	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
63	Hall/Stair D	Wood	Handrail	White	Negative	0.00	Intact
64	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
65	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
66	Exterior A	Cement Board	Trim	Gray	Negative	0.00	Intact
67	Exterior B	Wood	Trim at Roof	White	Negative	0.00	Intact
68	Exterior B	Cement Board	Siding	Tan	Negative	0.00	Intact
69	Exterior B	Metal	Downspout	White	Negative	0.00	Intact
70	Exterior B	Cement Board	Sliding Door Frame	Tan	Negative	0.00	Intact
71	Exterior B	Wood	Column	Gray	Negative	0.12	Intact

Unit 229

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
72	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
73	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
74	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
75	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
76	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
77	Kitchen/Dining Room B	Wood	Window Sill	White	Negative	0.00	Intact
78	Kitchen/Dining Room C	Wood	Cabinetry	Brown	Negative	0.00	Intact
79	Living/Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
80	Living/Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
81	Living/Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
82	Living/Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
83	Living/Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
84	Living/Room A	Metal	Door	Gray	Negative	0.00	Intact
85	Living/Room A	Wood	Door Frame	White	Negative	0.00	Intact
86	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
87	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
88	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
89	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
90	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
91	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
92	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
93	Bathroom D	Wood	Cabinetry	Brown	Negative	0.00	Intact
94	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
95	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
96	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
97	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
98	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
99	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
100	Bedroom 1 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
101	Bedroom 1 C	Wood	Door	Brown	Negative	0.00	Intact
102	Bedroom 1 C	Wood	Door Frame	Brown	Negative	0.00	Intact
103	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
104	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
105	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
106	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
107	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
108	Bedroom 2 B	Wood	Window Sill	Brown	Negative	0.00	Intact
109	Bedroom 2 A	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
110	Bedroom 3	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
111	Bedroom 3 A	Gypsum Wallboard	Wall		Negative	0.00	Intact
112	Bedroom 3 B	Gypsum Wallboard	Wall		Negative	0.00	Intact
113	Bedroom 3 C	Gypsum Wallboard	Wall		Negative	0.00	Intact
114	Bedroom 3 C	Gypsum Wallboard	Wall		Negative	0.00	Intact
115	Bedroom 3 A	Wood	Door	Brown	Negative	0.00	Intact
116	Bedroom 3 A	Wood	Door Frame	Brown	Negative	0.00	Intact
117	Bedroom 3 C	Wood	Window Sill	White	Negative	0.00	Intact
118	Bedroom 3 D	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
119	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
120	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
121	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
122	Stairwell A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
123	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
124	Stairwell B	Wood	Handrail	White	Negative	0.00	Intact
125	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
126	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
127	Exterior A	Cement Board	Trim	Gray	Negative	0.00	Intact
128	Exterior A	Cement Board	Siding	Gray	Negative	0.00	Intact
129	Exterior B	Cement Board	soffit	Tan	Negative	0.00	Intact
130	Exterior B	Cement Board	Siding	Tan	Negative	0.00	Intact
131	Exterior B	Wood	Column	Gray	Negative	0.00	Intact
132	Exterior B	Cement Board	Storage Siding	Tan	Negative	0.00	Intact
133	Exterior B	Metal	Door	Tan	Negative	0.00	Intact
134	Exterior B	Wood	Door Frame	Tan	Negative	0.00	Intact
Unit 239							
135	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
136	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
137	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
138	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
139	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
140	Kitchen/Dining Room B	Wood	Window Sill	White	Negative	0.00	Intact
141	Kitchen/Dining Room C	Wood	Cabinetry	Brown	Negative	0.00	Intact
142	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
143	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
144	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
145	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
146	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
147	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
148	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
149	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
150	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
151	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
152	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
153	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
154	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
155	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
156	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
157	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
158	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
159	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
160	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
161	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
162	Bedroom 1 D	Wood	Closet Roll Door	Brown	Negative	0.01	Intact
163	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
164	Wall A	Gypsum Wallboard	Wall A	White	Negative	0.00	Intact
165	Wall B	Gypsum Wallboard	Wall B	White	Negative	0.00	Intact
166	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
167	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
168	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
169	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
170	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
171	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
172	Bedroom 2 C	Wood	Door	Brown	Negative	0.00	Intact
173	Bedroom 2 C	Wood	Door Frame	Brown	Negative	0.00	Intact
174	Bedroom 2 D	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
175	Stairwell A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
176	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
177	Stairwell B	Wood	Hand Rail	White	Negative	0.00	Intact
178	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
179	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
180	Exterior A	Cement Board	Trim	Gray	Negative	0.00	Intact
181	Exterior D	Wood	Trim at Roof	White	Negative	0.00	Intact
182	Exterior D	Wood	Column	Gray	Negative	0.00	Intact
183	Exterior D	Cement Board	Soffit	Tan	Negative	0.00	Intact
184	Exterior D	Cement Board	Siding	Tan	Negative	0.00	Intact
Unit 243							
185	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
186	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
187	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
188	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
189	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
190	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
191	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
192	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
193	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
194	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
195	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
196	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
197	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
198	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
199	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
200	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
201	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
202	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
203	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
204	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
205	Bathroom B	Wood	Cabinetry	Brown	Negative	0.00	Intact
206	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
207	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
208	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
209	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
210	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
211	Bedroom 1 C	Wood	Window Sill	White	Negative	0.00	Intact
212	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
213	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
	Bedroom 2						
214	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
215	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
216	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
217	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
218	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
219	Bedroom 2 D	Wood	Door	Brown	Negative	0.00	Intact
220	Bedroom 2 D	Wood	Door Frame	Brown	Negative	0.00	Intact
221	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
222	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
223	Standardize						
224	Stairwell A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
225	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
226	Stairwell B	Wood	Handrail	White	Negative	0.00	Intact
227	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
228	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
229	Exterior C	Wood	Trim	White	Negative	0.00	Intact
230	Exterior C	Wood	Column	Gray	Negative	0.00	Intact
231	Exterior C	Cement Board	Siding	Tan	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
	Standardize						
	Calibrate				Negative	0.92	
	Calibrate				Negative	0.96	
	Calibrate				Negative	0.85	
	Calibrate				Positive	1.12	
	Calibrate				Positive	1.09	
	Calibrate				Positive	1.05	
Community Center Management Building							
4	Maintenance 117 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
5	Maintenance 117 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
6	Maintenance 117 C	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
7	Maintenance 117 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
8	Maintenance 117	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
9	Maintenance 117 D	Metal	Roll Door	White	Negative	0.00	Intact
10	Maintenance 117 D	Metal	Door	White	Negative	0.00	Intact
11	Maintenance 117 D	Wood	Door Frame	White	Negative	0.00	Intact
12	Office 113 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
13	Office 113 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
14	Office 113 C	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
15	Office 113 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
16	Office 113	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
17	Office 113 A	Wood	Window Sill	White	Negative	0.00	Intact
18	Office 113 D	Wood	Window Sill	White	Negative	0.00	Intact
19	Office 114 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
20	Office 114 A	Wood	Window Sill	White	Negative	0.00	Intact
21	Office 114 B	Gypsum Wallboard	Wall	Green	Negative	0.00	Intact
22	Office 114 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
23	Office 114 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
24	Office 114 D	Wood	Door	Brown	Negative	0.00	Intact
25	Office 114 D	Wood	Door Frame	Brown	Negative	0.00	Intact
26	Restroom 114	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
27	Restroom 114 A	Gypsum Wallboard	Wall	Orange	Negative	0.01	Intact
28	Restroom 114 B	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
29	Restroom 114 C	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
30	Restroom 114 D	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
31	Foyer	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
32	Office 102 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
33	Office 102 B	Gypsum Wallboard	Wall	Gray	Negative	0.00	Intact
34	Office 102 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
35	Office 102 D	Gypsum Wallboard	Wall	Gray	Negative	0.00	Intact
36	Office 103 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
37	Office 103 B	Gypsum Wallboard	Wall	Gray	Negative	0.00	Intact
38	Office 103 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
39	Office 103 D	Gypsum Wallboard	Wall	Gray	Negative	0.00	Intact
40	Kitchen A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
41	Kitchen B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
42	Kitchen C	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
43	Kitchen D	Gypsum Wallboard	Wall	Green	Negative	0.00	Intact
44	Janitor 110 A	Wood	Wall	Brown	Negative	0.00	Intact
45	Janitor 110 B	Metal	Door	Black	Negative	0.00	Intact
46	Janitor 110 B	Gypsum Wallboard	Door Frame	White	Negative	0.00	Intact
47	Janitor 110 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
48	Janitor 110 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
49	Storage 109	Wood	Door	Brown	Negative	0.00	Intact
50	Storage 109	Metal	Door Frame	Black	Negative	0.00	Intact
51	Teens 107 A	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
52	Teens 107 B	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
53	Teens 107 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
54	Teens 107 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
55	Teens 107 C	Wood	Window Sill	White	Negative	0.00	Intact
56	Teens 107 D	Wood	Window Sill	White	Negative	0.00	Intact
57	Classroom 104 A	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
58	Classroom 104 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
59	Classroom 104 B	Wood	Window Sill	White	Negative	0.00	Intact
60	Classroom 104 C	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
61	Classroom 104 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
62	Classroom 104 D	Wood	Door	Brown	Negative	0.00	Intact
63	Classroom 104 D	Metal	Door Frame	Black	Negative	0.00	Intact
64	Computer Lab 105 A	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
65	Computer Lab 105 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
66	Computer Lab 105 C	Gypsum Wallboard	Wall	Orange	Negative	0.00	Intact
67	Computer Lab 105 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
68	Computer Lab 105 D	Metal	Window Sill	Black	Negative	0.00	Intact
69	Computer Lab 105 D	Metal	Window Sill	Black	Negative	0.00	Intact
70	Girls Restroom 3	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
71	Girls Restroom 3 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
72	Girls Restroom 3 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
73	Girls Restroom 3 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
74	Girls Restroom 3 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
75	Boys Restroom 112	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
76	Boys Restroom 112 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
77	Boys Restroom 112 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
78	Boys Restroom 112 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
79	Boys Restroom 112 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
80	Exterior A	Cement Board	Siding	Yellow	Negative	0.00	Intact
81	Exterior A	Cement Board	Siding	Green	Negative	0.00	Intact
82	Exterior A	Cement Board	Siding	Gray	Negative	0.00	Intact
83	Exterior A	Wood	Door	White	Negative	0.00	Intact
84	Exterior A	Cement Board	Door Frame	Orange	Negative	0.00	Intact
85	Exterior B	Wood	Window Frame	White	Negative	0.00	Intact
86	Exterior B	Cement Board	Siding	Yellow	Negative	0.00	Intact
87	Exterior B	Cement Board	Siding	Gray	Negative	0.00	Intact
88	Exterior B	Wood	Door	White	Negative	0.00	Intact
89	Exterior B	Cement Board	Door Frame	White	Negative	0.00	Intact
90	Exterior B	Wood	Window Frame	White	Negative	0.00	Intact
91	Exterior B	Cement Board	Siding	Yellow	Negative	0.00	Intact
92	Exterior D	Cement Board	Siding	Green	Negative	0.00	Intact
93	Exterior D	Cement Board	Siding	Gray	Negative	0.00	Intact
94	Exterior D	Wood	Door	White	Negative	0.00	Intact
95	Exterior D	Wood	Door Frame	White	Negative	0.00	Intact
96	Exterior D	Wood	Window Frame	White	Negative	0.00	Intact
97	Exterior D	Wood	Trim at Roof	White	Negative	0.00	Intact
98	Exterior C	Cement Board	Siding	Gray	Negative	0.00	Intact
99	Exterior C	Cement Board	Siding	Yellow	Negative	0.00	Intact
100	Exterior C	Wood	Trim at Roof	White	Negative	0.00	Intact
101	Exterior C	Cement Board	Siding	Orange	Negative	0.00	Intact
102	Exterior C	Wood	Window Frame	White	Negative	0.00	Intact
103	Exterior C	Wood	Door Frame	White	Negative	0.00	Intact
104	Exterior C	Wood	Window Frame	White	Negative	0.00	Intact
105	Exterior C	Wood	Roll Door Frame	White	Negative	0.00	Intact
106	Exterior C	Cement Board	Siding	Yellow	Negative	0.00	Intact
Unit 355							
107	Living/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
108	Living/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.03	Intact
109	Living/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
110	Living/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
111	Living/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.02	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
112	Living/Dining Room C	Gypsum Wallboard	Window Sill	White	Negative	0.00	Intact
113	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
114	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
115	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
116	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
117	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
118	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
119	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
120	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
121	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
122	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
123	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
124	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
125	Bedroom 1 C	Wood	Window Sill	White	Negative	0.00	Intact
126	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
127	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
128	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
129	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
130	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
131	Bedroom 2 C	Wood	Window Sill	White	Negative	0.00	Intact
132	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
133	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
134	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
135	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
136	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
137	Bedroom 2 A	Wood	Door	Brown	Negative	0.00	Intact
138	Bedroom 2 A	Wood	Door Frame	Brown	Negative	0.00	Intact
139	Bedroom 2 B	Wood	Window Sill	White	Negative	0.00	Intact
140	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
141	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
142	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
143	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
144	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
145	Bathroom B	Wood	Cabinetry	Brown	Negative	0.00	Intact
146	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
147	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
148	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
149	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
150	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
151	Stairwell D	Wood	Handrail	White	Negative	0.00	Intact
152	Exterior A	Cement Board	Soffit	Tan	Negative	0.01	Intact
153	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
154	Exterior A	Cement Board	Trim at Roof	Gray	Negative	0.00	Intact
155	Exterior D	Wood	Column	Gray	Negative	0.00	Intact
156	Exterior D	Cement Board	Soffit	Tan	Negative	0.00	Intact
157	Exterior D	Wood	Sliding Door Frame	White	Negative	0.00	Intact
158	Exterior D	Wood	Beam	Tan	Negative	0.00	Intact
Unit 339							
159	Kitchen/Dining	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
160	Kitchen/Dining A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
161	Kitchen/Dining B	Gypsum Wallboard	Wall	White	Negative	0.03	Intact
162	Kitchen/Dining C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
163	Kitchen/Dining C	Wood	Window Sill	White	Negative	0.00	Intact
164	Kitchen/Dining D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
165	Kitchen/Dining B	Wood	Cabinetry	Brown	Negative	0.00	Intact
166	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
167	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
168	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
169	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
170	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
171	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
172	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
173	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
174	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
175	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
176	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
177	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
178	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
179	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
180	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
181	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
182	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
183	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
184	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
185	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
186	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
187	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
188	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
189	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
190	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
191	Bedroom 2 B	Wood	Window Sill	White	Negative	0.00	Intact
192	Bedroom 2 C	Wood	Window Sill	White	Negative	0.00	Intact
193	Bedroom 2 D	Wood	Door Frame	Brown	Negative	0.00	Intact
194	Bedroom 2 A	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
195	Bedroom 3	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
196	Bedroom 3 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
197	Bedroom 3 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
198	Bedroom 3 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
199	Bedroom 3 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
200	Bedroom 3 A	Wood	Window Sill	White	Negative	0.00	Intact
201	Bedroom 3 B	Wood	Roll Door	Brown	Negative	0.00	Intact
202	Bedroom 3 A	Wood	Door	Brown	Negative	0.00	Intact
203	Bedroom 3 A	Wood	Door Frame	Brown	Negative	0.00	Intact
204	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
205	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
206	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
207	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
208	Stairwell C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
209	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
210	Stairwell D	Wood	Handrail	White	Negative	0.00	Intact
211	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
212	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
213	Exterior A	Wood	Door Frame	White	Negative	0.00	Intact
214	Exterior B	Metal	Trim at Roof	White	Negative	0.00	Intact
215	Exterior B	Cement Board	Siding	Tan	Negative	0.00	Intact
216	Exterior B	Wood	Window Frame	White	Negative	0.00	Intact
217	Standardize						
218	Standardize						
219	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
220	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
221	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
222	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
223	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.03	Intact
224	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
225	Kitchen/Dining Room C	Wood	Cabinetry	Brown	Negative	0.00	Intact
226	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
227	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
228	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
229	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
230	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
231	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
232	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
233	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
234	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
235	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
Unit 349							
236	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
237	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
238	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
239	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
240	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
241	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
242	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
243	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
244	Bedroom 1 B	Wood	Roll Door	Brown	Negative	0.00	Intact
245	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
246	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
247	Bedroom 1 D	Wood	Window Sill	White	Negative	0.00	Intact
248	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
249	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
250	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
251	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
252	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
253	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
254	Bedroom 2 B	Wood	Roll Door	Brown	Negative	0.00	Intact
255	Bedroom 2 C	Wood	Door	Brown	Negative	0.00	Intact
256	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
257	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
258	Hall C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
259	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
260	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
261	Stairwell D	Wood	Handrail	White	Negative	0.00	Intact
262	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
263	Exterior A	Metal	Door Frame	Tan	Negative	0.00	Intact
264	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
265	Exterior A	Cement Board	Trim	Gray	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
266	Exterior D	Metal	Door	Tan	Negative	0.00	Intact
267	Exterior D	Metal	Door Frame	Tan	Negative	0.01	Intact
268	Exterior D	Wood	Trim at Roof	White	Negative	0.00	Intact
Unit 351							
269	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
270	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
271	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
272	Kitchen/Dining Room B	Wood	Window Sill	White	Negative	0.00	Intact
273	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
274	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
275	Kitchen/Dining Room A	Wood	Cabinetry	Brown	Negative	0.00	Intact
276	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
277	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
278	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
279	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
280	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
281	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
282	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
283	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
284	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
285	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
286	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
287	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
288	Bathroom D	Wood	Door	Brown	Negative	0.00	Intact
289	Bathroom D	Wood	Door Frame	Brown	Negative	0.00	Intact
290	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
291	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
292	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
293	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
294	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
295	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
296	Bedroom 1 B	Wood	Roll Door	Brown	Negative	0.00	Intact
297	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
298	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
299	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
300	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
301	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
302	Bedroom 2 A	Wood	Door	Brown	Negative	0.00	Intact
303	Bedroom 2 A	Wood	Door Frame	Brown	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
304	Bedroom 2 C	Wood	Window Sill	White	Negative	0.00	Intact
305	Bedroom 3	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
306	Bedroom 3 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
307	Bedroom 3 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
308	Bedroom 3 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
309	Bedroom 3 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
310	Bedroom 3 C	Wood	Window Sill	White	Negative	0.00	Intact
311	Bedroom 3 D	Wood	Roll Door	Brown	Negative	0.00	Intact
312	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
313	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
314	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
315	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
316	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
317	Stairwell D	Wood	Handrail	White	Negative	0.00	Intact
318	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
319	Exterior A	Metal	Door Frame	Tan	Negative	0.00	Intact
320	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
321	Exterior A	Cement Board	Trim	Gray	Negative	0.00	Intact
322	Exterior D	Metal	Door	Tan	Negative	0.00	Intact
323	Exterior D	Metal	Door Frame	Tan	Negative	0.00	Intact
324	Exterior D	Wood	Trim at Roof	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
		Test Paint		Red	Positive	1.79	
		Test Paint		Red	Positive	1.94	
		Test Paint		Red	Positive	1.44	
Unit 321							
2	Kitchen / Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
3	Kitchen / Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
4	Kitchen / Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
5	Kitchen / Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
6	Kitchen / Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
7	Kitchen / Dining Room B	Wood	Window Sill	White	Negative	0.00	Intact
7	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
8	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
9	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
10	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
11	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
12	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
13	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
14	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
15	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
16	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
17	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
18	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
19	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
20	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
21	Bedroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
22	Bedroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
23	Bedroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
24	Bedroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
25	Bedroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
26	Bedroom A	Wood	Closet Roll door	Brown	Negative	0.00	Intact
27	Bedroom B	Wood	Door	Brown	Negative	0.00	Intact
28	Bedroom B	Wood	Door Frame	Brown	Negative	0.00	Intact
29	Bedroom D	Wood	Window Sill	White	Negative	0.00	Intact
30	Exterior A	Cement Board	Soffit	Brown	Negative	0.00	Intact
31	Exterior A	Cement Board	Door Frame	Brown	Negative	0.00	Intact
32	Exterior A	Cement Board	Siding	Brown	Negative	0.00	Intact
33	Exterior D	Cement Board	Sliding door Frame	Brown	Negative	0.00	Intact
34	Exterior D	Metal	Downspout	White	Negative	0.00	Intact
35	Exterior A	Cement Board	Storage Unit Siding	Brown	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
Unit 323							
36	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
37	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
38	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
39	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
40	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
41	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
42	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
43	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
44	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
45	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
46	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
47	Living Room C	Wood	Window Sill	White	Negative	0.00	Intact
48	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
49	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
50	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
51	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
52	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
53	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
54	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
55	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
56	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
57	Bedroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
58	Bedroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
59	Bedroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
60	Bedroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
61	Bedroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
62	Bedroom A	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
63	Bedroom B	Wood	Window Sill	White	Negative	0.00	Intact
64	Bedroom D	Wood	Door	Brown	Negative	0.01	Intact
65	Bedroom D	Wood	Door Frame	Brown	Negative	0.00	Intact
66	Exterior A	Cement Board	Soffit	Brown	Negative	0.00	Intact
67	Exterior A	Cement Board	Siding	Brown	Negative	0.00	Intact
68	Exterior A	Cement Board	Door Frame	Brown	Negative	0.00	Intact
69	Exterior B	Cement Board	Window Frame	White	Negative	0.00	Intact
70	Exterior B	Cement Board	Trim at Roof	White	Negative	0.00	Intact
Unit 325							
71	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
72	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.03	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
73	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
74	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
75	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
76	Living Room	Gypsum Wallboard	Ceiling	White	Negative	Test Aborted	Intact
76	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
77	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
78	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
79	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
80	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
81	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
82	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
83	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
84	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
85	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
86	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
87	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
88	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
89	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
90	Bedroom	Gypsum Wallboard	ceiling	White	Negative	0.00	Intact
91	Bedroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
92	Bedroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
93	Bedroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
94	Bedroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
95	Bedroom A	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
96	Bedroom B	Wood	Door	Brown	Negative	0.00	Intact
97	Bedroom B	Wood	Door Frame	Brown	Negative	0.00	Intact
98	Bedroom D	Wood	Window Sill	White	Negative	0.00	Intact
99	Exterior A	Cement Board	Soffit	Brown	Negative	0.00	Intact
100	Exterior B	Cement Board	Siding	Brown	Negative	0.00	Intact
101	Exterior B	Cement Board	Panel	Yellow	Negative	0.00	Intact
102	Exterior D	Cement Board	Window Frame	Brown	Negative	0.00	Intact
103	Exterior D	Cement Board	Trim at Roof	White	Negative	0.00	Intact
104	Exterior D	Cement Board	Siding	Brown	Negative	0.00	Intact
105	Exterior D	Metal	Gutter	White	Negative	0.00	Intact
Unit 327							
106	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
107	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
108	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
109	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.05	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
110	Kitchen/Dining Room C	Wood	Wall	White	Negative	0.00	Intact
111	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
112	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
113	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
114	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
115	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
116	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
117	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
118	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
119	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
120	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
121	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
122	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
123	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
124	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
125	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
126	Bedroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
127	Bedroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
128	Bedroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
129	Bedroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
130	Bedroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
131	Bedroom A	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
132	Bedroom B	Wood	Window Sill	White	Negative	0.00	Intact
133	Bedroom D	Wood	Door	Brown	Negative	0.00	Intact
134	Bedroom D	Wood	Door Frame	Brown	Negative	0.00	Intact
135	Exterior A	Cement Board	Soffit	Brown	Negative	0.00	Intact
136	Exterior A	Cement Board	Siding	Brown	Negative	0.00	Intact
137	Exterior A	Cement Board	Door Frame	Brown	Negative	0.00	Intact
138	Exterior C	Metal	Gutter	White	Negative	0.00	Intact
139	Exterior C	Metal	Downspout	White	Negative	0.00	Intact
140	Exterior C	Cement Board	Trim at Roof	White	Negative	0.00	Intact
141	Exterior C	Cement Board	Window Frame	Brown	Negative	0.00	Intact
142	Standardize	---	---	---	---	---	---
Unit 237							
143	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
144	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
145	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
146	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
147	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
148	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
149	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
150	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
151	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
152	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
153	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
154	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
155	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
156	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
157	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
158	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
159	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
160	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
161	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
162	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
163	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
164	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
165	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
166	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
167	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
168	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
169	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
170	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
171	Bedroom 1 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
172	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
173	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
174	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
175	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
176	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
177	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
178	Bedroom 2 B	Wood	Closet Roll Door	White	Negative	0.00	Intact
179	Bedroom 2 C	Wood	Door	Brown	Negative	0.00	Intact
180	Bedroom 2 C	Wood	Door Frame	Brown	Negative	0.00	Intact
181	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
182	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
183	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
184	Stairwell A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
185	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
186	Stairwell A	Wood	Handrail Round	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
187	Stairwell A	Wood	Handrail Flat	White	Negative	0.00	Intact
188	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
189	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
190	Exterior A	Cement Board	Door Frame	Tan	Negative	0.00	Intact
191	Exterior B	Wood	Column	Gray	Negative	0.00	Intact
192	Exterior B	Cement Board	Soffit	Tan	Negative	0.00	Intact
193	Exterior B	Wood	Trim at Roof	Gray	Negative	0.00	Intact
Unit 241							
194	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
195	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.04	Intact
196	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
197	Kitchen/Dining Room B	Wood	Window Sill	White	Negative	0.00	Intact
198	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
199	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
200	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
201	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
202	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
203	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
204	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.06	Intact
205	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
206	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
207	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
208	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
209	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
210	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
211	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
212	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
213	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
214	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
215	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
216	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
217	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
218	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
219	Bedroom 1 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
220	Bedroom 1 C	Wood	Window Sill	White	Negative	0.00	Intact
221	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
222	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
223	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
224	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
225	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
226	Bedroom 2 A	Wood	Door	Brown	Negative	0.00	Intact
227	Bedroom 2 A	Wood	Door Frame	Brown	Negative	0.00	Intact
228	Bedroom 2 C	Wood	Window Sill	White	Negative	0.00	Intact
229	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
230	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
231	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
232	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
233	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
234	Stairwell B	Wood	Hand Rail (round)	White	Negative	0.00	Intact
235	Stairwell B	Wood	Hand Rail (flat)	White	Negative	0.00	Intact
236	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
237	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
238	Exterior A	Cement Board	Door Frame	Tan	Negative	0.00	Intact
239	Exterior B	Wood	Beam	Gray	Negative	0.00	Intact
240	Exterior B	Wood	Column	Gray	Negative	0.00	Intact
Unit 265							
241	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
242	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
243	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
244	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
245	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
246	Kitchen/Dining Room C	Wood	Window Sill	White	Negative	0.00	Intact
247	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
248	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
249	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
250	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
251	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
252	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
253	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
254	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
255	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
256	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
257	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
258	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
259	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
260	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
261	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
262	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
263	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
264	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
265	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
266	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
267	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
268	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
269	Bedroom 1 B	Wood	Window Sill	White	Negative	0.00	Intact
	Bedroom 2						
270	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
271	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
272	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
273	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
274	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
275	Bedroom 2 A	Wood	Window Sill	Brown	Negative	0.00	Intact
276	Bedroom 2 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
277	Bedroom 2 A	Wood	Door	Brown	Negative	0.00	Intact
278	Bedroom 2 A	Wood	Door Frame	Brown	Negative	0.00	Intact
279	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
280	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
281	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
282	Stairwell C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
283	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
284	Stairwell C	Wood	Handrail (round)	White	Negative	0.00	Intact
285	Stairwell C	Wood	Handrail (flat)	White	Negative	0.00	Intact
286	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
287	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
288	Exterior A	Cement Board	Door Frame	Tan	Negative	0.00	Intact
289	Exterior D	Wood	Column	Gray	Negative	0.00	Intact
290	Exterior D	Wood	Beam	Gray	Negative	0.00	Intact
291	Exterior D	Wood	Trim at Roof	White	Negative	0.00	Intact
292	Exterior D	Metal	Gutter	White	Negative	0.00	Intact
293	Exterior D	Metal	Downspout	White	Negative	0.00	Intact
	Unit 263						
294	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
295	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
296	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
297	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
298	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
299	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
300	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
301	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
302	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
303	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
304	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
305	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
306	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
307	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
308	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
309	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
310	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
311	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
312	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
313	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
314	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.01	Intact
315	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
316	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
317	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
318	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
319	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
320	Bedroom 1 D	Wood	Window Sill	White	Negative	0.00	Intact
321	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
322	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
323	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
324	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
325	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
326	Bedroom 2 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
327	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
328	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
329	Bedroom 2 C	Wood	Window Sill	White	Negative	0.00	Intact
330	Bedroom 2 D	Wood	Window Sill	White	Negative	0.00	Intact
331	Bedroom 2 C	Wood	Door	Brown	Negative	0.00	Intact
332	Bedroom 2 C	Wood	Door Frame	Brown	Negative	0.00	Intact
333	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.01	Intact
334	Hall	Wood	Attic Frame	White	Negative	0.51	Intact
335	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
336	Hall D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
337	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
338	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
339	Stairwell B	Wood	Handrail (round)	White	Negative	0.00	Intact
340	Stairwell B	Wood	Handrail (flat)	White	Negative	0.00	Intact
341	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
342	Exterior A	Cement Board	Corner Trim	Gray	Negative	0.00	Intact
343	Exterior D	Wood	Column	Gray	Negative	0.00	Intact
344	Exterior D	Wood	Beam	Gray	Negative	0.01	Intact
345	Exterior D	Cement Board	Soffit	Tan	Negative	0.00	Intact
346	Exterior D	Wood	Trim at Roof	White	Wood	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
	Standardize						
	Calibrate	Test Paint		Red	Positive	1.64	
	Calibrate	Test Paint		Red	Negative	0.89	
	Calibrate	Test Paint		Red	Positive	1.75	
	Calibrate	Test Paint		Red	Positive	1.84	
Unit 335							
2	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
3	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
4	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
5	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
6	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
7	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
8	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
9	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
10	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
11	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
12	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
13	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
14	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
15	Stairwell C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
16	Stairwell B	Wood	Handrail (round)	White	Negative	0.00	Intact
17	Stairwell B	Wood	Handrail (flat)	White	Negative	0.00	Intact
18	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
19	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
20	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
21	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
22	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
23	Hall C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
24	Hall D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
25	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
26	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
27	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
28	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
29	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
30	Bedroom 1 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
31	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
32	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
33	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
34	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
35	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
36	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
37	Bedroom 2 B	Wood	Window Sill	White	Negative	0.00	Intact
38	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
39	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
40	Bedroom 2 D	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
41	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
42	Exterior A	Cement Board	Door Frame	Tan	Negative	0.00	Intact
43	Exterior A	Cement Board	Soffit	Tan	Negative	0.00	Intact
44	Exterior C	Wood	Column	Gray	Negative	0.00	Intact
45	Exterior C	Wood	Beam	Gray	Negative	0.00	Intact
46	Exterior C	Wood	Trim at Roof	White	Negative	0.01	Intact
Unit 329							
47	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
48	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
49	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
50	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
51	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
52	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
52	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
53	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
54	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
55	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
56	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
57	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
58	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
59	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
60	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
61	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
62	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
63	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
64	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
65	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
66	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
67	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
68	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
69	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
70	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
71	Bedroom 1 C	Wood	Window Sill	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
72	Bedroom 1 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
73	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
74	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
75	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
76	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
77	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
78	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
79	Bedroom 2 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
80	Bedroom 2 D	Wood	Door	Brown	Negative	0.00	Intact
81	Bedroom 2 D	Wood	Door Frame	Brown	Negative	0.00	Intact
82	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
83	Hall C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
84	Hall D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
85	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
86	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
87	Stairwell D	Wood	Hand Rail (round)	White	Negative	0.00	Intact
88	Stairwell D	Wood	Hand Rail (flat)	White	Negative	0.00	Intact
89	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
90	Exterior A	Cement Board	Door Frame	Tan	Negative	0.00	Intact
91	Exterior D	Cement Board	Soffit	Tan	Negative	0.00	Intact
92	Exterior D	Wood	Beam	Gray	Negative	0.00	Intact
93	Exterior D	Wood	Column	Gray	Negative	0.00	Intact
94	Exterior D	Metal	Storage Door	Tan	Negative	0.00	Intact
95	Exterior D	Cement Board	Storage Door Frame	Tan	Negative	0.00	Intact
Unit 221							
96	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
97	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
98	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
99	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
100	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
101	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
102	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
103	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
104	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
105	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
106	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
107	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
108	Living Room B	Wood	Door Frame	White	Negative	0.00	Intact
109	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
110	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
111	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
112	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
113	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
114	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
115	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
116	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
117	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
118	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
119	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
120	Bedroom 1 D	Wood	Window Sill	White	Negative	0.00	Intact
121	Bedroom 1 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
122	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
123	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
124	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
125	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
126	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
127	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
128	Bedroom 2 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
129	Bedroom 2 C	Wood	Door	Brown	Negative	0.00	Intact
130	Bedroom 2 C	Wood	Door Frame	Brown	Negative	0.00	Intact
131	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
132	Hall B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
133	Hall C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
134	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
135	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
136	Stairwell D	Wood	Handrail (round)	White	Negative	0.00	Intact
137	Stairwell D	Wood	Handrail (flat)	White	Negative	0.00	Intact
138	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
139	Exterior C	Cement Board	Window Frame	Tan	Negative	0.00	Intact
140	Exterior C	Cement Board	Siding	Green	Negative	0.00	Intact
141	Exterior D	Wood	Column	Gray	Negative	0.00	---
142	Exterior D	Cement Board	Soffit	Gray	Negative	0.00	Intact
143	Exterior D	Wood	Trim at Roof	White	Negative	0.00	Intact
144	Exterior D	Metal	Storage Door	Tan	Negative	0.00	Intact
145	Exterior D	Metal	Storage Door Frame	Tan	Negative	0.00	Intact
Unit 227							
146	---	---	---	---	---	---	---
147	Kitchen/Dining	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
148	Kitchen/Dining A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
149	Kitchen/Dining B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
150	Kitchen/Dining C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
151	Kitchen/Dining D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
152	Kitchen/Dining D	Wood	Window Sill	White	Negative	0.00	Intact
153	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
154	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
155	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
156	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
157	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
158	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
159	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
160	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
161	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
162	Stairwell B	Wood	Hand Rail (round)	White	Negative	0.00	Intact
163	Stairwell B	Wood	Hand Rail (flat)	White	Negative	0.00	Intact
164	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
165	Hall	Wood	Attic Hatch Frame	White	Negative	0.27	Intact
166	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
167	Hall C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
168	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
169	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
170	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
171	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
172	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
173	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
174	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
175	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
176	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
177	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
178	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
179	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
180	Bedroom 1 D	Wood	Window Sill	White	Negative	0.00	Intact
181	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
182	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
183	Bedroom 1 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
184	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
185	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
186	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
187	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
188	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
189	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
190	Bedroom 2 B	Wood	Closet Roll Door	Brown	Negative	0.00	Intact
191	Bedroom 2 D	Wood	Door	Brown	Negative	0.00	Intact
192	Bedroom 2 D	Wood	Door Frame	Brown	Negative	0.00	Intact
193	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
194	Exterior A	Cement Board	Door Frame	Tan	Negative	0.00	Intact
195	Exterior D	Cement Board	Window Frame	Tan	Negative	0.00	Intact
196	Exterior D	Cement Board	Sliding Door Frame	Tan	Negative	0.00	Intact
197	Exterior D	Wood	Column	Gray	Negative	0.34	Intact
198	Exterior A	Metal	Downspout	White	Negative	0.00	Intact
199	Exterior A	Metal	Gutter	White	Negative	0.00	Intact
Unit 231							
200	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
201	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
202	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
203	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
204	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
205	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
206	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
207	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
208	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
209	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
210	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
211	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
212	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
213	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
214	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
215	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
216	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
217	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
218	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
219	Bathroom B	Wood	Door Frame	Brown	Negative	0.00	Intact
220	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
221	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
222	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
223	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
224	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
225	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
226	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
227	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
228	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
229	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
230	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
231	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
232	Bedroom 2 C	Wood	Door	Brown	Negative	0.00	Intact
233	Bedroom 2 C	Wood	Door Frame	Brown	Negative	0.00	Intact
234	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
235	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
236	Hall C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
237	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
238	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
239	Stairwell D	Wood	Hand Rail (round)	White	Negative	0.00	Intact
240	Stairwell D	Wood	Hand Rail (flat)	White	Negative	0.00	Intact
241	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
242	Exterior A	Cement Board	Corner Trim	Gray	Negative	0.00	Intact
243	Exterior A	Cement Board	Siding	Green	Negative	0.00	Intact
244	Exterior D	Wood	Column	Gray	Negative	0.17	Intact
245	Exterior D	Cement Board	Sliding Door Frame	Tan	Negative	0.00	Intact
246	Exterior D	Cement Board	Window Frame	Tan	Negative	0.00	Intact
Unit 233							
247	Kitchen/Dining Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
248	Kitchen/Dining Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
249	Kitchen/Dining Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
250	Kitchen/Dining Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
251	Kitchen/Dining Room D	Gypsum Wallboard	Wall	White	Negative	0.02	Intact
252	Kitchen/Dining Room D	Wood	Window Sill	White	Negative	0.00	Intact
253	Living Room	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
254	Living Room A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
255	Living Room B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
256	Living Room C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
257	Living Room D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
258	Living Room A	Metal	Door	Gray	Negative	0.00	Intact
259	Living Room A	Wood	Door Frame	White	Negative	0.00	Intact
260	Stairwell B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
261	Stairwell D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
262	Stairwell B	Wood	Hand Rail (round)	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
263	Stairwell B	Wood	Hand Rail (flat)	White	Negative	0.00	Intact
264	Hall	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
265	Hall A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
266	Hall C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
267	Bathroom	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
268	Bathroom A	Gypsum Wallboard	Wall	White	Negative	0.00	---
269	Bathroom B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
270	Bathroom C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
271	Bathroom D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
272	Bathroom A	Wood	Door	Brown	Negative	0.00	Intact
273	Bathroom A	Wood	Door Frame	Brown	Negative	0.00	Intact
274	Bedroom 1	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
275	Bedroom 1 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
276	Bedroom 1 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
277	Bedroom 1 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
278	Bedroom 1 D	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
279	Bedroom 1 A	Wood	Window Sill	White	Negative	0.00	Intact
280	Bedroom 1 A	Wood	Door	Brown	Negative	0.00	Intact
281	Bedroom 1 A	Wood	Door Frame	Brown	Negative	0.00	Intact
282	Bedroom 1 B	Wood	Roll Closet Door	Brown	Negative	0.00	Intact
283	Bedroom 2	Gypsum Wallboard	Ceiling	White	Negative	0.00	Intact
284	Bedroom 2 A	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
285	Bedroom 2 B	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
286	Bedroom 2 C	Gypsum Wallboard	Wall	White	Negative	0.00	Intact
287	Bedroom 2 D	Gypsum Wallboard	Wall	White	Negative	0.01	Intact
288	Bedroom 2 A	Wood	Window Sill	White	Negative	0.00	Intact
289	Bedroom 2 C	Wood	Door	Brown	Negative	0.00	Intact
290	Bedroom 2 C	Wood	Door Frame	Brown	Negative	0.00	Intact
291	Exterior A	Cement Board	Siding	Tan	Negative	0.00	Intact
292	Exterior A	Cement Board	Corner Trim	Gray	Negative	0.00	Intact
293	Exterior A	Cement Board	Siding	Green	Negative	0.00	Intact
294	Exterior D	Wood	Beam	Gray	Negative	0.00	Intact
295	Exterior D	Wood	Column	Gray	Negative	0.15	Intact
296	Exterior D	Cement Board	sliding Door Trim	Tan	Negative	0.00	Intact
297	Exterior D	Cement Board	Window Frame	Tan	Negative	0.00	Intact
298	Exterior B	Metal	Storage Room Door	Tan	Negative	0.00	Intact
299	Exterior B	Metal	Storage Door Frame	Tan	Negative	0.00	Intact
300	Exterior B	Wood	Trim at Roof	White	Negative	0.00	Intact

Reading	Test Location	Substrate	Component	Color	Positive/Negative	XRF Reading	Condition
Playground Equipment/Climber							
301	Playground Equipment/Climber	Metal	Bench	Green	Negative	0.00	Intact
302	Playground Equipment/Climber	Metal	Pole	Red	Negative	0.00	Intact
303	Playground Equipment/Climber	Metal	Steps	Green	Negative	0.00	Intact
304	Playground Equipment/Climber	Metal	Pole	Yellow	Negative	0.02	Intact
305	Playground Equipment/Climber	Metal	Step (looks like a leaf)	Red	Negative	0.00	Intact

TAB 2
Certifications

STATE OF WASHINGTON

Department of Commerce

Lead-Based Paint Abatement Firm

PBS Engineering & Environmental Inc.

*Has fulfilled the certification requirements of
WAC 365-230
and has been certified to conduct lead-based
paint activities.*

Certification #

178

Issuance Date

05/24/2017

Expiration Date

09/03/2019



STATE OF WASHINGTON

Department of Commerce Lead-Based Paint Program

Janet J. Murphy

Has fulfilled the certification requirements of Washington Administrative code (WAC) 365-230 and has been certified to conduct lead-based paint activities pursuant to WAC 365-230-200 as a:

Risk Assessor

Certification #

0258

Issuance Date

3/23/2016

Expiration Date

3/8/2019